## LICENSEE EVENT REPORT

i ki	CONTROL BLOCK: [ ] [ ] [ ] [PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION]
0 1	P A T M I 2 2 0 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 15 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 67 CAT 58
CON'T	REPORT L 6 0 5 0 0 0 3 2 0 0 5 2 0 7 8 8 0 6 5 7 8 9
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [During performance of Surveillance Procedure 2303-M16 "Emergency Diesel Generator and
0 3	Cooling Water Valve Operability Test", the "B" diesel generator failed to start. Since
0 4	the redundant emergency diesel generator was operable, therefore this did not have an
0 5	adverse effect on the health and safety of the public.
0 6	
3 7	
0 8	
0 9	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
	TO REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER  A 18 Z 19 Z 20 Z 21 Q 0 0 0 0 N 23 N 24 A 25 F D 1 0
1101	Investigation revealed that the vertical shaft between the upper and lower grank shaft
11	had failed, due to improper material. Upon failure of DF-X-1B, Action a., of Tech.
1 2	Spec. 3.8.1.1 was entered. A complete coupling of the proper material was installed
1 3	and DF-X-1B was returned to operable status within the required time. DF-X-1A was als
1 4	inspected and it was confirmed that the proper material was used in the vertical (cont
1 5	B 28 0 0 0 29 11A Discovered during testing
A	CTIVITY CONTENT 12 13 44 45 46 LOCATION OF RELEASE 36 NA NA LOCATION OF RELEASE 36
17	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA NA
	9 PERSONNEL INJURIES 13 80 NUMBER DESCRIPTION 41 NA
1 9	LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION NA  NA
2 0	PUBLICITY OF SUED DESCRIPTION 45 NRC USE ONLY  Wee'clv News pelease 7904200 40/ NRC USE ONLY
3	9 10 68 69 80 NAME OF RESPONDED J. R. Stair 215-929-3601, Ext. 118

TER 78-39/3L

Cause Description and Corrective Actions drive coupling.