

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 P A B V S 1 2 0 0 - 7 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE J0 57 CAT 58

CON'T
01 R L 6 0 5 0 0 0 3 3 4 7 0 8 1 9 7 9 8 0 8 3 1 7 9 9
7 8 9 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 1446 hours, the reactor was manually tripped following the trip of the 1B Steam
03 Generator Feed Pump due to low NPSH. The operators performed the immediate manual
04 actions following a reactor trip and loss of normal feedwater. An operator, thinking
05 that the generator output breakers were taking too long to trip, manually tripped them
06 prior to the automatic trip which normally occurs 30 seconds after the trip. Frequency
07 dropped on the 1A and 1B 4KV Buses and all three RCPs tripped on underfrequency.

09 SYSTEM CODE: HA (11) CAUSE CODE: A (12) CAUSE SUBCODE: A (13) COMPONENT CODE: CKTBRK (14) COMP. SUBCODE: A (15) VALVE SUBCODE: Z (16)
7 8 9 10 11 12 13 14 15 16 17 18 19 20

(17) LER/RO REPORT NUMBER: 79 (21) EVENT YEAR: 79 (22) SEQUENTIAL REPORT NO.: 028 (24) OCCURRENCE CODE: 01 (28) REPORT TYPE: T (30) REVISION NO.: 0 (32)
ACTION TAKEN: H (18) FUTURE ACTION: Z (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS: 0000 (22) ATTACHMENT SUBMITTED: Y (23) NPRD 4 FORM SUB.: N (24) PRIME COMP. SUPPLIER: Z (25) COMPONENT MANUFACTURER: Z999 (26)
33 34 35 36 37 38 39 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The incident resulted from operator error in tripping the main generator output breaker
11 prior to the automatic trip. The 1C RCP was started four minutes after the trip and
12 forced flow was returned to the RCS. The involved operator was reprimanded for his
13 action and all Operations personnel will review the incident circumstances.

15 FACILITY STATUS: E (28) % POWER: 050 (29) OTHER STATUS: N/A (30) METHOD OF DISCOVERY: A (31) DISCOVERY DESCRIPTION: Operator observation (32)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 ACTIVITY CONTENT: Z (33) Z (34) AMOUNT OF ACTIVITY: N/A (35) LOCATION OF RELEASE: N/A (36)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 PERSONNEL EXPOSURES NUMBER: 000 (37) TYPE: Z (38) DESCRIPTION: N/A (39)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 PERSONNEL INJURIES NUMBER: 000 (40) DESCRIPTION: N/A (41)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

19 LOSS OF OR DAMAGE TO FACILITY TYPE: Z (42) DESCRIPTION: N/A (43)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 PUBLICITY ISSUED: N (44) DESCRIPTION: N/A (45) NRC USE ONLY
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER: J. A. Werling PHONE: 412-643-1258

7909060277 916183

Attachment To LER 79-28/01T
Beaver Valley Power Station
Duquesne Light Company
Docket No. 50-334

At 1446 hours on August 19, 1979, the reactor was manually tripped from approximately 50% rated power following the trip of the 1B Main Feed Pump due to low net positive suction head. The 1A Condensate Pump was shutdown for cleaning of its strainer. The 1B Main Feed Pump had just been started and the 1A Pump secured to investigate a high bearing temperature on the 1A Pump.

Upon initiation of the reactor trip, the operators performed the immediate manual actions following a reactor trip and loss of normal feedwater. An operator, thinking that the generator output breakers were taking too long to trip, manually tripped them prior to the automatic trip which normally occurs 30 seconds after the reactor/turbine trip. Since the main generator was no longer tied to the system, frequency dropped on the 1A and 1B 4KV Buses and all three reactor coolant pumps tripped on underfrequency (2 of 3 buses). The 1C and 1D 4KV Buses were tied into the system and did not experience the underfrequency condition. Thirty seconds after the turbine trip, the 1A and 1B Buses transferred to system power and the underfrequency condition cleared. Four minutes after the reactor trip, the 1C Reactor Coolant Pump was started and forced flow returned to the reactor coolant system. All systems operated as designed and at no time was the health and safety of the public jeopardized. The involved operator was reprimanded for his action. All Operations personnel will review the incident.

316184