## POOR ORIGINAL

NRC FOI	4 366 U. S. NUCLEAR REGULATORY COMMISSION
	LICENSEE EVENT REPORT EXHIBIT A
	CONTROL BLOCK:
0 1	A   R   A   N   O   2   O   O   O   O   O   O   O   O
OII	SOURCE SO 61 DOCKET NUMBER 68 60 EVENT DATE 74 75 HEPORT DATE 80
0 2	As a result of the analysis of Seismic Category I pipe supports for base-
0 3	plate flexibility as requested in NRC IE Bulletin 79-02, nine restraints
0 4	have been identified as having a safety factor of <2. Refer to response
0 5	of IE Bulletin 79-02 for identification. It was required to declare the
0 6	R.B. sump drain, outside containment isolation valve, 2CV-2061, inoperable
0 7	due to the inadequate pipe restraints. There have been no similar
08	occurrences. Reportable per T.S.6.9.1.9b.
0 9	XIX 11 B 12 C 13 SUBCODE SUBCO
	TO REPORT TO SEQUENTIAL APPORTING CODE TYPE TYPE TYPE TYPE TYPE TYPE TYPE TYP
	COMPONENT HOURS (22) SUBMITTED FORM SUPPLIER MANUFACTURER
	F 18 F 19 Z 10 1 0 10 10 10 1 N 20 A 30 B 1 1 3 10 6
1101	LAll pipe supports with a safety factor of less than two have been modified.
	Refer to the response to the IE Bulletin 79-02 for details.
1 2	
1 3	
1 5	TATUS TATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DISCOVERY DESCRIPTION 32 DISCOVERY DISCOVERY DESCRIPTION 32 DISCOVERY DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIPTION 32 DISCOVERY DISCOVERY DESCRIPTION 32 DISCOVERY DISCOVERY DISCOVERY D
	LEASED OF RELEASE  Z 33 Z NA  NA  LOCATION OF HELEASE 36
17	PERSONNEL EXPOSURES  JUMBER TYPE DESCRIPTION 39  O O O O O O O O O O O O O O O O O O O
1 8	PEHSONNEL INJURIES 13 SO SUMBER DESCRIPTION (41)
, I	OS OF OR DAMAGE TO FACILITY (2)
10	OSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION  Z 42 NA  7 9 0 9 2 8 0 4 4 4 4.
20	PUBLICITY SUED DESCRIPTION 45  NAC USE ONLY  N 44 NA
7 8	Chris N Shively 501/069 2510
	NAME OF PREPAREH CHITS N. SHIVETY