

# POOR ORIGINAL

NRC FORM 366  
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 

0	1	A	R	A	N	O	2	0	0	-	0	0	0	0	1	1	1	1	4	5	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	A	R	A	N	O	2	0	0	-	0	0	0	0	1	1	1	1	4	5	
7	8	9	LICENSEE CODE	14	15	LICENSE NUMBER	25	26	27	28	29	30	31	32	33	34	35	36	37	CAT 58

CONT'D

0 1	REPORT SOURCE	L	6	0	5	0	0	0	3	6	18	7	0	18	21	1	7	9	8	0	19	21	0	7	9	9	
7	8	9	60	61	DOCKET NUMBER	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

- 0 2 During Mode 1 operation, the Control Room Emergency Air Conditioning
- 0 3 Unit 2VE1B, failed to start on demand from the Control Room. The re-
- 0 4 undant Emergency Air Conditioning system was verified operable. Other
- 0 5 occurrences involving the Emergency Control Room Air Conditioning are
- 0 6 LER 50-368/79-053 and 79-050.
- 0 7 This occurrence is reportable per I.S.6.9.1.9b.

0 8																											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34

0 9	SYSTEM CODE	A	A	11	CAUSE CODE	E	12	CAUSE SUBCODE	B	13	COMPONENT CODE	H	T	I	X	C	H	14	COMP. SUBCODE	C	15	VALVE SUBCODE	Z	16					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34		
17	LER/HO REPORT NUMBER	7	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	
21	EVENT YEAR	7	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	
23	SEQUENTIAL REPORT NO.	0	1	7	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	
24	REPORT TYPE	L																											
25	REVISION NO.	1																											
26	COMP. MANUFACTURER	C	I	7	8	9	0	1	8	0	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

- 1 0 Immediate corrective action was to reset the low discharge oil pressure
- 1 1 switch and prove operable per procedure 2104.34. Investigation revealed
- 1 2 a crankcase oil leak. The leak was repaired, oil and freon were added,
- 1 3 and the unit was operational checked out.

1 4																												
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	

1 5	FACILITY STATUS	B	28	% POWER	0	5	0	29	PWR. ESC. TEST.	30	OTHER STATUS																	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	
31	METHOD OF DISCOVERY	A																										
32	DISCOVERY DESCRIPTION																											

1 6	ACTIVITY CONTENT	RELEASED OF RELEASE	Z	33	Z	34	NA																						
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34		

1 7	PERSONNEL EXPOSURES NUMBER	0	0	0	37	Z	38	DESCRIPTION	39	NA																		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	

1 8	PERSONNEL INJURIES NUMBER	0	0	0	40	NA																						
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	

1 9	LOSS OF OR DAMAGE TO FACILITY TYPE	Z	42	NA																								
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	

1 0	PUBLICITY ISSUED DESCRIPTION	N	44	NA																								
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	

1 1	NRC USE ONLY																											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	

NAME OF PREPARER Chris N. Shively

PHONE: 501/968-2519  
1038 282