

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | C | B | E | P | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 14 15 25 26 57 CAT 58

CONT
0 1 | L | 0 | 5 | 0 | - | 0 | 3 | 2 | 4 | 7 | 0 | 9 | 0 | 8 | 7 | 9 | 8 | 1 | 0 | 0 | 1 | 7 | 9 | 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | During a normal reactor startup, the operator noticed that rod 26-07 had no position
0 3 | indication at notch 48. All other indications were normal.
0 4 | Technical Specification 3.1.3.7, 6.9.1.9b
0 5 |
0 6 |
0 7 |
0 8 | _____

0 9 | I | D | E | A | I | N | S | T | R | U | I | Z |
7 8 9 11 12 13 18 19 20
17 | LER/RO REPORT NUMBER 7 9 | - | 0 7 6 | / | 0 3 | L | - | 0 |
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUPL. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X X Z Z 0 0 0 0 N Y N G 0 8 0
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | Rod 26-07 was operationally tested and no problem could be found with position indica-
1 1 | ting probe. The rod was notch in to notch 46 and back to notch 48 and normal indica-
1 2 | tion returned. An Engineering Work Request had been written to investigate the
1 3 | position indicating system due to the number of position indicating failure we have
1 4 | been experiencing.

1 5 | C | 0 3 0 | NA | A | Operator Surveillance
7 8 9 10 11 12 13 30 31 32

1 6 | Z | Z | NA | NA
7 8 9 10 11 33 34 35 36

1 7 | 0 0 0 | Z | NA
7 8 9 10 11 12 13 37 38 39

1 8 | 0 0 0 | NA
7 8 9 10 11 12 40 41

1 9 | Z | NA
7 8 9 10 42 43

2 0 | N | NA
7 8 9 10 44 45

7910090397

1114 127