

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 VANAS1 200-000000-000 341111 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CONT

01 L 015000338 7 0 0 4 7 9 8 1 0 0 3 7 9 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 On September 4, 1979, during Mode 1 operation, the motor driven auxiliary feedwater
03 pump 1-FW-P-3A became inoperable when the pump's lube oil strainer was removed for
04 maintenance after a lower than usual lube oil pressure was observed. The health and
05 safety of the general public were not affected by this incident because the redundant
06 auxiliary feedwater pumps 1-FW-P-3B and 1-FW-P-2 remained available for operation if
07 required. Reportable pursuant to T.S. 6.9.1.9.b.

08 _____ 80

09 H H 11 E 12 X 13 F I L T E R 14 Z 15 Z 16
7 8 9 10 11 12 13 18 19 20
17 7 9 1 0 8 0 3 L 0
21 22 23 24 26 27 28 29 30 31
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMF SUPPLIER COMPONENT MANUFACTURER
D 18 Z 19 Z 20 Z 21 0 0 0 0 V 23 N 24 A 25 C 7 4 5 26
33 34 35 36 37 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The decrease in the pump's lube oil pressure was caused by a partially clogged lube
11 oil strainer. After being removed and disassembled, the strainer was cleaned, adjust-
12 ed, and reinsta led.

13 _____
14 _____ 80

15 E 28 0 9 2 29 NA B 31 Surveillance Test 32
7 8 9 10 11 12 13 44 45 46 80

16 Z 33 Z 34 NA NA 35 NA 36
7 8 9 10 11 12 13 44 45 80

17 0 0 0 37 Z 38 NA 39
7 8 9 10 11 12 13 80

18 0 0 0 40 NA 41 1135 265
7 8 9 10 11 12 80

19 Z 42 NA 43
7 8 9 10 80

20 N 44 NA 45 7910100 337 S 68 69 80
7 8 9 10 80

NAME OF PREPARER W. R. CartwrightPHONE 703-894-5151

NRC USE ONLY

Virginia Electric and Power Company
North Anna Power Station, Unit #1
Docket No. 50-338
Report No. LER 79-108/03L-0

Attachment: Page 1 of 1

Description of Event

On September 4, 1979, during the performance of the monthly surveillance test, the lube oil pressure for the motor driven auxiliary feedwater pump 1-FW-P-3A was observed to be lower than usual. The pump's lube oil strainer was removed for maintenance rendering 1-FW-P-3A inoperable. This event is contrary to T.S. 3.7.1.2.a.

Probable Consequences of Occurrence

The consequences of this event were limited because the redundant motor driven auxiliary feedwater pump as well as the steam driven auxiliary feedwater pump were both available for operation if required. As a result, the public health and safety were not affected by this event. There are no generic implications associated with this occurrence.

Cause of Occurrence

The low lube oil pressure was caused by the lube oil strainer being partially clogged.

Immediate Corrective Action

The lube oil strainer was removed and disassembled to allow for cleaning. After being thoroughly cleaned, the strainer was adjusted and reinstalled.

Scheduled Corrective Action

No scheduled corrective action required.

Actions Taken to Prevent Recurrence

No further actions are required.