LICENSEE EVENT REPORT

CONTROL BLOCK:	D INFORMATION)
0 1 V A N A S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 4 57 CAT 58 5
DOCKET NUMBER	1 1 2 7 9 9 EPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0] 2 On September 13, 1979, during Mode 1 operation, loop B steam flow in	ndicator FI-1485
[0]3] read lower than the redundant indicator FI-1484. After ensuring that	it an actual low
o a steam flow did not exist, the channel was placed in the tripped condition and	
[0]5] [declared inoperable. Since the affected channel was placed in "Test	" and the redun-
[0]6] [dant channel remained operable, the health and safety of the general public were not]	
[0] [jeopardized. Reportable pursuant to T.S. 6.9.1.9.b.	
7 8 9 SYSTEM CAUSE CAUSE COMP.	VALVE 80
CODE SUBCODE COMPONENT CODE SUBCODE SU	D 16
17 REPORT 7 9 - 1115 CODE TYPE	No 0
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME CONTRACT ON PLANT METHOD HOURS 22 SUBMITTED FORMSUB, SUPPL	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	(25) V 1 3 5 (26)
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [1] O Steam flow indicator FI-1485 indicated low because the root valves	for the trans-
[1] [mitter were leaking causing a loss of reference leg level. The steam	m flow channel
[1] [was placed in the tripped condition and the loop was calibrated and functionally	
[1]3 tested satisfactorily. The transmitter root valve will be reworked	during the
[1]4] [current refueling outage.	80
FACILITY STATUS 30 METHOD OF DISCOVERY DE DISCOVERY DE LA 31 Operator Observation 15 Page 14 Page 15 P	SCRIPTION (32)
ACTIVITY CONTENT RELEASED OF RELEASE 1 6 Z 3 3 Z 34 NA	ELEASE (36)
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 1 7 0 0 37 Z 38 NA	
PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA	80
1 9 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA	1168 146
7 8 9 10 PUBLICITY ISSUED DESCRIPTION 45	NRC USE ONLY
2 0 N (44) NA	69 80 %
NAME OF PREPARER W. R. La, twright PHONE 70	3-894-5151 %

Virginia Electric and Power Company North Anna Power Station, Unit #1 Docket No. 50-338 Report No. LER 79-115/03L-0

Attachme : Page 1 of 1

Description of Event

On September 13, 1979, during Mode 1 operation at 49% power, loop B steam flow indicator FI-1485 gave a low flow indication. The redundant loop B steam flow indicator FI-1484 did not indicate a low flow. The affected channel was placed in the tripped condition and declared inoperable.

Probable Consequences of Occurrence

Steam line flow is used to initiate both a reactor trip and a safety injection. A safety injection will occur on a high steam line flow coincident with low steam line pressure or low-low TAVG. A reactor trip will be actuated by a steam flow/feedwater flow mismatch and low steam generator level. Since the affected steam flow channel was placed in the tripped condition and the redundant channel remained operable, the health and safety of the general public were not affected by this event. There are no generic implications associated with this occurrence.

Cause of Occurrence

Loop B steam flow indicator FI-1485 gave low indication because the root valves for the flow transmitter were both leaking causing a loss of reference leg level.

Immediate Corrective Action

The channel was placed in the tripped condition and the root valve was temporarily repaired.

Scheduled Corrective Action

The transmitter root valves will be reworked during the refueling outage presently in progress.

Actions Taken to Prevent Recurrence

No further actions are required.