

## UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

OCT 1 1979

Docket No. 50-346

Toledo Edison Company ATTN: Mr. Richard P. Crouse

> Vice President Energy Supply

Edison Plaza 300 Madison Avenue Toledo, OH 43652

Gentlemen:

The enclosed IE Information Notice No. 79-24 provides information with regard to an analysis that identifies as event that could result in overpressurization of containment at a pressurized water reactor.

Sincerely,

James G. Keppler Director

Enclosure: IE Information Notice No. 79-24

cc w/encl:
Mr. T. Murray, Station
Superintendent
Central Files
Director, NRR/DPM
Director, NRR/DOR
PDR
Local PDR
NSIC
TIC
Harold W. Kohn, Power
Siting Commission
Helen W. Evans, State
of Ohio

1177 197

SSINS: 6870 Accession No: 7908220123

## UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D. C. 20555

DUPLICATE

October 1, 1979

IE Information Notice No. 79-24

OVERPRESSURIZATION OF CONTAINMENT OF A PWR PLANT AFTER A MAIN STEAM LINE BREAK

Virginia Electric and Power Co. submitted a report dated September 7, 1979 that identified a deficiency in the original analyses of containment pressurization as a result of a steam line break for North Anna Power Station, Units 3 and 4.

Stone and Webster Engineering Corporation performed a reanalyses of containment pressure following a main steam line break and determined that, if the auxiliary feedwater system continued to supply feedwater at runout conditions to the steam generator that had experienced the steam line break, containment design pressure would be exceeded in approximately 10 minutes. The long term blowdown of the water supplied under runout conditions by the auxiliary feedwater system had not been considered in the earlier analyses. The corrective action is now under review by the owner, architect engineer, and NSSS supplier.

This Information Notice is provided as an early notification of a possibly significant matter that is still under review by the NRC staff. It is expected that recipients will review the information for possible applicability to their facilities. No specific action or response is requested at this time. If NRC evaluations so indicate, further licensee actions may be requested or required.

No written response to this Information Notice is required. If you have any questions regarding this matter please contact the Director of the appropriate NRC Regional Office.

Enclosure: List of IE Information Notices Issued in the Last Six Months

2

1177 198

## LISTING OF IE INFORMATION NOTICES ISSUED IN LAST SIX MONTHS

| Subject   | Date<br>Issued   | Issued To  |
|---|--|--|
| Nonconforming Pipe<br>Support Struts  | 4/16/79  | All power reactor facilities with a CP   |
| Lower Reactor Vessel Head<br>Insulation Support Problem   | 5/7/79   | All holders of Reactor<br>OLs and CPs  |
| Attempted Damage to New<br>Fuel Assemblies  | 5/11/79  | All Fuel Facilities<br>Research Reactors,<br>and Power Reactors<br>with an OL or CP  |
| Indication of Low Water<br>Level in the Oyster Creek<br>Reactor   | 5/29/79  | All Holders of Reactor<br>OLs and CPs  |
| NRC Position of Electrical<br>Cable Support Systems   | 6/11/79  | All Power Reactor<br>Facilities with a<br>CP   |
| Deficient Procedures  | 6/7/79   | All Holders of Reactor<br>OLs and CPs  |
| Nuclear Incident at Three<br>Mile Island  | 6/22/79  | All Research Reactors<br>and Test Reactors<br>with OLs   |
| Source Holder Assembly Damage<br>Damage From Misfit Between<br>Assembly and Reactor Upper<br>Grid Plate | 6/20/79  | All Holders of Reactor<br>OLs and CPs  |
| Skylab Reentry  | 7/5/79   | All Holders of Reactor<br>OLs  |
| Pipe Cracks In Stagnant<br>Borated Water Systems At<br>PWR Plants                                       | 7/17/79  | All Holders of Reactor<br>OLs and CPs  |
|   | Nonconforming Pipe Support Struts  Lower Reactor Vessel Head Insulation Support Problem  Attempted Damage to New Fuel Assemblies  Indication of Low Water Level in the Oyster Creek Reactor  NRC Position of Electrical Cable Support Systems  Deficient Procedures  Nuclear Incident at Three Mile Island  Source Holder Assembly Damage Damage From Misfit Between Assembly and Reactor Upper Grid Plate  Skylab Reentry  Pipe Cracks In Stagnant Borated Water Systems At | Nonconforming Pipe Support Struts  Lower Reactor Vessel Head Insulation Support Problem  Attempted Damage to New Fuel Assemblies  Indication of Low Water Level in the Oyster Creek Reactor  NRC Position of Electrical Cable Support Systems  Deficient Procedures  6/7/79  Nuclear Incident at Three Mile Island  Source Holder Assembly Damage 6/20/79 Damage From Misfit Between Assembly and Reactor Upper Grid Plate  Skylab Reentry  7/5/79  Pipe Cracks In Stagnant Borated Water Systems At |

## LISTING OF IE INFORMATION NOTICES ISSUED IN 1979

| Information<br>Notice No. | Subject  | Date<br>Issued | Issued To  |
|---------------------------|--|----------------|--|
| 79-20                     | NRC Enforcement Policy<br>NRC Licensed Individuals                     | 8/10/79        | All Holders of Reactor<br>OLs and CPs and Production<br>Licensees with Licensed<br>Operators |
| 79-21                     | Transportation and Commercial 9/7/79<br>Burial of Radioactive Material |                | All power and research reactors with OL's  |
| 79-22                     | Qualification of Control<br>Systems                                    | 9/14/79        | All power reactor facilities with operating licenses and construction permits.               |
| 79-23                     | Emergency Diesel Generator<br>Lube Oil Coolers                         | 9/26/79        | All Power facilities holding OLs and CPs   |

1177 200