NRC FORM 366 **U. S. NUCLEAR REGULATORY COMMISSION** (7.77) . . LICENSEE EVENT REPORT 10 CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 0 0 0 0 0 0 - 0 0 3 LICENSE NUMBER 25 0 1 B E (2)(5) 0 0 LICENSEE CODE CON'T REPORT 0 1 2 5 () 1 0 ]2 7 8 - 0 3 L(6)0 5 SOURCE REPORT DATE EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During normal operation, the operator noticed that the containment 0 2 atmospheric monitor 1-CAC-1263-2 had an unexplained shift in its output. 03 0 4 0 5 0 6 0 7 Technical Specifications 3.3.5.3, 6.9.1.9.b 0 8 80 SYSTEM CAUSE CAUSE COMP SUBCODE COMPONENT CODE SUBCODE SUBCODE E E (12) G (13) N S T R U (14 S X (15) Z (16) (11 12 SEQUENTIAL OCCURRENCE REPORT REVISION REPORT NO. CODE LER RO TYPE NO. (17) REPORT 19 0 0 0 NUMBER 30 11 32 COMPONENT ACTION FUTURE EFFECT ON PLANT SHUTDOWN ATTACHMENT NPRD-4 PRIME COMP. HOURS (22) FORM SUB. SUPPLIER (18) C Z (21) (19 Z (20) 0 0 0 (23) Y (24) (25) 0 Y B 1 3 5 (26) A CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) 10 investigation determined that the magnetic amplifier was failing intermittently An The amplifier was replaced and the monitor was returned to service. 1 1 Since air dryers were installed on these instruments two years ago, the problems with the 1 2 magnetic amplifiers have been significantly reduced. Due to the problems being 1 3 experienced with these containment monitors, Engineering is evaluating other 1 4 FACILITY METHOD OF OTHER STATUS 30 S POWER DISCOVERY DESCRIPTION (32) E 28 0 9 1 29 1 5 (31) NA Operator Surveillance 10 ACTIVITY CONTENT 80 AMOUNT OF ACTIVITY (35 RELEASED\_OF RELEASE LOCATION OF RELEASE (36) 3 23 6 Z NA NA 10 11 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE 0 (37) (38 0 Z NA PERSONNEL INJURIES DESCRIPTION (41) 391 NUMBER 01 0 (40) 0 NA 12 SOLOSS OF OR DAMAGE TO FACILITY (43) 80 TYPE DESCRIPTION 791126021 Z (42) NA PUBLICITY NRC USE ONLY DESCRIPTION (45) SSUED N 44 91 7-92 NA 10 68 69 80 A. C. Tollison, Jr. 919-457-9521 NAME OF PREPARER -PHONE: -

LER CONTINUATION - RO# 1-79-90

Facility: BSEP Unit No. 1

. ...

Event Date: 10-27-79

instrumentation to replace that now in use.

1391 118