LICENSEE EVENT REPORT

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N C B E P 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 15 CAT 58
CON'T	REPORT L 6 0 5 0 - 0 3 2 4 7 1 0 2 5 7 9 8 1 1 1 9 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) While performing PT 46.3, Control Building Chlorine Detection Test, the "Control
0 3	Building Intake Air High Chlorine" alarm did not annunciate on either unit.
0 4	
0 5	
0 6	
0 7	
7 8	Technical Specifications 3.3.5.5, 6.9.1.9b SYSTEM CAUSE CAUSE CAUSE COMP. VALVE
0 9	CODE SUBCODE COMPONENT CODE SUBCODE SU
	17 REPORT 7 9 0 9 4 0 3 L 0
	ACTION FUTURE EFFECT SHUTDOWN TAKEN ACTION ON PLANT METHOD HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER
	B B B F 19 Z 20 Z 21 10 0 0 0 Y 23 Y 24 A 25 X 9 9 9 20
110	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The internal power leads for both units were found lifted and were immediately
	terminated. It is believed that these leads were lifted during recent annunciator
	ground testing and not reconnected. The crew involved has been counseled on the
1 2	potential personnel and plant consequences incurred by this type of procedural
1,3	violation. All I&C and Electrical personnel will receive refresher training in
7 8	9 80
1 5	E 28 0 9 1 29 N/A B 31 Periodic Test
	9 10 12 13 44 45 46 RELEASE OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
7 8	Z 33 Z 34 N/A N/A N/A BO PERSONNEL EXPOSURES
1 7	NUMBER TYPE DESCRIPTION 39 N/A
7 8	PERSONNEL INJURIES 13 NUMBER DESCRIPTION 41
7 8	O O O O O O O O O O O O O O O O O O O
1 9	Z 42 N/A
[2]0	PUBLICITY ISSUED DESCRIPTION 45 N/A NRC USE ONLY N/A
, .	9 10 68 69 80 5 NAME OF PREADER A. C. Tollison, Jr. PHONE 919-457-9521

LER CONTINUATION -- RO# 2-79-94

Facility: BSEP Unit No. 2

Event Date: 10-25-79

the "Jumper & Wire Removal Procedure." An investigation is in progress at this time to ensure that all other annunciator wires are terminated correctly.

1401 255

331