LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 G A E I H 2 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
REPORT L 6 0 5 0 0 0 3 6 6 7 1 0 3 0 7 9 8 1 1 1 1 9 7 9 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 While performing surveillance procedure HNP-2-3307, HPCI Steam Line dP Functional
Test and Calibration, the No. 2 contact of 2E41-N004 actuated at +200 inches of
The Table Service State to State to State of votor for this instrument. The
No. 1 contact of 2E/1-NOO/ actuated within tolerance. Both contacts of 2E/1-NOO5 1
o 6 in the other channel were found to be set properly. Therefore, the HPCI system
would have operated satisfactorily. There was no effect on plant personnel, equip-
ment or the environment. A similar occurrence was reported on LER 2-79-83.
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
17) REPORT 7 9
The cause has been attributed to instrument drift. The instrument was recalibrated
and surveillance procedure HNP-2-3307 was performed satisfactorily.
13
7 8 9
FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 6 9 9 29 NA B 31 Surveillance Testing 7 8 9 10 12 13 44 45 46 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA NA NA NA NA NA NA NA NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA NA
7 8 9 PERSONNEL INJURIES 13 NA 1390 172 NA 1390 172
7 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA 7 311260 287 80
7 6 9 10 PUBLICITY (45) NRC USE ONLY
SSUED DESCRIPTION (45) NA SECOND N
NAME OF PREPARER R. T. Nix PHONE: 912-367-7781