

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I L Z I S I 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

CON'T REPORT SOURCE L 0 5 0 0 0 2 9 5 7 1 0 1 6 7 9 8 1 1 1 3 7 9 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During a purge of Unit 1 containment, the containment purge iodine rad monitor, IRT-PRO9B, failed low. The purge was secured. The monitor was taken OOS. Shiftly grab sampling was initiated, as required by T.S. 3.14.1.c, but no samples were actually taken because the monitor was back in service within 1 shift. There were no safety implications and the health and safety of the general public was not affected.

0 9 M C 11 E 12 D 13 I N S T R U 14 E 15 Z 16

17 LER/RO REPORT NUMBER 7 9 0 7 4 0 3 L 0

A 18 Z 19 Z 20 0 0 0 0 22 N 23 N 24 A 25 N 3 0 5 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The detector was found to be defective, due to crud buildup around the seal and caused by corrosion. The detector was replaced (NMC P/N SC-2-1SL). The monitor was tested and returned to service; the purge was continued. This is the first incidence of this cause. No further corrective action is necessary.

1 5 H 28 C 0 0 0 29 NA 30 A 31 Operator Observation 32

1 6 Z 33 Z 34 NA 35 NA 36

1 7 0 0 0 37 Z 38 NA 39

1 8 0 0 0 40 NA 41

1 9 Z 42 NA 43

2 0 N 44 NA 45 1399 116 312-746-2084

POOR ORIGINAL

7911270 333

NAME OF PREPARER Fred Ost

PHONE 312-746-2084

1-226