



# Public Service Company of Colorado

16805 Weld County Road 19 1/2, Platteville, Colorado 80651

November 20, 1979  
Fort St. Vrain  
Unit No. 1  
P-79276

Mr. Karl V. Seyfrit, Director  
Nuclear Regulatory Commission  
Region IV  
Office of Inspection and Enforcement  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, Texas 76012

REF: Facility Operating License  
No. DPR-34

Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/  
79-41/03-X-1, Supplement, submitted per the requirements of Technical  
Specification AC 7.5.2(b)4.

Also, please find enclosed one copy of the Licensee Event Report for  
Reportable Occurrence Report No. 50-267/79-41/03-X-1.

Very truly yours,

*Don Warembourg*  
Don Warembourg  
Manager, Nuclear Production

DW/cis

cc: Director, MIPC

1470 349

7912040 296

A002  
S  
11/1  
S

REPORT DATE: November 19, 1979

REPORTABLE OCCURRENCE 79-41

OCCURRENCE DATE: October 26, 1979

ISSUE 1

Page 1 of 2

FORT ST. VRAIN NUCLEAR GENERATING STATION  
PUBLIC SERVICE COMPANY OF COLORADO  
16805 WELD COUNTY ROAD 19 1/2  
PLATTEVILLE, COLORADO 80651

REPORT NO. 50-267/79-41/CL .1

Supplement

IDENTIFICATION OF  
OCCURRENCE:

A malfunction of helium circulator IC speed modifier caused loss of Plant Protective System function of high speed trips. This resulted in operation under a degraded mode permitted by LCO 4.4.1 and is reportable per Fort St. Vrain Technical Specification AC 7.5.2(b)2.

EVENT  
DESCRIPTION:

On October 26, 1979, while operating at 30% thermal power and 76 MW electrical power, operations personnel observed that one of three channels for the IC circulator speed protection tripped on low speed while the circulator was operating at approximately 4,500 rpm.

This resulted in loss of the speed signal and trip capability in one of the three associated high speed trip channels for the IC circulator. Two redundant channels were available and operable.

CAUSE  
DESCRIPTION:

Instrument calibration drift due to bridge unbalance.

The balancing problem is caused by a change in resistance between the two leads of the speed element and ground at the circulator connection end. The difference in resistance occurs over a period of time in the cable connectors as a result of the temperature and humidity of the ambient air.

CORRECTIVE  
ACTION:

Adjusting the IC circulator speed modifier restored overspeed protection to the affected channel.

As an interim measure, the adjustment of the speed modifiers is being checked on a weekly basis.

New connectors have been ordered and will be environmentally qualified for installation. The results will be reported in a future supplemental report.

1470 50

Prepared by: Michael J. Ferris  
Michael J. Ferris  
Technical Services Engineer

Reviewed by: J. W. Gahm  
J. W. Gahm  
Technical Services Supervisor

Reviewed by: Frank M. Mathie  
Frank M. Mathie  
Operations Manager

Approved by: Don Warembourg  
Don Warembourg  
Manager, Nuclear Production

1470 351