

710

**DAIRYLAND POWER COOPERATIVE**

*La Crosse, Wisconsin*

54601

October 24, 1979

In reply, please  
refer to LAC-6602

DOCKET NO. 50-409

Mr. James G. Keppler  
Regional Director  
U. S. Nuclear Regulatory Commission  
Directorate of Regulatory Operations  
Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

SUBJECT: DAIRYLAND POWER COOPERATIVE  
LA CROSSE BOILING WATER REACTOR (LACBWR)  
PROVISIONAL OPERATING LICENSE NO. DPR-45  
IE BULLETIN NO. 79-02 - PIPE SUPPORT BASE PLATE  
DESIGNS USING CONCRETE EXPANSION ANCHOR BOLTS

- Reference: (1) NRC Letter, Keppler to Linder, dated  
March 8, 1979, enclosing IE Bulletin  
No. 79-02.  
(2) NRC Letter, Keppler to Linder, dated  
June 21, 1979, enclosing IE Bulletin  
No. 79-02, Revision 1.  
(3) DPC Letter, Linder to Keppler, LAC-6389,  
dated July 6, 1979.  
(4) DPC Letter, Linder to Keppler, LAC-6483,  
dated August 23, 1979.

Dear Mr. Keppler:

The La Crosse Boiling Water Reactor recently completed an unscheduled cold shutdown which allowed us to verify the actual installation of the pipe support base plates that were in areas restricted to no-entry during reactor operation.

The pipe support on the Decay Heat System that had not been inspected in Reference 4 was found to be installed in accordance with design.

The three pipe supports on the recirculation piping (Item 1 on page 3 of Reference 4) were found not to be in accordance with design. The base plates were found to be welded to plates imbedded in the concrete floor and were not fastened by concrete anchors. This installation was determined to be superior to that designed and therefore this portion of the system is capable of continued safe operation.

1550 024

NOV 23 1979

7912130 006

Mr. James G. Keppler  
Regional Director

LAC-6602  
October 24, 1979

However, inspection of recirculation piping in other areas of no-entry during reactor operation revealed that 4 pipe hanger installations that were designed to be welded to imbedded plates were in fact installed with concrete anchors. Measurements of the base plates and bolt hole locations and other data were made and sent to our design consultants for analysis and evaluation.

Based on their analysis, we believe that the recirculation system is capable of continued safe operation with the present anchor bolt hangers.

Since these discrepancies do exist between design drawings and actual installations, DPC will design and install new hanger installations in accordance with current criteria. Since the October 1979 outage was not conducted as planned earlier, it is our intention to commence a hanger replacement program during the next scheduled refueling outage. This outage is expected to occur in March 1980. Every effort would be made to complete the replacements during the outage.

If there are any questions regarding this submittal, please contact us.

Very truly yours,

DAIRYLAND POWER COOPERATIVE



Frank Linder, General Manager

FL:HAT:af

cc: U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Division of Reactor Operations Inspection  
Washington, D. C. 20555

1550 025