**NORTHEAST UTILITIES** 



P.O. BOX 270 HARTFORD, CONNECTICUT 06101 (203) 666-6911

November 8, 1979

Docket No. 50-245

Mr. Boyce H. Grier, Director Region I Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

- References: (1) W. G. Counsil letter to B. H. Grier dated August 1, 1979.
  - (2) W. G. Counsil letter to B. H. Grier dated August 31, 1979.
  - (3) W. G. Counsil letter to B. H. Grier dated September 28, 1979.

Gentlemen:

Millstone Nuclear Power Station, Unit No. 1 Response to I&E Bulletin No. 79-14

References (1), (2), and (3) provided status reports of the inspections required by I&E Bulletin No. 79-14. This letter transmits an update report of Northeast Nuclear Energy Company's (NNECO) progress in verifying the seismic analysis input for safety-related piping systems.

The inspection and measurement phases of all accessible piping and supports contained in the 21 systems under investigation have now been completed. The attachment provides the results of this work. Based upon the high degree of confidence derived from the inspections that have been completed and the system work/ISI inside the drywell as outlined in References (1), (2), and (3) and within the attachment, NNECO reaffirms that the most prudent course available is the examination of the remaining inaccessible areas at the next refueling outage. Any shutdowns which may occur due to maintenance problems will be used to perform as much work as possible inside the drywell. A preliminary schedule will be submitted in early December, 1979, for any reanalysis and any modifications that may be required based on evaluations of deviations from the original design. Should you have any questions, please contact us.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

Vice President

1552 240

#### ATTACHMENT

MILLSTONE NUCLEAR POWER STATION, UNIT NO. 1

RESPONSE TO I&E BULLETIN NO. 79-14

1552 241

Twenty-one systems are included in the I&E Bulletin No. 79-14 investigations. These systems contain in excess of 21,000 feet of seismic Category I piping and 1,300 supports in accessible and inaccessible areas. The inspection and measurement phases of all accessible piping and supports contained in the 21 systems under investigation have been completed. This verification was conducted in accordance with I&E Bulletin No. 79-14 dated July 2, 1979, and revisions or supplements dated July 18, August 15, and September 7, 1979. All system analysis review packages for accessible areas have been forwarded to our architect engineering firm for stress analysis and support/restraint review. The piping lengths and the number of supports associated with each system are presented in Table I. Table II summarizes the verification effort to date indicating the proportion of accessible versus inaccessible piping and supports.

Throughout the inspection and measurement phase of this project, the need for accurate verification has been emphasized as well as the complete documentation of all deviations. By the utilization of two man teams, documentation and installation reviews, compiling deviation lists upon completion of walkdowns, spot checking of records, there is high confidence in the accuracy of the inspections completed. The deviations identified to date are recorded by separating them into three distinct categories:

#### Category 1: Minor Deviations

- Deviation will not adversely affect safe plant shutdown during a seismic event.
- · Deviation will not affect the results of the stress analysis.
- · Field fixes in some cases alleviates deviation (loose turnbuckles, etc.).

#### Category 2: Deviations Requiring Review

- Deviation requires review and potential reanalysis by stress analysis and support/restraint groups prior to final judgment as to severity of deviations.
- Deviations have been placed in this category by cognizant site engineer and stress analyst.

#### Category 3: Significant Deviation

- Deviation would affect safe plant shutdown during a seismic event.
- · Deviation in this category is classified as a nonconformance.

The following is presented as a summary of site inspection and measurement findings to date:

- . The vast majority of deviations are either Category 1 or 2.
- Of the 988 supports, two Category 3 deviations were discovered and corrected as follows:
  - 1. Service Water System
    - a. Installation of an anchor on 16"-SW-46
    - b. Installation of a restraint on 12"-SW-47 and 8"-SW-28
    - c. Installation of an anchor on 6"-SW-15
  - 2. Containment Cooling System
    - a. Installation of two anchors on 20"-CC-15a

After the initial engineering review uncovered the above nonconformances, recommendations to resolve the situation until a complete system reanalysis could be accomplished were forwarded to NUSCO and were implemented immediately, as described above. Technical Specifications and operational procedures were adhered to in all cases.

Of 988 supports reviewed, the locations requiring modifications represent 0.5 percent of the total number of supports reviewed. Although the nonconformances found were serious enough to require field modifications, the results of the total inspection and measurement effort have been excellent and confidence levels for work in the inaccessible areas is still high. As outlined in previous submittals, (References (1), (2), and (3)), there are many items which support this high level of confidence for inaccessible inspections. Additionally, the following list identifies supports/restraints that have been dye penetrant checked at the welded attachment to the pipe during ISI examinations.

Main Steam	Feedwater	Isolation Condens	Low Pressure Coolant Injection		
MSR-H2	FWR-H2	IC-H21			
MSR-H7	FWR-H4		CC-H101		
MSR-H8	FWR-H5	Cleanup Water	CC-H100		
MSR-H34	FWR-H11		CC-H104		
MSR-H22	FWR-H1.4	CUW-H5			
MSR-H14	FWR-H20				
	Recirculation	Core Spray	Shutdown Cooling		
	Н9	CS-H1	SHC-H44		
	H1.0	CS-H56	SHC-H46		
	SS2				

The following information represents the status of the systems presently under stress analysis and support/restraint review in the accessible areas. If a particular system has all accessible areas inspected, it may not be possible to completely review the stress problem because portions may be inaccessible. If this occurs, a review of the information available will be conducted; if it is deemed acceptable, the remainder of the review will be completed when the inaccessible portion is verified. If it is found to be questionable as to the acceptability of the accessible portion, then field modifications will be made to whatever extent is necessary to maintain system integrity.

#### System

Service Water

#### Analysis/Review Status

- Service water system in the reactor building and turbine building will be reviewed by stress analysis
- If reanalysis is required, NUSCO will perform
- Ebasco Support and Restraint Group will then review the supports utilizing the NUSCO stress information

Reactor Building Closed Cooling Water

· Review to begin shortly

Isolation Condenser

- Stress analysis of supply piping is acceptable
- NUSCO is to reanalyze vent and return piping
- Results will be forwarded to Ebasco Support and Restraint Group for review

Standby Liquid Control

- System required reanalysis
- Reanalysis performed and system found acceptable
- Support and Restraint Group now reviewing system

Secondary Cooling System

Review to begin shortly

Sy	s	t	e	m
Co	-	0		9

Core Spray

Containment Cooling/ Core Spray

Fuel Pool Cooling System

Shutdown Cooling System

Condensate System

Feedwater System

Reactor Water Cleanup

Standby Gas Treatment

Control Rod Hydraulic System

Nuclear Boiler

Radwaste System

Atmospheric Control System

Main, Extraction, and Auxiliary Steam

Fire, Domestic, and Condensate Transfer Systems

Primary Containment Coding Service Water

#### Analysis/Review Status

Review to begin shortly

Review to begin shortly

· Review to begin shortly

 Stress analysis review partially completed, review continuing

· Presently being reviewed

· Accessible areas have been reviewed

 Inaccessible area information is required to complete analysis properly

· Review to begin shortly

· Presently being reviewed

· Review to begin shortly

System is presently inaccessible

· Review to begin shortly

· Presently being reviewed

System is presently inaccessible

· Presently being reviewed

 Stress isometrics X-1, 2, and VI-6 being reviewed  Stress isometric VI-5 had been reviewed and requires reanalysis. NUSCO will perform the reanalysis

Diesel Generator Fuel Oil System

Review to begin shortly

Engineering reviews and stress analysis reviews accomplished by our architect engineering firm have not uncovered any nonconformances to-date, which have not either been corrected by the field modifications described previously or deemed acceptable by engineering review/analysis. In all cases, safe shutdown of the plant during a postulated seismic event was not jeopardized.

Based upon the high degree of confidence derived from the inspections that have been completed and the system work/ISI inside the drywell as outlined in References (1), (2), and (3) and within this report, the most prudent course available is still the examination of the remaining inaccessible areas at the next refueling outage. Preparations are underway to prepare to the maximum extent possible to conduct the surveys of inaccessible areas in the most expeditious and accurate manner possible.

1552 246

## PROJECT STATUS SUTURY

			Publi								~ :	· .
	70. 8. F. P.		Pre Prese	2/2	Pre 74 19. 00	10t. 10 10 10 10 10 10 10 10 10 10 10 10 10	Tot Survey 18.	Pet Suria	De Verifie	Sang.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Compri
. Service Water	1260		1120	140	140	9,7	92	92	5	4	100	
. Reactor Closed Cooling Water	2050	1300	1300	750	0	145	86	. 80	65	0	100	_
. Isolation Condenser	706	583	583	123	0	55	49	49	6	0	100	_
. Standby Liquid Control	300	225	225	75	0	37	30	30	7	0	100	_
. Secondary Cooling System	2464	2233	2233	231	0	123	115	115	8	0	100	_
Core Spray	1700	1400	1400	300	0	110	80	80	30	.0	100	
Core Spray	800	700	700	100	0	85	75	75	10	0	100	_
3. Fuel Pool Cooling System	1160	1000	1000	160	0	63	63	63	0	0	100	_
Shutdown Cooling System	790	620	620	170	0	68	56	56	12	0	100	
10. Condensate System	3650	1500	1500	2150	100	238	120	120	118	7	100	_

POOR ORIGINAL 1552 247

# TABLE I

### MILLSTONE UNIT NO. 1

### IE 79-14 AS BUILT VERIFICATION

.

# PROJECT INSPECTION & MEASUREMENT SUMMARY

TIEM	QUANTITY	PERCENT
Total Linear Feet to be Investigated (Accessible & Inaccessible)	21,657 FT	100%
Accessible Piping	13,700 FT	63%
Inaccessible Piping	7,957 FT	37%
Total Linear Feet Verified to Date .		
Accessible Piping	13,700 FT	100%
Inaccessible Piping	240 FT	3%
Total Number of Supports & Restraints to be Investigated (Accessible & Inaccessible)	1428	100%
Accessible Supports & Restraints	988	69%
Inaccessible Supports & Restraints	440	31%
Total Supports & Restraints Verified to Date		
Accessible Supports & Restraints	988	100%
Inaccessible Supports & Restraints	0	0%