POOR ORIGINAL Previous Report Date 6/26/79

NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

	LICENSEE EVENT REPORT EXHIBIT A
	CONTROL BLOCK:
0 1	A R A N 0 2 2 0 0 - 0 0 0 0 0 0 0
CON'T 0 1 7 8	SOURCE L 6 10 5 0 0 0 13 6 1 8 0 0 15 1 2 7 1 7 19 8 11 12 10 6 1 7 1 9 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During an NRC audit of Category "E" valve positions while in Mode 3
	operation, Low Pressure Safety Injection Discharge Header valve
0 3	
0 4	2SI-5091-3 was discovered to be in the closed position. The redundant
0 5	flow path, thru 2CV-5091, was operational; therefore, full Low Pressure
0 6	Injection flow would have been available if required. There have been
0 7	no similar occurrences. This occurrence is reportable per T.S.6.9.1.9.c.
0 8 7 8	9 - SYCIEM CAUSE CAUSE CAUSE COMP NAME
0 9	SYSTEM CAUSE CAUSE CODE SUBCODE COMPONENT CODE SUNCODE SUICODE
110	LERING TO BE ACTION FUTURE COMPONENT MANUFACTURER ACTION ON PLANT SHUTDOWN HOURS (27) ATTACHMENT NORW SUPPLIER MANUFACTURER SUPPLIER SUPPLIER MANUFACTURER SUPPLIER MANUFACTURER TO SUBMITTED TO SUBMITTED TO SUPPLIER MANUFACTURER TO SUPPLIER TO SUPPLIER MANUFACTURER TO SUPPLIER TO SUPPLIER MANUFACTURER TO SUPPLIER TO
11	discussed with the operating shift involved. The procedural valve
112	lineup sheets have been revised to separate those which can only be
1 3	Verified after Shutdown Cooling System realignment to LPSI. Valve
7 8	2SI-5091-3 was modified by installing an indicator opposite the actuator to assist in position verification. TATUS TATUS OTHER STATUS OF DISCOVERY DESCRIPTION (32) B) (8) (9) (9) (9) (9) (9) (9) (9) (12) (13) (13) (14) (15) (15) (15) (15) (15) (15) (15) (15
	LEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36
17	O O O O O O O O O O O O O O O O O O O
1 1 1 8	OSS OF OR DAMAGE TO FACILITY (43)
1 9	Z) 42 NA 1592 142
2101	SUED CESCRIPTION 45 NAC USE ONLY
	Chris N. Shively 501/968-2519
	NAME OF PREPARER CRITS N. SHIVELY PHONE SU1/900-2519