

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | G | A | E | I | H | 1 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 2 | 1 | 7 | 1 | 1 | 2 | 7 | 7 | 9 | 8 | 1 | 2 | 1 | 1 | 7 | 9 | 9

2 | While performing surveillance procedure HNP-1-3882, H<sub>2</sub> and O<sub>2</sub> Analyzer Instrument  
3 | Calibration, during steady state power operations, technicians found the oxygen  
4 | analyzers on P33-P001A and B out of tolerance. For an expected 5% oxygen concentra-  
5 | tion, P33-P001A indicated 3% and P33-P001B indicated 2.5% oxygen. There was no  
6 | affect on the environs. This is a non-repetitive event.

POOR ORIGINAL

9 | S | A | 11 | E | 12 | E | 13 | I | N | S | T | R | U | 14 | X | 15 | Z | 16  
17 | 7 | 9 | 0 | 9 | 6 | 0 | 3 | L | 0  
18 | Z | 19 | Z | 20 | 0 | 0 | 0 | 0 | Y | 23 | N | 24 | N | 25 | X | 9 | 9 | 9 | 26

0 | The cause of the occurrence has been attributed to instrument drift. The analyzers  
1 | were re-calibrated and successfully tested.

5 | E | 28 | 0 | 9 | 8 | 29 | NA | B | 31 | Surveillance Testing

6 | Z | 33 | Z | 34 | NA | NA

7 | 0 | 0 | 0 | 37 | Z | 38 | NA

8 | 0 | 0 | 0 | 40 | NA | 1592 298

42 | NA

0 | N | 44 | NA

NAME OF PREPARER R. T. Nix PHONE 12-367-7781 7912170 321

CPD 91-7-226

NARRATIVE REPORT

Georgia Power Company  
Plant E. I. Hatch  
Baxley, Georgia 31513

Reportable Occurrence Report No. 50-321/1979-096

While performing surveillance procedure HNP-1-3882, H<sub>2</sub> and O<sub>2</sub> Analyzer Instrument Calibration, during steady state power operation at 98% power, technicians found the oxygen analyzers on panel P33-P001A and B out of tolerance. For an expected 5% oxygen concentration "A" indicated 3% and "B" indicated 2.5% oxygen. There was no affect on the environs. This is a non-repetitive event. The cause of the occurrence has been attributed to instrument drift. The analyzers were re-calibrated and successfully retested. This problem is only applicable to Unit 1 because a different analyzer is utilized for the Unit 2 drywell/torus H<sub>2</sub> and O<sub>2</sub> analyzer. The analyzers are not utilized on any other safety related system on either unit.

1592 299