NIS

NONDESTRUCTIVE INSPECTION SERVICE, INC.

P. O. BOX 215

HURRICANE, WEST VA. 25526

2825 U. S. ROUTE 60 E.

PHONE A. C. 304
727-3501 QR 562-6835
November 30 1039

United States Niclear Regulatory Commission Region II 101 Marietta St., N.W. Suite 3100 Atlanta, Georgia 30303

Attention: Mr. James P. O'Reilly

RE: RII:RAB 47-11883 01

Dear Mr. O'Re'lly.

I have answered the violations noted diring Mr. Brown's inspection of October 10 and 12 1979.

It has been our intent to operate in a safe and efficient matter.

We weldome your visits and suggestions any time.

If you have any further questions, contack me anytime.

Yours truly,

H. M. Haildren, President

HMH/db

POOR ORIGINAL

2177 058

7912260

336

License No. 47-1883-01

Based on the NRC inspection October 10 and 12, 1979, certain of our activities were apparently not conducted in compliance with NRC requirements. Following are explanations to our violations as described in your letter of November 21, 1979

- A. As was explained in my letter of November 5, 1979, explaining the conditions of which I feel the over exposure was caused. I did investigate the situation on the job and explained the importance of wearing their film badge at all times, however no other person working that job had any abnormal exposure. Roger Massey, 210 MR, Ray Allen, 70 MR and Pat Kinder, 2030 MR. I have explained our emergency procedures to all radiographers on November 23, 1979 and again on November 26, 1979 in oir meetings on the findings of Mr. Brown. Ray Allen and myself will visit jobs more frequently to be sure these procedures are being followed.
- B. As required by CFR 20.405, I failed to report to the Niclear Regulatory Commission Regional Office and the U.S. Niclear Regulatory Commission, Washington, D. C. of the 3950 rems. our film badge report indicated, Pat Kinder had received. I was aware this was to be done. I have field notes of my visit to the job to investigate. It was an oversight in my not reporting this and in no way was there any intent to cover the situation up.
- C. On October 10, 1979, the day of the inspection by Mr. Brown source #13134 was in Camera #10 an Automation Industries Model 520, serial #567, with a strength of 116 curies. These cameras are designed to have plugs installed at the drive cable and source tub connectors, however, the plugs were not in their proper position at the time Mr. Brown took readings. When the plugs were installed in their proper positions the readings were as follows at a distance of 6" using a Gamma Model 25011 Survey Meter.

Left side 15 MR Front 14 MR Right side 15 MR Rear 18 MR Top 15 MR

With the plug removed and the camera locked and the source moved as far forward and reverse as possible, a reading of 380 MR was obtained.

License No. 47-1883-01

C cont'd.

A constant check will be made on all cameras and especially camera #10 to be sure a leakage problem does not exist. The manufactor, Automation Industries (Mr. Steve Boyko) has been notified of this condition and are ready to assist in correcting the problem. I have instructed each radiographer the plugs will be installed in all cameras when not in use and myself and Ray Allen, will see this is done.

- D. My not having knowledge of 2000 mr condition in the storage area I had not removed the tape covering the word High from the "Caution High Radiation Area" sign, that is located in the center of the storage door. Photo enclosed.
- E. In the future a survey will be made each time a camera is removed and returned to storage and recorded on a permanent storage record. A copy is enclosed.

2177 060

POOR ORIGINAL

NONDESTRUCTIVE INSPECTION SERVICE, INC.

PERMANENT STORAGE RECORD

Record	survey each	h time source	is removed and retur	ned to the permanent stora	ge area.
Camera	Number				
Source	Type				
Date	Removed	Time Out	Survey Results	Technician (Signed)	
14.2					

Date Returned	Time In	Survey Results	Technician (Signed)
		,	
-			

Keep posted in permanent storage and file weekly in office.



POOR ORIGINAL

2177 062