



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION V
1990 N. CALIFORNIA BOULEVARD
SUITE 202, WALNUT CREEK PLAZA
WALNUT CREEK, CALIFORNIA 94596

TIC

December 26, 1979

Docket Nos. 50-206, 50-361,
50-362

Southern California Edison Company
P. O. Box 800
2244 Walnut Grove Avenue
Rosemead, California 91770

Attention: Mr. A. Arenal, Vice President
Advanced Engineering

Gentlemen:

This Information Notice is provided as an early notification of a possibly significant matter. It is expected that recipients will review the Information Notice for possible applicability to their facilities. No specific action or response is requested at this time. However, we anticipate that further NRC evaluations will result in issuance of an IE Circular or Bulletin in the near future which will recommend or request specific applicant or licensee actions. If you have questions regarding the matter, please contact the Director of the appropriate NRC Regional Office.

Sincerely,

R. H. Engelken
Director

Enclosures:

1. IE Information Notice No. 79-33
2. List of Recently Issued Information Notices

cc w/enclosures:
J. M. Curran, SCE
J. T. Head, SCE
J. H. Drake, SCE

1737 341

8001110

Q33

Q

DUPLICATE

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

SSINS NO.: 6870
Accession No.:

December 21, 1979

10250

520

IE Information Notice No. 79-33

IMPROPER CLOSURE OF PRIMARY CONTAINMENT EQUIPMENT ACCESS HATCHES

Description of Circumstances:

On December 8, 1979 difficulty was experienced in establishing the required nitrogen pressure in primary containment during power range startup testing of the Browns Ferry Nuclear Plant, Unit 3, following a refueling outage. On December 9, 1979, the licensee found three loose bolts on an equipment hatch to be the cause of leakage from the primary containment. The leakage was calculated to have been ten times the allowable containment leakage rate. This hatch had previously passed a local leak rate test (LLRT) and an integrated leak rate test of the containment in November 1979. The reactor had returned to operation on December 6, 1979 from the refueling outage and had operated at power levels less than 25 percent since December 6, 1979.

A subsequent inspection by the licensee of both primary containment equipment access hatches for Unit 2 was performed. TVA reported on December 20, 1979, to the NRC that they had found six of twelve closing dogs on one hatch improperly aligned and one closing bolt not torqued. A LLRT, performed with the hatch in this condition, showed a leakage rate higher than normal but within Technical Specification limits. The second hatch on this unit was found to have eight of twelve closing dogs improperly aligned.

The licensee is in the process of inspecting the closure of both primary containment equipment access hatches on Unit 1 and is reinspecting these hatches on Unit 3.

It is anticipated that further NRC evaluation will result in issuance of an IE Circular or Bulletin in the near future which will recommend or request specific applicant or licensee actions.

This information is provided to inform licensees of a possibly significant matter. The improper closure of the primary containment access hatches resulted from a lack of procedures for torque values, sequence of torque, and alignment of the closing dogs. We expect that recipients will review the adequacy of their procedures for access hatch installation at all facilities. If installation procedures do not exist or are inadequate, inspection and local leak rate testing can be used to confirm containment penetration integrity. If you have any questions regarding this matter, please contact the Director of the appropriate NRC Regional Office.

No written response to this Information Notice is required.

1737 342

RECENTLY ISSUED
IE INFORMATION NOTICES

| Information Notice No. | Subject | Date Issued | Issued To |
|------------------------|---|-------------|---|
| 79-32 | Separation of Electrical Cables for HPCI and ADS | 12/21/79 | All power reactor facilities holding OLs and CPs |
| 79-31 | Use of Incorrect Amplified Response Spectra (ARS) | 12/13/79 | All holders of power reactor OLs and CPs |
| 79-30 | Reporting of Defects and Noncompliance, 10 CFR Part 21. | 12/6/79 | All power reactor facilities holding OLs and CPs and vendors inspected by LCVIP |
| 79-29 | Loss of NonSafety-Related Reactor Coolant System Instrumentation During Operation | 11/16/79 | All power reactor facilities holding OLs or CPs |
| 79-28 | Overloading of Structural Elements Due to Pipe Support Loads | 11/16/79 | All power reactor facilities with an OL or CP |
| 79-27 | Steam Generator Tube Ruptures At Two PWR Facilities | 11/16/79 | All power reactor facilities holding OLs and CPs |
| 79-12A | Attempted Damage To New Fuel Assemblies | 11/9/79 | All Fuel Facilities, research reactors, and power reactors with an OL or CP |
| 79-26 | Breach of Containment Integrity | 11/5/79 | All power reactor facilities holding OLs and CPs |
| 79-25 | Reactor Trips At Turkey Point Units 3 And 4 | 10/1/79 | All power facilities with an OL or a CP |
| 79-24 | Overpressurization Of Containment Of A PWR Plant After A Main Steam Line Break | 10/1/79 | All power reactor facilities with a CP |

1737 343