

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 101 MARIETTA ST., N.W., SUITE 3100 ATLANTA, GEORGIA 30303

JUN 6 1979

TIRA

In Reply Refer To: RII:JPO 50-348 50-364

> Alabama Power Company Attn: F. L. Clayton, Jr. Executive Vice President Post Office Box 2641 Birmingham, Alabama 35291

Gentlemen:

Enclosed is supplement IE Bulletin 79-01A. It requires action by you with regard to power reactor facilities with an operating license except for the 11 SEP plants which are listed in Enclosure 3.

This Bulletin is also being sent for information to the 11 SEP plants and all power reactor facilities with a construction permit. No action or written response is required for construction permit facilities or the 11 SEP plants.

Should you have questions regarding this Bulletin or the actions required of you, please contact this office.

Sincerely, James P. O'Reilly Director

Enclosures:

- 1. IE Bulletin No. 79-01A
- 2. List of IE Bulletins Issued in the past
  - 12 months
  - 12 MOLLIS
- 3. List of SEP Plants (11)

336 283

Alabama Power Company

cc w/encl: A. R. Barton Executive Vice President Post Office Box 2641 Birmingham, Alabama 35291

C. Biddinger, Jr. Manager-Corporate Quality Assurance Post Office Box 2641 Birmingham, Alabama 35291

N. O. Thrash Manager-Nuclear Generation Post Office Box 2641 Birmingham, Alabama 35291

H. G. Hairston, III Plant Manager Drawer 470 Ashford, Alabama 36312

R. E. Hollands, Jr. QA Supervisor Post Office Box U Ashford, Alabama 36312

# 336 284

7907020173

### -2-

#### UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D.C. 20555

June 6, 1979

IE Bulletin No. 79-01A

SUPPLEMENT NO. 79-01A TO IE BULLETIN 79-01 - ENVIRONMENTAL QUALIFICATION OF CLASS 1E EQUIPMENT (DEFICIENCIES IN THE ENVIRONMENTAL QUALIFICATION OF ASCO SOLENOID VALVES)

Description of Circumstances:

Recently, a noncompliance report under 10 CFR Part 21 was received by the NRC from the Henry Pratt Company, manufacturer of butterfly valves which are installed in the primary containment at the Three Mile Island Unit 2 Nuclear Station. These butterfly valves are used for purge and exhaust purposes and are required to operate during accident conditions. The report discusses the use of an unqualified solenoid valve for a safety-related valve function which requires operation under accident conditions. The solenoid valve in question is Catalogue No. HT-8331A45, manufactured by the Automatic Switch Company (ASCO) of Florham Park, New Jersey. This pilot valve is used to pilot control the pneumatic valve actuators which are installed on the containment ventilation butterfly valves at this facility.

The deficiency in these solenoid values identified in the Part 21 Report concerns the parts made of acetal plastic material. The acetal disc ho assembly and bottom plug in the pilot value assembly are stated by ASCO ave a maximum service limit of 400,000 Rad integrated dosage and 200 degrees temperature. According to ASCO, exposure of these acetal plastic parts to specified maximum environmental conditions may render the solenoid pilot value inoperable which would cause the associated butterfly value to malfunction.

Further investigation at ASCO by the NRC staff has revealed that the valve seals in most ASCO solenoid valves contain Buna "N" elastomer material, which reportedly has a maximum service limit of 7,000,000 Rad integrated dosage and 180 degrees F temperature. The investigation further revealed that ASCO has available a line of qualified solenoid operated pilot valves (ASCO Catalogue No. NP-1) which have no plastic parts, utilize ethylene propylene or viton elastomers and have a continuously energized operating life of four years, under normal embient conditions up to 140 degrees F. According to the manufacturer, at the end of this period, the coil, manual operator (optional feature) and all resilient parts must be replaced. These preventive maintenance instructions are specified in the installation and instruction bulletins which are provided to the purchaser with each shipment of solenoid valves.

The final items of concern identified during this investigation deals with the application of Class "A", "B", or "F", solenoid coils which are exposed to an accident environment. In this regard, ASCO representatives stated that the

336 285

#### IE Bulletin No. 79-01A

June 6, 1979 Page 2 of 3

336 286

high temperature coils identified as Class "HT" or "HB" are the only coils considered suitable for service under accident conditions; whereas, Class "A", "B", and "F" coils are not.

With respect to the corrective measures to be taken to resolve the above concerns, ASCO recommends the following:

- 1. The parts of the solenoid valve made of acetal plastic material should be replaced with similar parts made of metal which can be provided by ASCO.
- The valve seals and gaskets which are made of Buna "N" material should be replaced with either ethylene propylene or viton elastomers, considered by ASCO as suitable for the service intended.
- Review and determine that the coils of the solenoid valves installed inside containment are Class "HT" or "HB" as required for high temperature environmental conditions.
- 4. Review and determine that the solenoid enclosures installed inside containment have at least a NEMA 4 enclosure rating.
- 5. Establish a preventive maintenance program to assure replacement of those valve parts identified above in the time period recommended in the appropriate ASCO valve bulletin.
- 6. ASCO also stated that all unqualified solenoid valves inside containment be retrofitted to qualified ASCO No. NP-1 valves in lieu of the above.
- Questions from licensees to ASCO concerning corrective measures should reference both catalogue and serial numbers of each valve in question. These numbers are stamped on the metal nameplate on each solenoid valve.

Action to be Taken by Licensees of all Power Reactor Facilities (except those 11 SEP Plants listed on Enclosure 3) with an Operating License:

- Determine whether or not ASCO solenoid values are used or planned for use in safety-related systems at your facility(ies).
- 2. If such valves are used or planned for use, identify the safety system involved and determine that: (a) valves which could be subjected to a LOCA environment are qualified to that environment. Specifically that no parts made of acetal plastic or Buna "N" materials or Class "A", "B", or "F" solenoid coils are used in such valves; (b) a preventive maintenance program is being conducted suc? that the solenoid coil, the manual operator (if applicable), and the res ient parts of the valve are being replaced in accordance with the time period established by the manufacturer and documented as the qualified life of the assembled component.

#### IE Bulletin No. 79-01A

June 6, 1979 Page 3 of 3

3. All holders of operating licenses of power reactor facilities are obligated to meet the review and reporting requirements established in previously issued IE Bulletin 79-01, regarding environmental qualification of electrical equipment installed in their plants.

No additional written response to this Supplement IE Bulletin is required other than those responses described above. NRC inspectors will continue to monitor the licensees' progress in completing the requested action described above. If additional information is required, contact the Director of the appropriate NRC Regional Office.

Approved by GAO, B180225 (R0072); clearance expires 7/31/80. Approval was given under a blanket clearance specifically for identified generic problems.

336 280

IE Bulletin No. 79-01A June 6, 1979 Enclosure Page 1 of 3

# LISTING OF IE BULLETINS ISSUED IN LAST TWELVE MONTHS

| Bulletin<br>No.   | Subject  | Date Issued | Issued To   |
|-------------------|--|-------------|---|
| 79-12             | Short Period Scrams at<br>BWR Facilities   | 5′31/79     | All GE BWR Facilities with an OL  |
| 79-11             | Faulty Overcurrent Trip<br>Device in Circuit Breakers<br>for Engineered Safety<br>Systems                            | 5/22/79     | All Power Reactor<br>Facilities with an<br>OL or a CP   |
| 79-10             | Requalification Training<br>Program Statistics   | 5/11/79     | All Power Reactor<br>Facilities with an OL  |
| 79–09             | Failures of GE Type AK-2<br>Circuit Breaker in Safety<br>Related Systems   | 4/17/79     | All Power Reactor<br>Facilities with an<br>OL or CP   |
| 79-08             | Events Relevant to BWR<br>Reactors Identified During<br>Three Mile Island Incident                                   | 4/14/79     | All BWR Power Reactor<br>Facilities with an OL  |
| 79-07             | Seismic Stress Analysis<br>of Safety-Related Piping  | 4/14/79     | All Power Reactor<br>Facilities with an<br>OL or CP   |
| 79–06B            | Review of Operational<br>Errors and System Mis-<br>alignments Identified<br>During the Three Mile<br>Island Incident | 4/14/79     | All Combustion Engineer-<br>ing Designed Pressurized<br>Water Power Reactor<br>cilities with an<br>Operating Licensee |
| 79-06A<br>(Rev 1) | Review of Operational<br>Errors and System Mis-<br>alignments Identified<br>During the Three Mile<br>Island Incident | 4/18/79     | All Pressurized Water<br>Power Reactor Facilities<br>of Westinghouse Design<br>with an OL                             |
| 79-06A            | Review of Operational<br>Errors and System Mis-<br>alignments Identified<br>During the Three Mile<br>Island Incident | 4/14/79     | All Pressurized Water<br>Power Reactor Facilities<br>of Westinghouse Design<br>with an OL                             |

IE Bulletin No. 79-01A June 6, 1979

٠

Enclosure Page 2 of 3

## LISTING OF IE BULLETINS ISSUED IN LAST TWELVE MONTHS

| Bulletin<br>No.    | Subject   | Date Issued | Issued To  |
|--------------------|---|-------------|--|
| 79–06              | Review of Operational<br>Errors and System Mis-<br>alignments Identified<br>During the Three Mile<br>Island Incident                              | 4/11/79     | All Pressurized Water<br>Power Reactors with an<br>OL except B&W facilities          |
| 7905A              | Nuclei c Incident at<br>le Island   | 4/5/79      | All B&W Power Reactor<br>Facilities with an OL                                       |
| 79-05              | Nuclear Socident at<br>Three Mile Island  | 4/2/79      | All Power Reactor<br>Facilities with an<br>OL and CP                                 |
| 79-04              | Incorrect Weights for<br>Swing Check Valves<br>Manufactured by Velan<br>Engineering Corporation   | 3/30/79     | All Power Reactor<br>Facilities with an<br>OL or CP                                  |
| 79-03              | Longitudinal Welds Defects<br>In ASME SA-312 Type 304<br>Stainless Steel Pipe Spools<br>Manufactured by Youngstown<br>Welding and Engineering Co. | 3/12/79     | All Power Reactor<br>Facilities with an<br>OL or CP                                  |
| 7 <del>9</del> -02 | Pipe Support Base Plate<br>Designs Using Concrete<br>Expansion Anchor Bolts   | 3/2/70      | All Power Reactor<br>Facilities with an<br>OL or CP                                  |
| 79-01              | Environmental Qualification<br>of Class IE Equipment  | 2/8/79      | All Power Reactor<br>Facilities with an<br>OL or CP                                  |
| 8-14               | Deterioration of Buna-N<br>Component In ASCO<br>Solenoids   | 12/19/78    | All GE BWR facilities<br>with an OL or CP  |
| 78-13              | Failures in Source Heads<br>of Kay-Ray, Inc., Gauges<br>Models 7050, 7050B, 7051,<br>7051B, 7060, 7060B, 7061<br>and 7061B                        | 10/27/78    | All general and<br>specific licensees<br>with the subject<br>Kay-Ray, Inc.<br>gauges |

IE Bulletin No. 79-01A June 6, 1979

.

Enclosure Page 3 of 3

## LISTING OF IE BULLETINS ISSUED IN LAST TWELVE MONTHS

| Bulletin<br>No. | Subject   | Date Issued | Issued To   |
|-----------------|---|-------------|---|
| 78-12B          | Atypical Weld Material<br>in Reactor Pressure<br>Vessel Welds               | 3/19/79     | All Power Reactor<br>Facilities with an<br>OL or CP   |
| 8-12A           | Atypical Weld Material<br>in Reactor Pressure<br>Vessel Welds               | 11/24/78    | All Power Reactor<br>Facilities with an<br>OL or CP   |
| 8-12            | Atypical Weld Material<br>in Reactor Pressure<br>Vessel Welds               | 9/29/78     | All Power Reactor<br>Facilities with an<br>OL or CP   |
| 78-11           | Examination of Mark I<br>Containment Torus Welds                            | 7/21/78     | BWR Power Reactor<br>Facilities for action:<br>Peach Bottom 2 and 3,<br>Quad Cities 1 and 2,<br>Hatch 1, Monticello and<br>Vermont Yankee     |
| 78-10           | Bergen-Paterson Hydraulic<br>Whock Suppressor Accumulator<br>Spring Coils   |             | All BWR Power Reactor<br>Facilities with an<br>OL or CP   |
| 78-09           | BWR Drywell Leakage Paths<br>Associated with Inadequate<br>Drywell Closures | 6/14/79     | All BWR Power Reactor<br>Facilities with an<br>OL or CP   |
| 78-08           | Radiation Levels from Fuel<br>Element Transfer Tubes                        | 6/12/78     | All Power and Research<br>Reactor Facilities with<br>a Fuel Element transfer<br>tube and an OL  |
| 78-07           | Protection afforded by<br>Air-Line Respirators and<br>Supplied-Air Hoods    | 6/12/78     | All Power Reactor<br>Facilities with an OL,<br>all class E and F<br>Research Reactors with<br>an OL, all Fuel Cycle<br>Facilities with an OL, |

336 289

and all Priority 1 Material Licensees

# Enclosure No. 3

SEP Plants

| Plant          | Region |
|----------------|--------|
| Dresden 1      | III    |
| Yankee Rowe    | I      |
| Big Rock Point | III    |
| San Onofre 1   | v      |
| Haddam Neck    | I      |
| LaCrosse       | III    |
| Oyster Creek   | I      |
| R. E. Ginna    | I      |
| Dresden 2      | III    |
| Millstone      | I      |
| Palisades      | III    |

- 336 290