Homestake Mining Company of California



David W. Pierce Closure Manager

05 August 2019

Ashlynne Winton Mining Environmental Compliance Section Ground Water Quality Bureau New Mexico Environment Department P.O. Box 5469 Santa Fe, NM 87502

Ron C. Linton Project Manager/Hydrogeologist U.S. Nuclear Regulatory Commission Office of Nuclear Material Safety and Safeguards MS T-5A10, 11545 Rockville Pike Rockville, MD 20852

RE: Homestake Mining Company, Grants Reclamation Project, License Source Materials License SUA-1471, Docket Number 40-8903; NMED Discharge Permit DP-200: NMED 15-Day/NRC 30-Day Corrective Action Report for the Unauthorized Discharge from Evaporation Pond EP-1

Dear Ms. Winton/Mr. Linton:

This letter will serve as the 15-day report as required by 20.6.2.1203.A (6) NMAC in the Homestake Mining Company (HMC) New Mexico Environmental Department (NMED) Discharge Permit (DP-200). In addition, this letter will also serve as the 30-day report of a release as required by Condition 41 of Nuclear Regulatory Commission (NRC) Materials License SUA-1471. The letter report provides additional details regarding the unauthorized release of impacted water from HMC Evaporation Pond #1 (EP-1) as previously notified by letter on 7/30/2019 to the NMED and NRC.

In anticipation of the EP-1 re-lining project, the water level in EP-1 had been lowered during the spring. Since the re-lining project was deferred to 2020 and residual salts were exposed in EP-1, HMC commenced transferring water from Evaporation Pond #2 (EP-2) on July 11, 2019. The discharge stream into EP-1 tore a hole in the liner on July 23, 2019 and the transfer was stopped that afternoon, leaving an approximate six-inch hole in the liner slightly above the water line. An estimated volume of up to 12,000 gallons of brine was released through the tear. A photograph of the tear area is attached.

Repairs were performed on July 31, 2019. Sandbags were used to isolate the tear and then a fabric patch was used to cover the tear prior to application of Deery Oil #6 to seal the tear. A photograph showing the final patch is attached.

It should also be noted that EP-1 is located upgradient of the hydraulic barrier created by injection of water into the alluvial and Upper Chinle aquifers. Multiple injections wells are located downgradient of the evaporation ponds and help control potential migration of impacted groundwater from this area.

NMSSD1 NMSS

TELE: (505) 287-4456

If you have any questions or comments regarding this matter, please contact me via e-mail at <u>dpierce@homestakeminingcoca.com</u> or at the Grants office at 505.238.9701.

U

Respectfully,

Diene Savil W.


David W. Pierce Closure Manager Homestake Mining Company of California Office: 505.287.4456 x34 | Cell: 505.238.9701

Copy To:

Document Control, NRC (hard copy) Mark Purcell, EPA, Dallas, Texas (electronic copy) M. McCarthy, Barrick, Salt Lake City, Utah (electronic copy) C. Burton, Barrick, Henderson, Nevada (electronic copy) R. Whicker, ERG, Albuquerque, New Mexico (electronic copy)

attachment

Page 2 of 2



Photograph 1: View showing water discharge causing water/air to infiltrate below liner



Photograph 2: View showing liner after repair with fabric patch and sealed with Deery Oil #6