

677  
Pl. 5 encl.

NUCLEAR REGULATORY COMMISSION

---

IN THE MATTER OF:  
STATUS OF MAY 2 EVENT AT OYSTER CREEK

Place - Washington, D. C.  
Date - Wednesday, May 30, 1979  
Pages 1 - 32

---

311 036

Telephone:  
(202) 347-3700

ACE - FEDERAL REPORTERS, INC.

*Official Reporters*

444 North Capitol Street  
Washington, D.C. 20001

NATIONWIDE COVERAGE - DAILY 7907090

49  
019

DISCLAIMER

This is an unofficial transcript of a meeting of the United States Nuclear Regulatory Commission held on Wednesday, May 30, 1979 in the Commissions's offices at 1717 H Street, N. W., Washington, D. C. The meeting was open to public attendance and observation. This transcript has not been reviewed, corrected, or edited, and it may contain inaccuracies.

The transcript is intended solely for general informational purposes. As provided by 10 CFR 9.103, it is not part of the formal or informal record of decision of the matters discussed. Expressions of opinion in this transcript do not necessarily reflect final determinations or beliefs. No pleading or other paper may be filed with the Commission in any proceeding as the result of or addressed to any statement or argument contained herein, except as the Commission may authorize.

311 037

5072  
Hoffman  
Jeri

UNITED STATES OF AMERICA  
NUCLEAR REGULATORY COMMISSION

STATUS OF MAY 2 EVENT AT OYSTER CREEK

Room 1130  
1717 H Street, N.W.  
Washington, D. C.

Wednesday, May 30, 1979

The Commission met, pursuant to notice, at 2:15 p.m.

BEFORE:

- DR. JOSEPH M. HENDRIE, Chairman
- VICTOR GILINSKY, Commissioner
- RICHARD T. KENNEDY, Commissioner
- PETER A. BRADFORD, Commissioner

ALSO PRESENT:

- H. Denton
- D. Eisenhut
- L. Gossick
- E. Jordan
- J. Davis
- Mr. Moseley
- Mr. Check

1                   CHAIRMAN HENDRIE: Now let's see. If the staff  
2 members will come up to the table. I invite others to come,  
3 go and stretch, or whatever suits.

4                   MR. DENTON: We have a two-part presentation planned  
5 on the abnormal occurrence at Oyster Creek on May 2nd. We  
6 talked to Commissioner Gilinsky about this several days ago.  
7 The first part will be by I&E, who will discuss those aspects  
8 related to the response of the applicant to the NRC's official  
9 notification. We'll discuss the technical evaluation of the  
10 occurrence itself, the tech spec changes we have required as  
11 a result of the occurrence and procedure changes in the  
12 operator training aspects.

13                   Based on our technical review, we conclude that it  
14 is safe to permit the licensee to resume operation.

15                   Let me turn it over to John.

16                   MR. DAVIS: Ed Jordan, who discussed this originally  
17 down here on May 3, will be our principal spokesman. It's  
18 like going to the Hill. You bring 100 copies with you.

19                   (Laughter.)

20                   MR. JORDAN: Could I have the Slide IE-2, please?

21                   (Slide.)

22                   Great.

23                   The facts of the May 2nd event were established by  
24 an inter-office team assembled at the site on May 3rd. The  
25 team consisted of 11 NRC employees, the Region 1 regional

1 director, three reactor inspectors, health physicists, a radi-  
2 ation environmental specialist, four NRR specialists and a  
3 public affairs representative.

4 The inspection consisted of reviews of the circum-  
5 stances surrounding the event, a review of the procedures  
6 used by the licensee, and interviews with the operating staff.  
7 Based on the results of this review, the inspectors concluded  
8 that the procedures did not give sufficient specific caution  
9 on recirculation loop isolation to the operators, and that the  
10 operator training had not been sufficient to ensure the  
11 proper awareness of instrument sensing locations and the  
12 potential for level difference indication between the core and  
13 the annulus regions.

14 The two major contributors to this event appear to  
15 be the failure to modify a procedure following the plant modi-  
16 fication, and the failure to follow a procedure which prohibited closure of  
17 the pump suction and discharge valves of all recirculation loops simultaneous.

18 COMMISSIONER GILINSKY: Are you going to explain that?

19 MR. JORDAN: I can. But I'll wait and follow through  
20 the sequence of events in detail for you. In fact, this is  
21 a good time to break to that.

22 CHAIRMAN HENDRIE: I'd just as soon have a laying  
23 out of the event for those--if there are any in the audience  
24 who are puzzled, I will remark that on May 2nd Oyster Creek  
25 went through a series of water level matters in the vessel.

1 And I look forward with great interest to seeing what we think  
2 happened and why this stuff sloshed around the way it did.

3 MR. DENTON: Darrell Eisenhut and Paul Check will discuss  
4 that.

5 MR. CHECK: I'm Paul Check, Reactor Safety Branch,  
6 Director of Operating Reactors. With me today are members of the  
7 branch, also the Plant Systems Branch, the DOR, as well as the  
8 DOR project manager and his chief.

9 Mr. Chairman, I had planned on introducing remarks  
10 describing the event with a little description of the plant.  
11 We could skip that, if you wish, and go right to the event.

12 CHAIRMAN HENDRIE: I think some brief comment about  
13 the plant is likely to be useful to all assembled.

14 MR. CHECK: Let me focus us in Slide 1, then, on the  
15 purpose of our portion of the presentation.

16 (Slide.)

17 Which is to describe the plant, the event at the  
18 plant, on May 2nd, discuss the safety considerations related  
19 thereto, and describe the actions taken as a result.

20 As a brief bit of background on Slide 2, we show  
21 something of the bibliography of Oyster Creek.

22 (Slide.)

23 The plant is owned and operated by Jersey Central  
24 Power & Light Company, a subsidiary of the General Public  
25 Utilities. It's located in New Jersey approximately 35 miles

1 north of Atlantic City.

2 The reactor is a General Electric BWR 2. It's one  
3 of 11 plants under review in the systematic evaluation program.  
4 The plant went into power operation in mid-'69. Currently, it  
5 is loaded with fuel manufactured by Exxon. Over the past several  
6 years, it's had an availability of about 75 percent.

7 (Slide.)

8 Although this gets a little bit ahead of the story,  
9 I want to distinguish at this point between Oyster Creek and  
10 plants like it, for which this event has implications, and the  
11 reason for doing this is, I think, going to become apparent  
12 quickly. The purpose is to allow us to proceed as efficiently  
13 as possible in taking whatever prompt regulatory actions are  
14 required.

15 Okay, on Slide 4 --

16 (Slide.)

17 -- we show a typical boiling water reactor, a GE  
18 direct cycle 1930-megawatt boiling water reactor, which  
19 Oyster Creek is. During operation, steam is produced in the  
20 reactor, flows to the steam lines. It expands to the turbine,  
21 which drives the generator.

22 Spent steam is then condensed in the main condenser,  
23 returned through the reactor feedwater system.

24 The containment you see there includes the drywell  
25 which houses the reactor, and the suppression chamber torus.

1 Steam released in the drywell is vented to the torus and  
2 condensed as the torus water.

3 Slide 5, we get a little closer now to what this  
4 reactor looks like.

5 (Slide.)

6 The steam supply system. The reactor, with five  
7 recirculation loops. Only one is shown explicitly here. It's  
8 typical, of course. There are four others. There is main  
9 steam piping and there is feedwater piping.

10 The system is also equipped with an isolation cooling  
11 system, consisting of circulation piping and condensers,  
12 designed to provide for heat removal from the reactor via  
13 natural circulation. The main steam piping is equipped with  
14 relief valves inside the drywell. It can be operated either  
15 automatically or manually to relieve excess pressure and to  
16 depressurize the system.

17 Each of the two steam lines is also equipped with an  
18 isolation valve to isolate the pressure vessel either auto-  
19 matically or manually. The feedwater piping delivers water  
20 to the annular region or downcomer of the reactor. The  
21 feedwater mixes in this annular region with recirculation  
22 water and is then routed to the core through the recirculation  
23 loops.

24 The variable speed recirculation pumps take suction  
25 from the annular region of the pressure vessel between the



1 vessel wall and the core shroud, through a normally open  
2 suction valve and discharge water through a discharge valve  
3 equipped with a two-inch bypass line, into the bottom of the  
4 pressure vessel. There are five such recirculation loops, as  
5 I said before, for Oyster Creek. And all suction, discharge  
6 and bypass valves are normally open during operation.

7 At the time of the May 2nd event, one of these  
8 recirculation loops, Loop D, was out of service awaiting  
9 replacement parts for a pump seal. Two of the recirculation  
10 loops, A and E, have ten-inch connections on the suction side  
11 of the recirculation pump, upstream of the isolation valve.  
12 These connections are the return lines from the isolation  
13 condensers.

14 There are two isolation condensers. These are  
15 connected to the reactor vessel steam region on the suction  
16 side of the recirculation loops, A and E, as I mentioned a  
17 moment ago. These isolation condensers provide a loop for  
18 natural circulation through the reactor core.

19 When operating, the system receives steam from the  
20 reactor vessel, the steam is condensed and returns as water  
21 to the recirculation loop. The system is actuated automaticall  
22 on detection of a persistent signal by either high reactor  
23 pressure or low low reactor water level. The system may  
24 also be actuated manually be the operator.

1 (Slide.)

2 As I said earlier, steam from the reactor drives the  
3 main turbine generator. It's then condensed and returned to  
4 the reactor via one-third capacity condensate pumps and three  
5 one-third capacity feed pumps. The condensate feedwater and  
6 recirculation pumps are powered normally in operation from the  
7 station and nonvital 4160 Volt buses A, 1A and 1B of electri-  
8 city, as conveniently shown in red. During normal operation,  
9 these buses receive power from the auxiliary transformer,  
10 connected directly to the generator.

11 Start-up transformers SA and SB provide power to  
12 buses 1A and 1B during plant shutdown. Condensate pump 1A,  
13 feed pump 1A, recirculation pumps A, C and E all receive power  
14 from nonvital bus 1A. Condensate pumps 1B and C, feedwater  
15 pumps 1B and C, and recirculation pumps B and D receive power  
16 from bus 1B.

17 The point here is that at the time of the May 2nd  
18 event, start-up transformer SB was out of service, as permitted  
19 by technical specifications, to perform a routine inspection  
20 of its associated 4160 Volt cabling. This point may have  
21 been the subject of some confusion at the previous briefing.  
22 I want to make the point here that that transformer was out  
23 per technical specifications, for routine surveillance. It  
24 had been out for approximately two hours before the event.

25 COMMISSIONER KENNEDY: Two hours?

1 MR. CHECK: Two hours, yes, sir. It is permitted to  
2 be out of service for seven days.

3 Also, all the feedwater pumps were in service. That  
4 was another point. It wasn't clear, at least initially, in  
5 the earlier briefing. All feedwater pumps were in service.

6 Back to Slide 5, now, Frank, I think.

7 We want to point out that in order to monitor system  
8 performance, instrumentation is provided to sense reactor  
9 water level, reactor pressure, valve position, recirculation  
10 flow rate and other system parameters. Reactor water level  
11 is monitored by three different types of level measuring  
12 devices. These instruments sense low level and low low level  
13 in the annular region of the pressure vessel, and low low low  
14 or triple low level inside the shroud above the core.

15 As I said earlier, on May 2nd all plant systems were  
16 in normal lineup, with the exception of the start-up trans-  
17 former SB and the recirculation loop D. Start-up transformer  
18 was removed from service for maintenance. Recirculation pump D  
19 had been removed about two months earlier from the system, due  
20 to a seal leak.

21 The discharge valve was closed, the suction valve  
22 open, the discharge bypass valve open, and a plate was  
23 discharged over the opening in the pump housing, so there was  
24 continuity in the loop.

25 Okay. Now, getting to the event. In your handouts

1 you have a figure which is perhaps unnumbered. Let's show  
2 the figure that shows the sequence. Slide 7, it is. And  
3 that's what you're looking for.

4 (Slide.)

5 We can't keep it up there all the time, but it  
6 would be handy to refer to. We're going to show you the reactor  
7 and what's going on.

8 We'll go back to 5, Frank, and state that at the  
9 time of the event, which was 1:51 p.m., the reactor was at  
10 98 percent power.

11 COMMISSIONER KENNEDY: 1:51?

12 MR. CHECK: The afternoon of the 2nd of May. The  
13 reactor was at 98 percent power and the water level was at  
14 13 feet, 4 inches, above the core. Feedwater flow and recir-  
15 culation flow are normal.

16 What I'm going to present now is a summary of the  
17 important elements of the transient. One thing -- the  
18 initiating event. While conducting routine tests in the  
19 isolation condenser actuation system, an instrument technician  
20 caused the hydraulic disturbance in the instrument line that  
21 was sensed by the reactor protection system as a high reactor  
22 pressure condition.

23 The reactor protection system scrammed the reactor  
24 and tripped the recirculation pumps. This reactor recircula-  
25 tion pump trip, it is interesting to note, is what we call an

1 ATWS pump trip. It is something that was installed in the  
2 fall of last year, more or less at our urging, as a product  
3 of our ATWS review.

4 Okay. Immediately then, the reactor water level  
5 began decreasing due to collapse of steam bubbles in the core.  
6 What Frank is going to show here is -- it should be in two  
7 colors, but it isn't. It would be too apparent. We're going  
8 to try to show the level within the shroud area that is  
9 directly above the core and that in the annulus.

10 Okay. Immediately the reactor water level began  
11 decreasing due to collapse of steam bubbles in the core, also  
12 the continuing flow of feedwater. But the feedwater pumps  
13 were on. The continued flow of feedwater to the annulus  
14 cooled and shrunk the water in the downcomer, this annulus  
15 region.

16 At 13 seconds, the turbine generator trips. Auto-  
17 matic transfer of loads -- Frank, perhaps if we went back to  
18 6 for a minute, it would be useful to look at this diagram  
19 again.

20 Automatic transfer of loads from the auxiliary  
21 transformer to the start-up transformers was successful for  
22 start-up transformer SA, but failed, of course, for SB, because  
23 it was out of service. This left feed and condensate pumps  
24 1B and 1C without power, and they tripped temporarily.

25 Condensate pump 1A alone could not meet the suction

1 pressure requirements of feedwater pump 1A. So feedwater pump  
2 tripped. This is a known characteristic of the feedwater  
3 system.

4 We now have a loss of feedwater transient.

5 Perhaps we can go back to 5.

6 The operator at this point makes an unsuccessful  
7 attempt to restart feedwater pump 1A. This was due, we  
8 learned later, to a lack of a permissive signal from the  
9 lubrication system. Oil pumps provide lubrication to feedwater  
10 pumps. There was a lack of a permissive signal which indi-  
11 cated that the feedwater pump was being adequately lubricated.  
12 So he couldn't start up the feedwater pump.

13 At this point --

14 COMMISSIONER BRADFORD: What is the line below the  
15 water level?

16 MR. CHECK: That's a mistake. This is an artist's  
17 conception of Oyster Creek.

18 COMMISSIONER BRADFORD: Yeah, you know them artists.

19 MR. CHECK: We didn't QA the slides sufficiently.

20 COMMISSIONER KENNEDY: You say there was not a  
21 signal? This is just a failure of signal or an actual  
22 failure?

23 MR. CHECK: I don't want to get into too much  
24 detail. We can if you wish. But functionally, a signal or  
25 a condition which would allow the feedwater pump to start up

1 didn't exist.

2 COMMISSIONER KENNEDY: Was that because of a failure?

3 MR. CHECK: A breaker failed to close or open.

4 COMMISSIONER KENNEDY: It's not the question of the  
5 whole loop?

6 MR. CHECK: No. It's a minor electromechanical  
7 problem.

e-8

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

1           Okay. We're still at 13 seconds, and counting.

2           At about this time, then, the water level decreases  
3 to the low-level SCRAM set point. Had the plant not SCRAM'd now,  
4 it would upon reaching the 11'5" set point above the core.

5           At 43 seconds, when the water level was 8'8" above  
6 the core, the operator initiated the closure of the main steam  
7 isolation valve to conserve inventory.

8           I will try to back up a little bit in the talk.

9           Inventory is, of course, important here. The feed-  
10 water pumps were on until about 30 seconds ago; that is, until  
11 the turbine generator tripped. So supply was continuing to the  
12 reactor. That's fine. At the same time, of course, the steam  
13 lines were open, and water in the form of steam was leaving the  
14 vessel, but this was balanced. Feedwater pumps had tripped at  
15 13 seconds; and now 30 seconds later, because the operator knows  
16 he wants to conserve inventory, he isolates the reactor by clos-  
17 ing the main steam isolation valves, so now he has a closed  
18 system and one of constant inventory.

19           This action would have happened automatically 30-odd  
20 seconds later, we calculate, on the basis of a knowledge of  
21 how rapidly the water level was running in the annulus. When the  
22 water level reaches a low-low set point -- 7'2" above the core  
23 -- a signal is generated to isolate the reactor, close the main  
24 steam isolation valves.

25           That, of course, did not happen here, because the



1 operator interrupted -- properly -- the sequence of events.

2 At a minute and a quarter into the event, the opera-  
3 tor put an isolation condenser into service and began a con-  
4 trolled cooldown program of intermittent isolation condenser  
5 operation. This was carried out over the next half-hour.

6 Now, here is an important point: The procedures  
7 governing isolation condenser operation instruct the operator to  
8 close the discharge valves on recirculation loops A and E, the  
9 two loops to which the isolation condensers are connected. This  
10 is to protect against an excessive flow condition in the con-  
11 denser piping that would actuate the break-sensing automatic  
12 isolation provisions of the isolation condenser. High-flow con-  
13 ditions in the isolation condenser are sensed automatically as  
14 a break in that system, and automatically then the reactor takes  
15 steps to isolate itself to isolate the break.

16 This system, this break-sensing system, was especially  
17 sensitive during the time when recirculation pumps continued to  
18 run. They pulled water down from the isolation condensers. But  
19 as I mentioned earlier, these recirc pumps were tripped on the  
20 event or shortly thereafter because of the ATWS pump trip.

21 Here, perhaps, is where a procedure hasn't caught up  
22 with the actual modification of the plant. At this same time,  
23 the operator apparently closed the discharge valves in recircu-  
24 lation loops B and C, as well, most probably in preparation for  
25 restarting those pumps. Closing the discharge valves is required

1 by procedure for restarting pumps.

2           So, he's got two procedures together: One of them  
3 was perhaps out of date. The other one, he maybe shouldn't have  
4 been looking at quite so quickly.

5           But at any rate, he prepared to start the recirc pumps  
6 by closing the discharge valves, but he didn't carry through on  
7 the action.

8           In a minute and a half, then, we have not an isolation  
9 condition, but certainly a choked-flow condition. It's not true  
10 of isolation. A choked-flow condition between the annulus and  
11 the core, the only path being through the bypass lines around  
12 each of the discharge valves and each of the five loops.

13           In a minute and a half after the event --

14           COMMISSIONER KENNEDY: Five loops or four loops?

15           MR. CHECK: Five. There are five, although one was  
16 out of service. It has the same bypass capacity.

17           COMMISSIONER KENNEDY: The bypass was open? Okay.

18           MR. CHECK: Yes.

19           At a minute and a half, then, the low-level alarm  
20 cleared as water was added to the annulus from the isolation  
21 condenser. The inventory in isolation condenser just sort of  
22 whooshed in, and the level, at about three minutes into the  
23 event, the low-low-low or triple-low condition inside the shroud  
24 was alarmed. This corresponds to 5'6" above the core.

The operator continued controlling reactor cooldown

1 with an isolation condenser flow.

2 We now skip to about a half-hour after the SCRAM, but  
3 observe that it was during this period -- that is, from three --  
4 actually, from seven minutes to 32 minutes -- that the minimum  
5 water level has been calculated to occur. The minimum calculated  
6 levels ranged from one foot to 3-1/2 feet above the core; under  
7 the alarm point, but above the core.

8 MR. EISENHUT: Somewhere in that hatched area.

9 MR. CHECK: Right.

10 MR. EISENHUT: Depending on different assumptions in  
11 the calculations.

12 MR. CHECK: We'll talk about the calculations in a  
13 little bit.

14 At 32 minutes, then, the operator restarted recircula-  
15 tion pump C, but upon learning that the water level in the annu-  
16 lus had dropped three feet in less than two minutes, he shut down  
17 the pump and isolated it to investigate it.

18 At this time, the low-low-low level alarm apparently  
19 cleared. At 39 minutes, the operator placed recirculation pump  
20 A in service. This removed the disparity in water level between  
21 the annulus and the core, the resultant level being 11'4" above  
22 the core. It equilibrated at that point.

23 At one hour, the startup transformer that had been  
24 out of service for the surveillance was returned to service. And  
25 in nine hours, the reactor reached a cold shutdown -- eight or

1 nine, in that area.

2           Okay, now, we get to our safety review.

3           As we undertook to review the May 2 event, it was our  
4 purpose first to establish that the plant was in a safe, stable  
5 condition; second, to determine what, if any, prompt regulator  
6 actions were required for other plants; third, to assess syste-  
7 matically the condition of the reactor and its readiness to start  
8 up again.

9           To get firsthand information regarding the event, the  
10 condition of the plant, we sent a factfinding team to the site  
11 that worked with the I&E team already there. On the basis of  
12 their telephone report back to us on the afternoon of the 3rd,  
13 we were able to confirm our earlier reports from the licensee,  
14 and I&E, that the plant was in a safe, stable condition.

15           We were also able to make a preliminary finding that  
16 the principal factor contributing to the severity of the event  
17 was the interruption of the good hydraulic communication between  
18 the annulus and the core region of the reactor. With this lat-  
19 ter information, we knew we could confine our immediate attention  
20 for other reactors to non-jet pump BWRs, because on a jet pump  
21 plant there is no way to isolate the core from the annulus. As  
22 luck would have it, on May 3 no non-jet pump BWRs were operating.

23           So, with Oyster Creek determined safe and no prompt  
24 regulatory action apparently needed for other plants, we con-  
25 tinued with our systematic review. Before permitting Oyster

1 Creek to start up, we needed to find that the core was  
2 damaged, that the event would not reoccur. Also, we had to  
3 examine whether any other actions needed to be taken -- for example,  
4 by Inspection and Enforcement -- to the condition of the core  
5 question, to determine that the core was undamaged.

6 Calculations of minimum water level were performed  
7 by Exxon, General Electric on behalf of the licensee, and by us.  
8 Throughout the event, the rate at which the water-steam mixture  
9 in the reactor could accept heat exceeded the rate at which heat  
10 was transferred from the fuel to the water. Thus, it would be  
11 sufficient to show that the core remained covered.

12 All calculations indicated that the core did not  
13 uncover.

14 To support the conclusion of no core damage, the  
15 licensee and we examined plant records for radiological evidence  
16 of core uncover.

17 (Commissioner Bradford leaves the room at 2:48.)

18 MR. CHECK: We found that the reactor coolant sample  
19 analyses from before and several days after the event showed no  
20 unusual increases in concentrations of radionuclides.

21 Also, the continuously recorded signals from the plant  
22 stack and the steam air ejector monitors showed no unusual  
23 increases of airborne radioactivity.

24 We have concluded from all of this that the core was  
25 not damaged.

1 Safety analyses of a spectrum of postulated transients  
2 and analyses are performed for each plant. The response of the  
3 plant is shown generally by calculation to be acceptable; that  
4 is, to meet specified acceptance criteria. These acceptance  
5 criteria, or simulations of postulated events, take explicit  
6 credit for certain equipment and design features in the plant;  
7 where this is done, and to assure that things will go as analyzed,  
8 technical specifications are established to assure the availa-  
9 bility and correct operation of the essential equipment.

10 But, again, on May 2, the loss-of-feedwater transient  
11 did not proceed as expected, because essential equipment was not  
12 operated as assumed; specifically, the discharge valves and the  
13 recirculation loops were closed.

14 The licensee has now performed and we have reviewed  
15 a suitably bounding analysis for events of this type. Further,  
16 the licensee has proposed, and we have accepted, technical speci-  
17 fication changes which will assure that the plant matches the  
18 assumptions of the safety analysis. Specifically, these tech spec  
19 changes require that the suction and discharge valves on each of  
20 two recirculation loops remain open to guarantee easy hydraulic  
21 communication between the annulus and the core. Also, the low-  
22 low water level signal that has been assumed in the analysis to  
23 actuate the isolation condensers would be added as a limiting  
24 safety system setting.

1 any ambiguity, the low-low-low water level has been established  
2 as a safety limit for all modes of reactor operation.

3 With these technical specification changes, we have  
4 completed our technical review of the May 2 event at Oyster Creek  
5 and are reasonably assured that it won't reoccur.

6 In connection with one other thing, I&E has been look-  
7 ing at certain things. One thing that remains before recommend-  
8 ing that the Oyster Creek plant be permitted to resume operation  
9 is a finding by I&E that the licensee has attended to those  
10 matters within the scope of that office -- for example, that  
11 needed procedure revisions and indicated operator training have  
12 been satisfactorily accomplished. And I look --

13 COMMISSIONER GILINSKY: Could you just return to the  
14 point about the procedures being out of date? I didn't fully  
15 understand that.

16 MR. JORDAN: I will pick up on that in just a moment.

17 An inspection of the licensee's corrective actions  
18 was conducted on May 7 through 11, and on May 14, in conjunction  
19 with the detailed inspection of Bulletin 7908. As you recall,  
20 Bulletin 7908 was a bulletin sent to all boiling water reactors  
21 based on the Three Mile Island accident, for them to take actions  
22 in response to the problems that were found at Three Mile Island.

23 The procedure changes were initiated by the licensee  
24 to assure that at least two recirculation loops discharge valves  
25 are open at all times.

1 (Commissioner Bradford returned to the room at 2:52.)

2 MR. JORDAN: Training sessions had been verified and  
3 conducted by the licensee on the May 2 event. The training pro-  
4 gram was revised to include in-depth review and procedure  
5 changes to include conditions which may arise from multiple or  
6 coincidental failures. The inspectors verified that a startup  
7 program has been developed in compliance with the conditions of  
8 the safety analysis review.

9 Could I have slide IE-4, please.

10 (Slide.)

11 The inspections of the licensee's action in response  
12 to Bulletin 7908 included review of operator training, which was  
13 a discussion with two operators per shift. During those dis-  
14 cussions, the discussions with regard to the May 2 event at this  
15 facility were also discussed.

16 The inspector verified the operability of 10 engineere  
17 safety feature systems. This is making a hand-over-hand walkdown  
18 of each of the systems, reviewing the valve lineups physically  
19 against the PNIDs, and verifying that the licensee's lineup  
20 procedure was correct.

21 Through that review, only one instance was identified  
22 in which there was a deficiency. This was a case in which three  
23 valves, which were identified as being locked in an open posi-  
24 tion, were in the correct position but they were not locked.

25 And so noncompliance consideration is being given with regard to



1 that item.

2 All of the safety systems were verified to be properly  
3 aligned both electrically and mechanically for automatic actua-  
4 tion.

5 The procedure changes with respect to both Three Mile  
6 Island-type event and this May 2 event at Oyster Creek were  
7 found to have been implemented.

8 The licensee has established two dedicated phone lines  
9 for NRC use and has promulgated a memo to operating personnel  
10 concerning prompt notification of events.

11 The inspector also identified instances in which the  
12 small instrument valves were not identified or were not shown on the  
13 piping instrumentation drawings. The licensee is committed to  
14 correct this problem in a timely fashion.

15 Now, so far as the procedures, your question is: How  
16 did this procedure omission occur; specifically, what it was.

17 There were two procedures that were involved. One  
18 procedure was a standing order which required tripping of A&E  
19 recirc pumps and opening the two-inch bypass valves, closing the  
20 discharge valves. This particular procedure should have been  
21 changed when a modification was made in August of '78 which  
22 caused the pumps to trip when there was a reactor trip. This is  
23 the ATWS modification. That modification was not done to the  
24 procedures.

1 made." Is this something they should have figured out, something  
2 that we asked them to do and they did not do?

3 MR. JORDAN: No. Anytime a modification is performed,  
4 the licensee is obligated to review his procedures to see how the  
5 modification affects his procedures and then train his personnel  
6 so they can respond to that physical plant change.

7 COMMISSIONER BRADFORD: Now, with all the bulletins  
8 that have come out after Three Mile Island, the B&W plants, will  
9 they have gone through that cycle as well and reviewed all of  
10 their procedures to be sure that they're consistent with the  
11 bulletins?

12 MR. JORDAN: The procedure review, they are being  
13 requested to do according to the bulletin does not specifically  
14 address design changes. That's another little nuance. If that  
15 answers your question.

16 COMMISSIONER BRADFORD: It would help if you would  
17 start by saying "Yes" or "No" at the beginning of that paragraph.

18 MR. MOSELEY: Excuse me. I think the answer to your  
19 question is: They are already required to do this. This is a  
20 part of the administrative controls in the QA program. This was  
21 just a glitch, in this particular case, that happened at Oyster  
22 Creek. So there was no new requirement. I believe that answers  
23 your question.

24 COMMISSIONER BRADFORD: But do we know, for example,  
25 that we have now required that a reactor trip instantly upon a

1 turbine trip? Are there any reviews of procedures?

2 MR. JORDAN: Those modifications that have been  
3 required by the bulletin and by the order are being reviewed  
4 specifically by the inspectors at the site, and they're being  
5 verified as those changes have been incorporated in the pro-  
6 cedures.

7 COMMISSIONER BRADFORD: I am sorry. Not just now,  
8 but are there also operating procedures -- in this case, appar-  
9 ently -- that effectively would improve the system, but didn't  
10 give the operator the right procedures to cope with the improved  
11 system? They've now improved the system in the B&W plants as  
12 well; does the operator have the corresponding procedures?

13 MR. JORDAN: Yes, sir.

14 MR. DENTON: In the B&W plants, part of our review  
15 was procedures that implemented the new design changes. So we  
16 would say "Yes" for the B&W changes.

17 MR. JORDAN: And for the changes with respect to the  
18 bulletin. That's with respect to the order. With respect to the  
19 bulletin, those are being reviewed by inspection procedures for  
20 each of the Westinghouse and GE plants where there are procedure  
21 changes or modifications of the facility as a result of that  
22 bulletin.

23

24

78.10.1

mgs

1 We do have that assurance. Were there further questions about  
2 the procedures?

3 COMMISSIONER GILINSKY: No.

4 CHAIRMAN HENDRIE: Please go ahead.

5 MR. JORDAN: Could I have slide five, please?

6 (Slide.)

7 In general the notifications by the licensee and  
8 within NRC did not proceed as rapidly as desired. Based on the  
9 potential seriousness of this event, offsetting this statement,  
10 it should be noted that at the time the NRC was notified that  
11 the reactor was in a safe shutdown condition with no  
12 abnormalities in plant parameters or radioactivity levels, the  
13 licensee was committed to remain in shutdown until the event  
14 was thoroughly reviewed.

15 COMMISSIONER GILINSKY: Now what is it that  
16 triggered the notification to the NRC?

17 MR. JORDAN: On the part of the licensee?

18 COMMISSIONER GILINSKY: Yes.

19 MR. JORDAN: His concern that he may have exceeded  
20 the safety limit.

21 COMMISSIONER GILINSKY: The triple low signal?

22 MR. JORDAN: Yes, and that procedure had been  
23 modified as a result of the I & E Bulletin 79-08 that he had  
24 placed in it. If the safety limit is exceeded you would notify  
25 the NRC within this one hour period. This notification was

311 063

78.10.2

1 done an hour and half after the onset of the event.

2 COMMISSIONER GILINSKY: And when would you expect  
3 them to notify you?

4 MR. JORDAN: Within an hour of the event. Within  
5 three minutes, we received the triple low level, so we're  
6 talking about 30 minutes of delay, if you will.

7 The subsequent notification was discussions by  
8 Region One inspectors and a section chief within our armed  
9 personnel. These were licensing projects people, and with  
10 the information they had, the concerns they had for this  
11 particular event were elevated. And I say that with the  
12 information we had, we feel that the internal notification was  
13 hampered by incomplete information. An inspector, based on  
14 this raising of our interest in this matter, an inspector was  
15 dispatched to the site that night from another site.

16 COMMISSIONER KENNEDY: In what respect was it  
17 incomplete?

18 MR. JORDAN: We had the information that there may  
19 have been the triple low level received, and we didn't have  
20 the full description of the plant parameters. So there was  
21 some question -- in fact there was some question on our part  
22 the following morning as to whether that had or had not been  
23 the triple low level received.

24 So there was a question of whether its  
25 instrumentation or whether it was -- a physical inspector was

311 064

78.10.3

mgc

1 on site at 3:30 a.m. to review the incident. He established to  
2 his satisfaction that the plant was in a safe shutdown  
3 condition at that point.

4 COMMISSIONER KENNEDY: What time was he directed to  
5 go?

6 MR. JORDAN: He was directed about 1:00 a.m., I  
7 believe. He was at another site, Salem.

8 MR. MOSELEY: He was at another site.

9 (At 3:05 p.m., Commissioner Bradford left the room.)

10 COMMISSIONER GILINSKY: I'm not sure I understand  
11 what you mean by NRC internal notification hampered. By  
12 incomplete information.

13 MR. JORDAN: Okay. The notification process is  
14 based on the severity of the incident.

15 COMMISSIONER GILINSKY: I see. Not having full  
16 information, the severity --

17 MR. JORDAN: It was not clear.

18 COMMISSIONER GILINSKY: Have we got that cleared up?

19 MR. JORDAN: Yes, we have. May I have the next  
20 slide, please?

21 (Slide.)

22 COMMISSIONER KENNEDY: How do you clear that up?  
23 That's a function of the information we have available.

24 MR. JORDAN: We've taken measures to help clear that  
25 up.

311 065

78.10.4

1 MR. MOSELEY: We also think, Commissioner, that  
2 maybe we didn't ask enough questions at the initial time.

3 MR. JORDAN: Okay. The actions that we've taken  
4 to try to clear that up include first of all emphasizing to all  
5 utilities — this was through a telephone call from the  
6 regional director to the top executive in that particular  
7 utility — emphasizing the importance of prompt reporting.

8 The second item was reviewing with each of the  
9 operating reactor branch chiefs in the regions their  
10 responsibilities and the importance once again of prompt  
11 reporting, and their passing forward and obtaining complete  
12 information.

13 Thirdly, we are developing — revising, I'll say —  
14 our internal instructions to emphasize promptness in internal  
15 reporting. We're also in the process of developing more  
16 definitive criteria for issuance of binding requirements to  
17 licensees, through either regulations or technical  
18 specifications or Regulatory Guide 1.16 -- the mechanism,  
19 estimate, and criteria are being developed.

20 We have verified that Oyster Creek has modified their  
21 reporting procedures since the event, so that they would now  
22 be more conservative in their reporting.

23 COMMISSIONER GILINSKY: I assume that when you give  
24 them an hour, you also expect them to notify the NRC as soon as  
25 possible, before an hour is up.

311 066

78.10.5

mqc

1 MR. JORDAN: We're not asking them to say, "At one  
2 hour, call us."

3 COMMISSIONER KENNEDY: The words are "within."

4 MR. JORDAN: Yes.

5 COMMISSIONER KENNEDY: That's just giving them  
6 enough flexibility so they can take care of the incident.

7 COMMISSIONER GILINSKY: Right. If they can do it  
8 earlier -- I would expect them to do it earlier.

9 MR. JORDAN: And one of the mechanisms to do it  
10 earlier is the installation of dedicated telephone lines at  
11 each of these facilities. The next presentation will discuss  
12 that area.

13 May I have the next slide, please?

14 (Slide.)

15 COMMISSIONER KENNEDY: Let me just note that given the  
16 experience of Three Mile Island, which was recently fresh in  
17 everyone's mind, and particularly in this region, Region One,  
18 I have to say I find it extraordinary that we have to  
19 reemphasize to the I & E reactor branch chiefs the necessity  
20 of prompt notification and of getting better information.

21 MR. MOSELEY: But we don't want to make excuses for  
22 this.

23 COMMISSIONER KENNEDY: I'm not asking. I'm just commenting

24 MR. MOSELEY: It was a function of the people who  
25 were available at that time, the people who were handling these

311 067



78.10.6

1 things, were not normally assigned to operating reactors. All  
2 the operating inspectors were out inspecting, and so these  
3 were people who were filling in for others, and they, perhaps,  
4 were not as well in tune as we would have liked them to have  
5 been.

6 COMMISSIONER KENNEDY: Okay.

7 MR. JORDAN: Okay. The last item is the fact that  
8 information on this event has been disseminated to all  
9 licensees. There will be an I & E Information Notice 79-13,  
10 a copy of which has been provided to you.

11 Discussions -- and I might add as a last thing to  
12 this -- discussions of this particular event with the Nine  
13 Mile Point licensee have identified a similar procedural  
14 weakness regarding control of the recirculation process, so  
15 that there is obvious value in disseminating the information  
16 and discussing it quickly with the licensee.

17 Would you like to make a summary statement?

18 MR. MOSELEY: I'll make the summary I & E statement.  
19 It is our assessment based upon the reviews of Region One and  
20 the I & E headquarters staff that the licensee has accomplished  
21 the needed actions and has demonstrated that he's capable of  
22 operating this facility within the conditions of his license  
23 with due regard to the safety implications of both the low  
24 water level event at Oyster Creek and the recent Three Mile  
25 Island event.

311 068

8.10.7

mgc

1                   So, we see no reason why they should not go back  
2 into operation.

3                   MR. EISENHUT: Along that same line I should probably  
4 point out that this same general kind of approach requiring a  
5 safety limit on keeping the loops open and the triple low  
6 being the safety limit, it's our intent that for the other  
7 similar plants that are shut down right now, we are going to  
8 require the same kind of changes in the other three or four  
9 affected plants before they are going to be allowed to return  
10 to power also. This goes across the rest of the affected  
11 plants.

12                   Then, to conclude, we propose to let the plant resume  
13 operation.

14                   CHAIRMAN HENDRIE: Okay. Everything from your  
15 standpoint, I & E has signed off on everything, and from your  
16 standpoint is in place?

17                   MR. DENTON: Ours is in place. I don't know if there  
18 are any loose items or other matters that I & E considers.

19                   MR. MOSELEY: We have no outstanding items. We have  
20 some things that need follow up.

21                   CHAIRMAN HENDRIE: That sounds reasonable.

22                   Thank you. Good.

23                   (Whereupon, at 3:10 p.m., Wednesday, May 30, 1979,  
24 the meeting was adjourned.)

25

311 069

STAFF EVALUATION OF MAY 2, 1979  
EVENT AT OYSTER CREEK NUCLEAR  
GENERATING STATION

PURPOSE

DESCRIBE EVENT

DISCUSS SAFETY CONSIDERATIONS

ACTIONS

OYSTER CREEK NUCLEAR GENERATING STATION

GENERAL ELECTRIC PWR/2

LICENSED 1969

IN SEP

EXXON FUEL

311 071


DIRECTLY AFFECTED

OYSTER CREEK  
NINE MILE POINT  
LACROSSE  
DRESDEN 1  
BIG ROCK POINT

NOT DIRECTLY AFFECTED

ALL OTHER  
OPERATING  
BWRs


# BOILING-WATER REACTOR POWER PLANT



311 073

**POOR ORIGINAL**

OUTSIDE DRYWELL | INSIDE DRYWELL




OYSTER CREEK RECIRCULATION, STEAM AND ISOLATION CONDENSER SCHEMATIC

POOR ORIENTATION

311 074

# Feedwater & Electrical Supply Systems



**POOR ORIGINAL**



## SEQUENCE OF EVENTS

0	REACTOR SCRAM, RECIRC PUMPS TRIP
13 SEC	TURBINE GENERATOR TRIPS, FEEDWATER SYSTEM TRIPS, LOW LEVEL SIGNAL
43 SEC	CLOSE MSIVS
49 SEC	REACTOR ISOLATED
1 1/4 MIN	CLOSE "A" AND "E" LOOP VALVES, PROBABLY "B" AND "C", COMMENCE INTERMITTENT ISOLATION CONDENSER OPERATION
1 1/2 MIN	LOW-LEVEL CLEARS
3 MIN	LOW-LOW-LOW SIGNAL
32 MIN	RESTART "A" RECIRC PUMP, LEVEL DROPS, SECURE PUMP, LOW-LOW-LOW CLEARS
39 MIN	PLACE "A" RECIRC PUMP IN SERVICE, LEVELS IN CORE AND ANNULUS EQUILIBRATE
1 HR	SB TRANSFORMER RETURNED TO SERVICE
8 HR	COLD SHUTDOWN

**POOR ORIGINAL**

311 076

CONCLUSION

CORE UNDAMAGED

RECURRENCE UNLIKELY

- TECH SPEC CHANGES
- PROCEDURE REVISIONS
- OPERATOR TRAINING

RESUME POWER OPERATION

CONCLUSION

CORE UNDAMAGED

RECURRENCE UNLIKELY

- TECH SPEC CHANGES
- PROCEDURE REVISIONS
- OPERATOR TRAINING

RESUME POWER OPERATION

311 078

NRC ACTIONS SUBSEQUENT TO OYSTER CREEK EVENT OF  
MAY 2, 1979

- COMPLETE INSPECTION OF EVENT
- PERFORM SAFETY EVALUATION
- INSPECT LICENSEE CORRECTIVE ACTIONS
- REVIEW NOTIFICATION PRACTICES
- DISSEMINATE INFORMATION TO ALL LICENSEES

311 079

INSPECTION OF EVENT MAY 3-4, 1979

● NRC TEAM:

REGIONAL DIRECTOR  
REACTOR INSPECTORS (3)  
HEALTH PHYSICIST  
ENVIRONMENTAL  
NRR (4)  
PUBLIC AFFAIRS

- ESTABLISHED FACTS OF EVENT BY REVIEW  
OF LOGS AND RECORDS AND INTERVIEWS  
WITH PERSONNEL

INSPECTION OF LICENSEE CORRECTIVE ACTIONS  
MAY 7-11, 14, 1979

- REVISE PROCEDURES
- TRAINING SESSIONS ON MAY 2 EVENT AND  
PROCEDURE REVISIONS
- STARTUP PROGRAM DEVELOPED
  - CRD INTERFERENCE CHECKS
  - CRD SCRAM TEST 25%
  - REACTOR COOLANT ANALYSIS
  - OFFGAS ANALYSIS
  - ACTION LEVELS FOR RADIOACTIVITY

INSPECTION OF IE BULLETIN 79-08

- OPERATOR TRAINING
- OPERABILITY OF ENGINEERED SAFETY FEATURES
- ASSESSMENT OF OPERATING PROCEDURES
- EVALUATION OF LICENSEE RESPONSE

NOTIFICATIONS

- EVENT INITIATED 1:50 PM, 5/2/79
- LICENSEE NOTIFICATION AT 3:20 PM  
DID NOT MEET INTENT OF IEB 79-08
- REGION I DISCUSSIONS WITH NRR ELEVATED  
CONCERNS
- NRC INTERNAL NOTIFICATION HAMPERED BY  
INCOMPLETE INFORMATION
- INSPECTOR ON SITE BY 3:30 AM, 5/3/79
- NRC TEAM ON SITE BY 3:00 PM, 5/3/79



#### ACTIONS ON NOTIFICATION

- IMPORTANCE OF PROMPT REPORTING EMPHASIZED TO ALL UTILITIES
- RESPONSIBILITIES OF REPORTING EMPHASIZED TO ALL IE OPERATING REACTOR BRANCH CHIEFS, 5/4/79
- INSTRUCTION BEING REVISED TO EMPHASIZE PROMPTNESS IN INTERNAL REPORTING
- DEFINITIVE CRITERIA BEING DEVELOPED FOR ISSUANCE AS BINDING REQUIREMENTS TO LICENSEES
- OYSTER CREEK MODIFIED REPORTING PROCEDURES
- STEPS UNDERWAY TO INSTALL DEDICATED TELEPHONE CONNECTIONS

DISSEMINATE INFORMATION TO ALL LICENSEES

- INFORMATION NOTICE ISSUED 5/29/79  
PROVIDES DETAILS OF THE OCCURRENCE  
FOR INFORMATION PURPOSES DISPATCHED  
TO ALL HOLDERS OF OPERATING LICENSES  
AND CONSTRUCTION PERMITS. NO SPECIFIC  
ACTION OR RESPONSE IS REQUIRED.