LICENSEE EVENT REPORT
CON HOL BLOCK: [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 1 1 2 1 5 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
CON'T O 1 SOURCE GO G1 DOCKET NUMBER GR GO EVENT DATE 74 75 HEPCHT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 19 O 2 During normal operation the fan belt for the blower for 1RT-PRO7 (pipe
[0]3 tunnel rad monitor) failed. The monitor was taken OOS. Grab samples
0 4 were not necessary because the monitor was repaired within one shift.
There were no safety implications and the health and safety of the
general public were not affected.
0 7
0 8 1
SYSTEM CAUSE CAUSE SUBCODE SUB
LER'RO EVENT YEAR REPORT NO. 17 REPORT 7 9 0 0 4 7 0 0 3 L L 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
The fan belt had broken due to normal wear. The fan belt was replaced
[1] [(Durkee-Atwood No. 390). The monitor was functionally tested and
returned to service. No further corrective action is necessary.
1 3
1 4 L
FACILITY STATUS SPOWER OTHER STATUS OF DISCOVERY DESCRIPTION (32) 1 5 E 28 1 0, 0 29 NA B 31 Operator Observation
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 I G Z 33 Z 34 NA PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA 44 45 46 NA LOCATION OF RELEASE 38 NA 80 80
1 7 0 0 0 Z 38 NA 7 8 9 PERSONNEL INJUHIES NUMBER DESCRIPTION (1) 1 8 0 0 0 (40) NA
LOSS OF OH DAMAGE TO FACILITY (43) TYPE DESCRIPTION 1 0 Z (12) NA
7 8 9 PUBLICITY 10 NRC USE ONLY 10 NRC USE O
746-2084 #2384