

DUKE POWER COMPANY USNRC REGION II
ATLANTA, GEORGIA

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

79 JUN 4 9:38

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

May 30, 1979

TELEPHONE AREA 704
373-4083


Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30302

Re: RII:JPO
50-269
50-270
50-287

Dear Mr. O'Reilly:

With regard to your letter of March 30, 1979 and my letter of May 2, 1979, please find attached Duke Power Company's response to IE Bulletin 79-04 for Oconee Nuclear Station.

Very truly yours,


William O. Parker, Jr.

RLG:scs
Attachment

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Construction Inspection
Washington, D. C. 20555

495 325

7907180 883

790295
OFFICIAL COPY

DUKE POWER COMPANY
OCONEE NUCLEAR STATION
Response to IE Bulletin 79-04

Duke Power Company has reviewed all Seismic Category I piping systems and has determined that 1500 psi Velan check valves were installed in the 3-inch discharge line of each high pressure injection (HPI) pump of each Oconee unit. An incorrect valve weight was used in the piping analysis of these lines.

A reanalysis of the affected HPI piping has been initiated to determine if additional supports or restraints are required. The computer code SUPERPIPE is being utilized in this analysis.

A report will be submitted upon completion of this analysis, which is expected to be completed by June 29, 1979.