

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

						1
						6

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	C	T	M	N	S	2	?	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4	L	5
7	6	9	LICENSEE CODE	14	15													25	26	LICENSE TYPE	20	57	CAT	58		

CONT'

0 1	REPORT SOURCE	L	6	0	5	0	0	3	3	6	7	0	6	1	9	7	9	8	0	7	1	8	7	9	9
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

- [0 2] Surveillance testing during reactor startup revealed the CEA Motion Inhibit (CMI) [0 3] interlock did not function properly. Investigations revealed that the CMI for group [0 4] deviation did not occur at the proper setpoints per Technical Specification 4.1.3.1.3. [0 5] The setpoints were checked and adjusted for all groups and the CMI was restored to [0 6] proper operation. Total time out of service was 1.1 hours.

[0 7]

[0 8]

7	6	9	SYSTEM CODE	J	F	11	CAUSE CODE	E	12	CAUSE SUBCODE	G	13	COMPONENT CODE	I	N	S	T	R	U	14	COMP. SUBCODE	P	15	VALVE SUBCODE	Z	16
0	9	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
7	8	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45
0	9	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45
9	10	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45
8	9	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45
7	8	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45
6	7	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45
5	6	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45
4	5	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45
3	4	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45
2	3	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45
1	2	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45
0	1	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

- [1 0] The out of sequence scanner power supply (Metra Instruments part no. 70235-01) [1 1] voltage drifted causing the group deviation setpoint voltages to shift. Readjustment [1 2] of the setpoint potentiometers returned the group deviation alarms and the resulting [1 3] CMI to proper operation.

[1 4]

2	8	9	FACILITY STATUS	C	28	% POWER	0	0	0	29	OTHER STATUS	NA	30	METHOD OF DISCOVERY	B	31	DISCOVERY DESCRIPTION	32
7	8	9	10	11	12	13	44	45	46					33	Surveillance Test	34		

7	8	9	10	11	12	13	44	45	46					35	LOCATION OF RELEASE	36	
1	6	7	8	9	10	11	12	13	14	15	16	17	18	19	NA	20	

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

POOR ORIGINAL

466 277

7907260592

NRC USE ONLY

277  
466