

LICENSEE EVENT REPORT

CONTROL BLOCK: ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	A L J M F 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5	LICENSEE CODE	14	15	LICENSE NUMBER	25	26	LICENSE TYPE	30	31	CAT 53
0 1	REPORT TO RICE	L 6 0 5 0 0 0 3 4 8 7 0 1 6 2 7 7 9 8 0 7 2 6 7 9 9	DOLAKET NUMBER	61	62	EVENT DATE	74	75	REPORT DATE	80	

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

- At 1335 on 6/27/79, Fuel Storage Pool-Area radiation monitor R-5 was declared inoperable due to a loss of power to R-5. Tech. Spec. section 3.3.3.1 and Table 3.3-6 requires R-5 to be operable when fuel is in the storage pool. Tech. Spec. 3.3.3.1 action statement requirements were met. R-5 was returned to operation at 1425 on 6/27/79. The health and safety of the public were not affected by this occurrence.

- 10 | The feed breaker to R-5 was found open. An investigation failed to determine the
11 | cause for the breaker being open. The breaker was closed and R-5 declared operable.
12 | at 1425 on 6/27/79.

POOR ORIGINAL

7908010

NHIC USE ONLY