LICENSEE EVENT REPORT

	CONTROL BLOCK: [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M E M Y P 1 2 0 0 - 0 0 0 - 0 0 3 4 1 3 1 1 4 5 5 5 CAT 58
0 1 7 8	REPORT L 6 0 5 0 0 0 3 0 9 7 0 7 2 2 7 9 8 0 7 2 7 7 9 9 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
OIX	During routine steady state operations, a spurious trip occurred on the RPS Ch. D
0 3	TM/LP circuit. All other channels and indications were normal. The following day,
0 4	Ch. D AT power indication became erratic. An unstable output from a hi select dual .]
0 5	amplifier was found to be the cause. Because the failure affected only one of the
06	four operable channels and the minimum degree of redundancy was maintained, there was
	no affec; on the public health or safety.
018	80
0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE SEFECT SHUTDOWN HOURS 22 ATTACHMENT NERD SUPPLIER MANUFACTURER MANUFA
1 0	The cause of the failure could not be determined on site and the unit was returned to]
	the manufacturer for failure analysis. A spare unit was installed, surveillance test-
12	ing was performed to verify channel operability, and the channel was returned to
13	service.
7 8	9 SO METHOD OF
1 5	STATUS N POWER OTHER STATUS 30 DISCOVERY DISCOVERY DESCRIPTION (32) E 28 0 9 7 29 NA A 44 45 46 Operator Observation
	ACTIVITY CONTENT SELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA N
1 7	NUMBER TYPE DESCRIPTION (39) NA PERSONNEL INJURIES 13 80
18	NUMBER DESCRIPTION(41) O O O O O
1 9	1
20	PUBLICITY ISSUED DESCRIPTION 45 NAC USE ONLY NA
7 8	9 10 68 69 80 5 Name of agentages Peter L. Anderson 580 05 207-442-8766