	LICENSEE EVENT REPORT
	CONTROL BLOCK: [] [] [] [] [] [[] [] [] []
0 1	N C B E P 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 CAT 58
CON'T 0 1 8	REPORT L 6 0 5 0 - 0 3 2 4 7 0 7 0 2 7 9 8 0 7 3 1 7 9 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 While performing PT 1.1.4PC, Reactor low water level #1 Channel Calibration,
0 [3]	B21-LIS-N017 C, switch 1 was found to be out of tolerance low. The required value is]
0 4	12.5 inches of water and the as found value was 7.07 inches of water.
0 5	Technical Specifications 2.2.1, 6.9.1.9a
0 6	
0 7	
08	
0 9	SYSTEM GAUSE SUBCODE S
	LERING EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE NO. NO. 17 REPORT 7 9
	ACTION FUTURE EFFECT SHUTBOWN HOURS 22 ATTACHMENT FORM SUB-PLIER MANUFACTURER E 18 X 19 Z 20 Z 21 0 0 0 0 N 23 Y 24 N 25 B 0 8 0 26 CAUST DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	The only reason determined was instrument drift. The instrument was recalibrated and]
111	returned to service. A plant modification has been written to replace the bi-stable
1121	switches with analog instrumentation during the 1980 refueling outage. This new
1 3	instrumentation is much more stable and should greatly reduce the drift problems now
1 4	being encountered.
	G 28 0 0 0 0 28 NA OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION (32) 9 10 12 17 4 45 80
	CETIVITY CONTENT LLEASED OF BELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 NA PERSONNEL EXPOSURES AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
1 7 8	D D D D D DESCRIPTION (39) D D D D D D DESCRIPTION (39) PERSONNEL INJURIES 13 80
T]B]	NUMBER DESCRIPTION (41) 0 0 0 (40) NA
1 9	2 11 12 12 13 12 143 1
20	PURILICITY SSUED DESCRIPTION (45) N 1(44) NA NBC USE ONLY
	NAME OF EDERAGE A. C. Tollison, Jr. 919-457-952468 230