

LICENSEE EVENT REPORT

CONTRACT BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | G A E I T H U | 0 0 0 0 0 0 0 0 0 0 0 0 0 0 | 3 4 1 1 1 1 1 | 4 | 5
7 8 9 14 15 25 26 30 37 CAT 38
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 38

0 1 | L | 0 5 1 0 3 0 3 2 1 | 7 | 0 7 2 5 7 9 | 8 | 0 7 3 0 7 9 | 9
60 61 68 69 74 75 80
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

0 2 | With the Reactor in the shutdown cooling mode, the IC RHR pump (E11-C002C) was found
 0 3 | to have an excessive leak at the mechanical seal. When the IC RHR pump was removed
 0 4 | from service to repair the seal, the reactor unit was not in compliance with Tech-
 0 5 | nical Specification 3.5.B.1.a because the RHR pumps in the B loop were already out
 0 6 | of service for hanger repairs. Public health and safety were not affected by this
 0 7 | incident.

0 1 9 | C F | E | b | P U M P X X | B | Z |
9 10 11 12 13 14 15 16 18 19 20
 SYSTEM CODE CAUSE CODE CAUSE SUB CODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

17 | 7 9 | 0 5 0 | 0 1 | T | 0 |
21 22 23 24 25 26 27 28 29 30 31 32
 LER NO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO

0 1 8 | A Z | Z | 0 0 0 0 | Y | Y | N | B 5 1 3 1 0 | 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

1 1 0 | The excessive leakage was caused by the mechanical seal being ruptured. The seal
 1 1 1 | was replaced and the IC RHR pump returned to service on 4-2/-79.
 1 1 2 |
 1 1 3 |
 1 1 4 |

1 5 | H | 0 0 0 | N/A | 21 | Operator Observation |
7 8 9 10 11 12 13 44 45 46 80
 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 | Z | Z | N/A | N/A | LOCATION OF RELEASE |
7 8 9 10 11 12 44 45 80
 ACTIVITY TAKEN CONTENT AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 | 0 0 0 | Z | N/A |
7 8 9 10 11 12 13 44 45 80
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 | 0 0 0 | N/A |
7 8 9 10 11 12 13 44 45 80
 PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | Z | N/A |
7 8 9 10 11 12 44 45 80
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 | N | N/A |
7 8 9 10 44 45 80
 PUBLICITY ISSUES DESCRIPTION NRC USE ONLY

7908060463

516 013

NARRATIVE REPORT -
LER 50-321/1979-50, Rev. 0

With the reactor shutdown for maintenance and refueling, while running in the shutdown cooling mode and preparing to perform the RPV hydrostatic test, the 1C RHR pump (E11-C002C) was found to have an excessive leak at the mechanical seal. When the 1C RHR pump was removed from service, to permit maintenance personnel to replace the seal, the reactor unit was not in compliance with Technical Specification section 3.5.B.1.a because the RHR pumps in the B loop were already out of service for hanger repairs.

The ruptured mechanical seal was replaced and the 1C RHR pump returned to service on 4-27-79.

Public health and safety were not affected by this incident.