

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | 0 | H | D | B | S | 1 | 2 | 0 | 0 | - | 0 | 0 | N | P | F | - | 0 | 3 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | - | 0 | 3 | 4 | 6 | 7 | 0 | 7 | 0 | 5 | 7 | 9 | 8 | 0 | 8 | 0 | 3 | 7 | 9 | 9

02 | On 7/5/79 and again on 7/9/79, while conducting surveillance testing on valve MS-106, |
03 | the Auxiliary Feedwater (AFW) Pump Turbine 1-1 Steam Inlet Valve, it was found that it |
04 | would not close on a simulated low turbine inlet pressure signal. There was no danger |
05 | to the health and safety of the public or station personnel. The unit was subcritical |
06 | and AFW Train 1-2 was operable. (NP-33-79-94) |
07 | |
08 | |

09 | SYSTEM CODE | CH | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | A | 13 | COMPONENT CODE | R | E | L | A | Y | X | 14 | COMP. SUBCODE | B | 15 | VALVE SUBCODE | Z | 16 |
17 | LER/RO REPORT NUMBER | 7 | 9 | SEQUENTIAL REPORT NO. | 0 | 7 | 7 | OCCURRENCE CODE | 0 | 3 | REPORT TYPE | L | REVISION NO. | 0 |
ACTION TAKEN | B | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | Y | 23 | NPRD-4 FORM SUB. | Y | 24 | PRIME COMP. SUPPLIER | A | 25 | COMPONENT MANUFACTURER | C | 6 | 4 | 9 | 26

10 | The cause of both of these occurrences was component failure. The pins on the control |
11 | relays were not making proper contact with their socket. Both relays have now been |
12 | replaced. Both sockets will be replaced to assure proper operation. |
13 | |
14 | |

15 | FACILITY STATUS | C | 28 | % POWER | 0 | 0 | 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | Post maintenance surveillance test | 32 |
16 | ACTIVITY CONTENT | Z | 33 | RELEASED OF RELEASE | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36

17 | PERSONNEL EXPOSURES | NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39

18 | PERSONNEL INJURIES | NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41

19 | LOSS OF OR DAMAGE TO FACILITY | TYPE | Z | 42 | DESCRIPTION | NA | 43

20 | PUBLICITY ISSUED | N | 44 | DESCRIPTION | NA | 45

POOR ORIGINAL

7908100406

526 353

TOLEDO EDISON COMPANY
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE
SUPPLEMENTAL INFORMATION FOR LER NP-33-79-94

DATE OF EVENT: July 5, 1979 and July 9, 1979

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Failure of MS 106 relays R1 and R3 to energize

Conditions Prior to Occurrence: The unit was in Mode 4 on July 5, and in Mode 3 on July 9, with Power (MWT) = 0, and Load (Gross MWE) = 0.

Description of Occurrence: On July 5, 1979 at 0200 hours while performing Surveillance Test ST 5071.04, "Auxiliary Feedwater System Channel Functional Test", valve MS 106, Auxiliary Feedwater Pump Turbine Steam Inlet Valve 1-1 from Steam Generator 1-1, would not automatically close as designed on a simulated low turbine inlet pressure signal. Since the unit was in Mode 4, the Auxiliary Feedwater System is not required, and no Action Statement was entered. The system was repaired and declared operable at 0145 hours on July 6, 1979. This occurrence is being reported to document a component failure.

A similar failure of MS 106 occurred on July 9, 1979 at 2230 hours while ST 5071.04 was being performed to assure operability after maintenance on a failure of a torque switch which occurred on July 8, 1979 at 1530 hours (Licensee Event Report NP-33-79-85). The unit was in Mode 3 and still in the Action Statement of Technical Specification 3.7.1.2 (as of July 8) which states, "With one Auxiliary Feedwater System inoperable, restore the inoperable system to operable status within 72 hours or be in Hot Shutdown (Mode 4) within the next 12 hours". The system was repaired and declared operable at 0245 hours on July 10, 1979, approximately 36 hours after the Action Statement was entered.

Designation of Apparent Cause of Occurrence: MS 106 was not operating because closing relays R3 and later R1 were not energizing. The relays were initially replaced with new ones but R3 still did not function. The problem was determined to be bad contact between the relay pins and the socket base. It was corrected by bending the pins on R3 out slightly. The second failure on July 9 was corrected by spreading the pins on R1.

Analysis of Occurrence: There was no danger to the health and safety of the public or to station personnel. During the first occurrence the unit was in Mode 4 and auxiliary feedwater was not required. During the second occurrence, the unit was subcritical and Auxiliary Feedwater Train 2 was operable.

Corrective Action: The first occurrence was investigated under Maintenance Work Order 79-2441. The R1 and R3 relays were replaced, and the pins on the R3 relay were spread apart to assure good contact. ST 5071.04 was performed on July 6, 1979 to verify operability.

LER #79-077

526 354

The second occurrence was investigated under Maintenance Work Order 79-2458. The corrective action for the second occurrence was to spread the pins apart on the R1 relay. ST 5071.04 was performed at 0245 hours on July 10, 1979 to verify operability, removing the unit from the Action Statement. New sockets will be installed on both the R1 and R3 relays to insure proper operation.

Failure Data: There have been other relay failures but none identified to have been caused by poor contact between the pins and the socket base.

LER #79-077

526 355