CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 A L B R F 1 2 0 0 - 0 0 0 0 0 3 4 1 1 1 1 4 5 5 CAT 58
CON'T O 1 REPORT L O O O O O O O O O
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0] 2 With unit in normal operation, HPCI failed to come to rated speed and flow within the
o 3 required time limit while SI 4.5.E.l.d and .e (T.S. 3.5.E-2) were being performed.
There was no significant occurrence or chain of events. Redundant systems were oper-
able. There was no danger to the health or safety of the public. There have been no
0 6 previous occurrences.
0 7
0 8 1
SYSTEM CAUSE CODE SUBCODE SUBC
SEQUENTIAL REPORT NO. 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER E 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 Y 24 X 25 S 0 7 5 26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
Stop valve FCV 73-18 did not fully open due to the loosening of an adjusting screw [1] [allowing the balance chamber to get out of adjustment. The adjusting screw was set
properly and locked. Shutte and Koerting 10-inch cast steel stop valve; 1250 class,
13 900 rating, 100 psi.
7 8 9 80
FACILITY STATUS 3. POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 0 9 4 29 NA B 31 Operator observation
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 6 Z 33 Z 34 NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA 11 12 13 13 13 80
PERSONNEL INJURIES NUMBER 0 0 0 0 40 NA NA 11 12
TYPE DESCRIPTION 1 9 Z (42) NA
AND THE TANK Y
2 6 N 44 NA SECRETION 45 80 5
NAME OF PREPARER PHONE

660 125