	LICENSEE EVENT REPORT
	CONTROL BLOCK: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
OTI 8	G A E I H 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
CON'T	REPORT LIG 0 5 0 0 0 3 6 6 7 0 7 1 12 7 9 6 0 8 0 3 7 9 9 9
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [During the course of performing maintenance on the "B" H2O2 analyzer the oxygen cell]
0 3	was found to be defective on July 12, 1979. The failure caused the analyzer to be
0 4	inoperative. The inoperability was reported to the shift supervisor but it was not
0 5	determined to be a limiting condition for plant operation until July 15, 1979 when
06	it was noted the AC power was off. The "A" analyzer was operable. This is not a
0 7	recurring problem.
0 8	
7 8	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
7 3	9 10 11 12 13 18 19 20 REVISION
	17 REPORT NO. 17 19 1 1 10 3 1 1 10 32 10 32 10 32 10 32 10 32 10 32 10 32 10 32 10 32
	ACTION FUTURE STREET SHUTDOWN HOURS 22 ATTACHVENT NORM SUB FRIME COMP. COMPONENT MANUFACTURED FORM SUB. FRIME COMP. MANUFACTURED FORM SUB. FRIME COMPONENT FORM SUB. FRIME F
10	A broken wire on the oxygen cell was found to be the problem. A new cell was
11	ordered and should be installed by August 10, 1979. The cause for the wire breaking
1 2	could have been many different things due to the extreme delicacy of the cell.
13	
13	60
	FACILITY SPOWER OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION (32) IG (23) 0 0 1 (29) N/A (31) Operator Observation
-	ACTIVITY CONTENT 12 13 44 45 46 LOCATION OF RELEASE 36
7 8	PERSONNEL EXPOSURES. NUMBER TYPE DESCRIPTION (39)
7 8	O O O O O Z O O O O O O O O O O O O O O
1 0	PERSONNEL INJURIES NUMBER DESCRIPTION (4) N/A 561 237
	LOSS OF OR DAMAGE TO FACILITY (3) TYPE DESCRIPTION N/A 7908130 435 5
, ,	PUBLICITY ISSUED DESCRIPTION (1) IN [13] N/A NRC USE ONLY N/A
1 B	R. T. Nix PHONE 912-367-7781