### OPERATING DATA REPORT

DOCKET NO.	<u>50-321</u>
DATE	8-8-79
COMPLETED BY TELEPHONE	912-367-7781

#### OPERATING STATUS

t.	Unit Name: Hatch - 1	Notes
	Reporting Period: July 1979	
	Licensed Thermal Power (MWt): 2436	
	Nameplate Rating (Gross MWe): 809.3	
5.	Design Electrical Rating (Net MWe):786.3	
6.	Maximum Dependable Capacity (Gross MWe):	
7.	Maximum Dependable Capacity (Net MWe):	
8.	If Changes Occur in Capacity Ratings (Items Number 3 Through 7) Since	e Last Report Give Reasons:

9. Power Level To Which Restricted, If Any (Net MWe):

10. Reasons For Restrictions, If Any:

	This Month	Yrto-Date	Cumulative
11. Hours In Reporting Period	744	5087	42793
12. Number Of Hours Reactor Was Critical	0	2449.9	30897.1
13. Reactor Reserve Shutdown Hours	0	0	0
14. Hours Generator On-Line	0	2414.1	28414.8
15. Unit Reserve Shutdown Hours	0	0	0
16. Gross Thermal Energy Generated (MWH)	0	5492776	55088561
17 Gross Electrical Energy Generated (MWH)	0	1798940	17849271
18. Net Electrical Energy Generated (MWH)	-4313	1707287	16979180
19. Unit Service Factor	0	47.5	68.3
20. Unit Availability Factor	0	47.5	68.3
21. Unit Capacity Factor (Using MDC Net)	0	45.9	55.8
22. Unit Capacity Factor (Using DER Net)	0	42.7	51.9
23. Unit Forced Outage Rate	0	9.5	17.4
	and the second s	And the second s	and the second s

24. Shutdowns Scheduled Over Next 6 Months (Type, Date, and Duration of Each):

8-15-79	
Forecast	Achistved

678252/77

7908150519

## AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO.	_ 50-321
UNIT	Hatch - 1
DATE	8-8-79
COMPLETED BY	P. B. Allen
TELEPHONE	912-367-7781

MONTH \_\_\_\_\_ July 1979

AVERAGE DAILY POWER LEVEL (MWe-Net)	DAY AV	ERAGE DAILY POWER LEVEL (MWe-Net)
-5	17	-6
6	18	-6
-6	19	-5
-6	20	- 6
-5	21	-6
-5	22	-6
-6	23	-6
-6	24	-5
-6	25	~ 5
-6	26	- 5
-6	27	-6
	20	-6
-6	29	-7
-6	30	-6
-6	31	-5
-6		

#### INSTRUCTIONS

On this format, list the average daily unit power level in MWe-Net for each day in the reporting month. Compute to the nearest whole megawatt,

(9/77)

1023

#### UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH July 1979

DO COMPL TEI

CKET NO.	50-321
DATE	<u>Hatch - 1</u> 8-8-79
ETED BY	P. B. Allen
EFHONE	912-367-7781

	Sin.	Date	Type1	Duration (Hours)	Reason?	Method of Shatting Down Reactor <sup>3</sup>	Licensee Event Report #	System Code <sup>4</sup>	Component Code <sup>5</sup>		Cause & Corrective Action to Prevent Recurrence
POOR ORIGINAL	79-10	790422	S	744	C	1	N/A	ZZ	FUELXX	Snutdown to	o facilitate refueling
\$5287.9	F: Fe	nced beduled	C-Re D-R E-G F-Ad G-Op	nipment Fa intenance o fo ity Re Train	estriction ning & L F frot (Ex	1 icense Exa	3 mination	Method 1-Manu 2-Manu 3-Auto		4	Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG- 0161) Exhibit 1 - Same Source

July 1979

#### Cold Shutdown for Refueling

Following the compilation of Health Physics Dosimetry Records for the previous month, it was found that seven employees received doses exceeding 10% of our annual allowable limits. The exposures were received as a result of cladding removal in the reactor vessel and were recorded as follows:

Employee	mr
1	1545
2	1428
3	1930
4	1352
u.	1268
5	1410
7	1364

678255

100.00

# HATCH 1 SAFETY - RELATED MAINTENANCE REQUESTS TO BE REPORTED FOR JULY 1979

NUMBER 78-3261	DATE COMPLETED	DESCRIPTION Sealed four 4" conduits under control room computer console with silicone foam
79-1254	7-12-79	Cleaned off pipe welds on Cont. Atmos. Cooling System - with class 2 Piping welds wire brush on air end grinder
78-3187	6-28-79	Patched breached fire barrier in RPS vertical cablewav with Semco patch kit, lot # 05913 on 130' el. vert. cablewav and on 147' el. cable spread over vert. cablewav
78-2712	6-28-79	Sealed the two penetrations in each unit 1 D/G SW GR. room west wall with silicone foam both in and around the cable ducts
79-3666	7-22-79	Rebuilt and installed 1B Fuel Pool Cooling Pump Outboard on G41-COOlB
79-1782	7-22-79	Removed old cylinders and installed 4 new air cylinders on F13-E008
79-3769	7-22-79	Installed terminal strips in junction boxes adjacent to subject switches, terminated switch- associated cables at terminal strips, and then installed necessary length of cable from terminal strip to switch (per DCR 78-330, Rev. 1)
79-943	7-20-79	Replaced valves and piping as per DCR 77-26
79-1255	7-12-79	Cleaned off weld on Core Sprav system-Class 2 piping welds with wire brush on air end grinder

4

\$78256

. . . . . . .

79-1253	7-12-79	Cleaned off weld on RHR system-Class 2 piping welds with wire brush on air end grinder
79-2742	7-13-79	RHR Ht. Exc. Crosstie Relief valve had blanks on both sides; lapped seats and set pressure at 83 psig
79-2424	7-12-79	Disassembled RHR return check valve, cleaned seats, rotated arm 1800 to pick seat up higher for better seat
79-2155	7-13-79	Installed circuit breakers and voltage devices on RPS MG set breaker panels A, B, C, and D as per DCR 78-419; completed internal wiring and installed panels in boxes
79-2529	7-18-79	Rebuilt Scram Pilot Valves per HNP-1-6107 on all HCV
79-3431	7-19-79	MR voided; see MR 1-79-3090
79-3641	7-18-79	Disconnected cable R25-S001 at B31-P002A as per DCR 77-271, Rev. 1
79-3955	7-22-79	Modified support as per DCR 79-300
79-624	7-31-79	Rebuilt spare RWCU pump using manual S17355
78-4078	7-27-79	Removed valve and transferred to hotmachine. Grounded spotweld off Bonnet/body and lapped seat reassembly valve; respot weld bonnet/body and reinstalled valve
78-3061	7-28-79	Cleaned poppett and replaced bonnett gasket on RWCU dump valve to condenser
79-1409	7-25-79	Installed and removed steamline plugs as needed during refueling outage

678257

- 57, 79

79-1415	7-25-79	Installed Drver Separator Pool plugs after moving
	•	separator and Dryer from pool
79-1410	7-27-79	Reinstalled R.P.V Head Insolation Iaw. HNP-1-6715
79-1420	7-27-79	Cleaned flanges, replaced gaskets and installed Head piping as per HNP-1-6710
79-1423	7-25-79	Cleaned RPV head flanges with stainless brushes and lent free rags; installed new Read o'rings; installed RPV head and tensioned studs
79-1424	7-25-79	Removed Dryer and Separator prior to refueling; reinstalled Dryer and Separator as per HNP-1-6730
79-3828	7-25-79	Removed fuel support from location 50-19 and found it was cocked with the alignment pin holding it up as evidenced by marks on 0.P.; removed burr between alignment ears and cleaned J.P.
79-3815	7-23-79	Vacuumed the Jet pump support plate as indicated by T. V. inspection performed on 5-30-79
78-2637	6-29-79	Disassembled 1C PSW pump disch check valve, welded stem, machined to proper clearance and reinstalled
79-1780	7-3-79	Fabricated shaft for pulley with zerk fittings and installed same as per DCR 79-143, Rev. 0
79-3214	6-28-79	Tested safety relief valve as per HNP-1-3258M; set pressure to 200 psig
79-2961	6-28-79	Reinstalled minimum flow value and torqued nuts to 675 ft. 1bs.

79-2556	7-11-79	Removed relief value on top of diesel air compressor R43-101, disassembled and cleaned parts. Value worked properly when tested so value was reinstalled
79-3595	7-13-79	Found bad alarm card in annunciator alarm which tripped when any A.C. spike occurred in Radwaste room; also replaced floor drain sample tank hi alarm, giving same problem
79-3320	7-6-79	Removed clamp from restraint 2N22-R109 and reinstalled on 1E21-CSR-78
70-3790	7-14-79	Removed control rod blade 50-19 and replaced with a new blade stored in the Unit 1 fuel pool
79-3667	÷ 7-8-79	Replaced blown fuse which feeds voltage to the pilot valve solenoid
79-3643	7-10-79	Installed and removed jumpers as per MR jumper sheet # 1-79-49
79-3497	7-11-79	Disconnected wiring on RCIC cond. Condensate motor; found suitable for Unit 1
79-1955	6-30-79	Lapped new seat after putting in HPCI turbine exhaust to Torus Check valve; replaced disk after machining disk down per DCR-290
79-2284	6-27-79	Honed seat ring and flapper seat, cleaned out inside of valve, repacked flapper hing pin; replaced hing pin gasket and reassembled valve
79-2154	7-2-79	Mounted racks and panels C71-P003A-D in RPS MG Set Room per drawing H-13121 R 244 and DCR 78-419

79-3390	7-1-79	Lapped seat ring to a 50° bevel and remachined plug to a 5° 1/2° bevel; lapped plug to seat ring with 600 grit lapping compound. Cap was welded
79-2154	6-20-79	back on. Removed disc and found that it was hanging off center of seat. Made a new bushing with a .030 off set
		and installed them, replaced hinge pins and all three pressure seals