

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 101 MARIETTA ST., N.W., SUITE 3100 ATLANTA, GEORGIA 30303

AUG 7 1979

In Reply Refer To: RII:JPO 50-400, 50-403 50-402, 50-403

> Carolina Power and Light Company ATTN: J. A. Jones Executive Vice President and Chief Operating Officer 411 Fayetteville Street Raleigh, North Carolina 27602

Gentlemen:

The enclosed Bulletin 79-18 is forwarded to you for information. No

written response is required. If you desire additional information

regarding this matter, please contact this office.

Sincerely,

James P. O'Reilly Director

Enclostes: 1. IE Bulletin No. 79-18 2. Listing of IE Bulletins

Issued in Last Six Months

845 308

110

Carolina Power and Light Company

cc w/encl: R. Parsons, Site Manager Post Office Box 101 New Hill, North Carolina 27562 -2-

845 309

ccessions No: 7908030403 FISINS No: 6820

UNITED STATES NUCLEAR REGULATORY COMMISSIO OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D.C. 20555

August 7, 1979

IE Bulletin No. 79-18

AUDIBILITY PROBLEMS ENCOUNTERED ON EVACUATION OF PERSONNEL FROM HIGH-NOISE AREAS

Description of Circumstances:

In January 1979, a number of licenses personnel were engaged in routine activities in the auxiliary building at the Florida Power Corporation, Crystal River Unit 3 nuclear plant. While these individuals were working in the auxiliary building, in a high-noise (fan) area, an unplanned release of radioactive noble gases was detected by building monitors within the auxiliary building at concentrations which caused the license to initiate the facility emergency plan auxiliary building evacuation proced at The facility Emergency Officer (Shift Supervisor) assessed the 'sonitor readings and initiated an suxiliary building evacuation. The evacuation announcement, made over the licensee's PA system, was not heard by the personnel working in the high-noise area. Licensee personnel did evacuate the auxiliary building upon observing that other personnel had left, and afte: calling the control room to inquire if an evacuation had been initiated. During these occurrences, licensee personnel were not exposed to quantities of radionuclides above regulatory guidance. However, the potential existed for inadvertent unnecessary exposition of individuals to radioactive materials.

Subsequent to the NRC followup inspection of this occurrence, Florida Power Corporation initiated an assessment of this situation and performed an engineering evaluation and identified several plant areas where the annunciator system needed audibility improvement. The licensee bas installed a new suxiliary building evacuation tone signal and may add visual alarm indicators in areas of very high-noise.

Action to be Taken by the Licensees:

For all power reactor facilities with an operating license:

1. Determine whether current alarm systems and evacuation announcement systems are clearly audible or visible throughout all plant areas with emphasis on high-noise areas. Determination in high noise areas must be made with the maximum anticipate

DUPLICATE DOCUMENT Entire document previously entered into system under: ANO 7908030403 No. of pages: