TIC



UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA DRIVE, SUITE 1000 ARLINGTON, TEXAS 76012

July 26, 1979

In Reply Refer To: RIV Do let No. STN 50-482/IE Bulletin No. 79-17

> Kansas Gas & Electric Co. Attn: Mr. Glean L. Koester Vice President-Operations Post Office Tox 208 Wichita, Kansas 67201

Gentlemen:

The enclosed IE Bulletin 79-17 is forwarded to you for information. No written response is required. However, the potential corrosion behavior of safety-related systems as it regards your plant over the long-term should be taken into consideration. If you desire additional information concerning this matter, please contact this office.

Sincerely,

night facting Karl V. Sevfrit

Director

Enclosures:

 IE Bulletin No. 79-17
List of IE Bulletins Issued in Last 12 Months

cc: w/enclosures

Messrs. Nicholas A. Petrick, SNUPPS D. T. McPhee, Kansas City Power and Light Company Gerald Charnoff, Shaw, Pittman, Potts & Trowbridge E. W. Creel, Kansas Gas and Electric Company



UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D. C. 20555

IE Bulletin No. 79-17 Date: July 26, 1979 Page 1 of 4

PIPE CRACKS IN STAGNANT BORATED WATER SYSTEMS AT PWR PLANTS

Description of Circumstances:

During the period of November 1974 to February 1977 a number of cracking incidents have been experienced in safety-related stainless steel piping systems and portions of systems which contain oxygenated, stagnant or essentially stagnant borated water. Metallurgical investigations revealed these cracks occurred in the weld heat affected zone of 8-inch to 10-inch type 304 material (schedule 10 and 40), initiating on the piping I.D. surface and propagating in either an intergranular or transgranular mode typical of Stress Corrosion Cracking. Analysis indicated the probable corrodents to be chloride and oxygen contamination in the affected systems. Plants affected up to this time were Arkansas Nuclear Unit 1, R. E. Ginna, H. B. Robinson Unit 2, Crystal River Unit 3, San Onofre Unit 1, and Surry Units 1 and 2. The NRC issued IE Circular 76-06 (copy attached) in view of the apparent generic nature of the problem.

During the refueling outage of Three Mile Island Unit 1 which began in February of this year, visual inspections disclosed five (5) through-wall cracks at welds in the spent fuel cooling system piping and one (1) at a weld in the decay heat removal system. These cracks were found as a result of local boric acid buildup and later confirmed by liquid penetrant tests. This initial identification of cracking was reported to the NRC in a Licensee Event Report (LER) dated May 16, 1979. A preliminary metallurgical analysis was performed by the licensee on a section of cracked and leaking weld joint from the spent fuel cooling system. The conclusion of this analysis was that cracking was due to Intergranular Stress Corrosion Cracking (IGSCC) originating on the pipe I.D. The cracking was localized to the heat affected zone where the type 304 stainless steel is sensitized (precipitated carbides) during welding. In addition to the main through-wall crack, incipient cracks were observed at several locations in the weld heat affected zone including the weld root fusion area where a miniscule lack of fusion had occurred. The stresses responsible for cracking are believed to be primarily residual welding stresses inasmuch as the calculated applied stresses were found to be less than code design limits. There is no conclusive evidence at this time to identify those aggressive chemical species which promoted this IGSCC attack. Further analytical efforts in this area and on other system welds are being pursued.

IE Bulletin No. 79-17 Date: July 26, 1979 Page 2 of 4

304056

Based on the above analysis and visual leaks, the licensee initiated a broad-based ultrasonic examination of potentially affected systems utilizing statical techniques. The systems examined included the spent fuel, decay

1 removal, makeup and purification, and reactor building spray systems in contain stagnant or intermittently stagnant, oxygenated boric acid environmeuts. These systems range from 2-1/2-inch (HPSI) to 24-inch (borated water storage tank suction), are type 304 stainless steel, schedule 160 to schedule 40 thickness, respectively. Results of these examinations were reported to the NRC on June 30, 1979, as an update to the May 16, 1979 LER. The ultrasonic inspection as of July 10, 1979, has identified 206 welds out of 946 inspected having UT indications characteristic of cracking randomly distributed throughout the aforementioned sizes (24"-14"-12"-10"-8"-2" etc.) of the above systems. It is important to note that sig of the crack indications were found in 2-1/2-inch diameter pipe of the high pressure injection lines inside containment. These lines are attached to the main coolant pipe and are nonisolable from the main coolant system except for check valves. All of the six cracks were found in two high pressure injection lines containing stagnated borates water. No cracks were found in the high pressure injection lines which were occasionally flushed during makeup operations. The ultrasonic examination is continuing in order to delineate the extent of the problem.

The above information was previously provided in Information Notice 79-19.

For All Pressurized Water Reactor Facilities with an Operating License:

- Conduct a review of safety-related stainless steel piping systems within 30 days of the date of this Bulletin to identify systems and portions of systems which contain stagnant oxygenated borated water. These systems typically include ECCS, decay/residual heat removal, spent fuel pool cooling, containment spray and borated water storage tank (BWST-RWST) piping.
 - (a) Provide the extent and dates of the hydrotests, visual and volumetric examinations performed per 10 CFR 50.55a(g) (Re: IE Circular 76-06 enclosed) of identified systems. Include a description of the nondestructive examination procedures, procedure qualifications and acceptance criteria, the sampling plan, results of the examinations and any related corrective actions taken.
 - (b) Provide a description of water chemistry controls, summary of chemistry data, any design changes and/or actions taken, such as periodic flushing of recirculation procedures to maintain required water chemistry with respect to pH, B, CL, F, 0₂.

POOR

ORIGINAL

IE Bulletin No. 79-17 Date: July 26, 1979 Page 3 of 4

- (c) Describe the preservice NDE performed on the weld joints of identified systems. The description is to include the applicable ASME Code sections and supplements (addenda) that were followed, and the acceptance criterion.
- (d) Facilities having previously experienced cracking in identified systems, Item 1, are requested to identify (list) the new materials utilized in repair or replacement on a system-by-system basis. If a report of this information and that requested above has been previously submitted to the NRC, please reference the specific report(s) in response to this Bulletin.
- Facilities at which ISI examinations have not been performed (i.e., visual and volumetric UT) on stagnant portions of systems identified in Item 1. above, shall complete the following actions at the earliest practical date but not later than 90 days after the date of the Bulletin.
 - (a) Perform ASME Section XI visual examination (IWA 2210) of normally accessible^{*} welds of all engineered safety systems at service pressure to verif^{**} system integrity.
 - (b) Conduct ultrasonic examination and liquid penetrant surface examination or a representative number of circumferential welds in normally accessible[±] portions of systems identified by Item 1 above. It is intended that the sample number of welds include all pipe diameters in the 2-1/2 inch to 24-inch range with no less than a 10 percent sample by system and pipe wall thickness. It is also intended that the UT examination cover the weld fusion zone and a minimum of 1/2-inch on each side of the weld at the pipe I.D. The examination shall be in accordance with the provisions of ASME Code Section XI-Appendix III and Supplements of the 1975 Winter Addenda, except all signal responses shall be evaluated as to the nature of the indications. These code methods or alternative examination methods, combination of methods, or newly developed techniques may be used provided the procedures yield a demonstrated effectiveness in detecting stress corrosion cracking in austenitic stainless steel piping.
 - (c) If cracking is identified during Item (a) and (b) examinations, all welds of safety-related piping systems and associated subsystems where dynamic flow conditions do not exist during normal operations (Item 1) shall be subject to volumetric examination and remain, including piping in areas which are normally inaccessible.

^{*} Normally accessible refers to those areas of the plant which can be entered during reactor operation.

IE Bulletin No. 79-17 Date: July 26, 1979 Page 4 of 4

- 3. Identification of cracking in one unit of a multi-unit facility which causes safety-related systems to be inoperable shall require immediate examination of accessible portions of other similar units which have not been inspected under the ISI provisions of 10 CFR 50.55a(g) unless justification for continued operation is provided.
- Any cracking identified shall be reported to the Director of the appropriate NRC Regional Office within 24 hours of identification followed by a 14-day written report.
- Provide a written report to the Director of the appropriate NRC Regional Office within 30 days of the date of this Bulletin addressing the results of your review required by Item 1.
- 6. Complete the examination required by Item 2 within 90 days of the date of this Bulletin and provide a written report to the Director of the appropriate NRC Regional Office within 120 days of the date of this Bulletin describing the results of the inspections required by Item 2 and any corrective measures taken.
- Copies of the reports required by Items 4, 5 and 6 above shall be provided to the Director, Division of Operating Reactors, Office of Inspection and Enforcement, Washington, D. C. 20555.

Approved by GAO, B180225 (R0072), clearance expires 7/31/80. Approval was given under a blanket clearance specifically for idenified generic problems.



IE Circular 76-06

November 24, 1976

904059

STRESS CORROSION CRACKS IN STAGNANT, LOW PRESSURE STAINLESS PIPING CONTAINING BORIC ACID SOLUTION AT PWR'S

DESCRIPTION OF GIRCUMSTANCES:

During the period November 7, 1974, to November 1, 1975, several incidents of through-wall cracking have occurred in the 10-inch, schedule 10 type 304 stainless steel piping of the Reactor Building Spray and Decay Heat Systems at Arkansas Nuclear Plant No. 1.

On October 7, 1976, Virginia Electric and Power also reported throughwall cracking in the 10-inch schedule 40 type 304 stainless discharge piping of the "A" recirculation spray heat exchanger at Surry Unit No. 2. A recent inspection of Unit No. 1 Containment Recirculation Spray Piping revealed cracking similar to Unit No. 2.

On October 8, 1976, another incident of similar cracking in 8-inch schedule 10 type 304 stainless piping of the Safety Injection Pump Suction . Line at the Ginna facility was reported by the licensee.

Information received on the metallurgical analysis conducted to date indicates that the failures were the result of intergranular stress corrosion cracking that initiated on the inside of the piping. A commonality of factors observed associated with the corrosion mechanism were:

- The cracks were adjacent to and propagated along weld zones of the thin-walled low pressure piping, not part of the reactor coolant system.
- 2. Cracking occurred in piping containing relatively stagnant boric acid solution not required for normal operating conditions.
- 3. Analysis of surface products at this time indicate a chloride ion interaction with oxide formation in the relatively stagnant boric acid solution as the probable corrodant, with the state of stress probably due to welding and/or fabrication.



The source of the chloride ion is not definitely known. However, at ANO-1 the chlorides and sulfide level observed in the surface tarnish file near welds is believed to have been introduced into the piping during testing of the sodium thiosulfate discharge valves, or valve leakage. Similarly, at Ginna the chlorides and potential oxygen availability were assumed to have been present since original construction of the borated water storage tank which is vented to atmosphere. Corrosion attack at Surry is attributed to in-leakage of chlorides through recirculation spray heat exchange tubing, allowing buildup of contaminated water in an otherwise normally dry spray piping.

ACTION TO BE TAKEN BY LICENSEE:

1. Provide a description of your program for assuring continued integrity of those safety-related piping systems which are not frequently flushed, or which contain nonflowing liquids. This program should include comsideration of hydrostatic testing in accordance with ASME Code Section XI rules (1974 Edition) for all active systems required for safety injection and containment spray, including their recirculation modes, from source of water supply up to the second isolation valve of the primary system. Similar tests should be considered for other safetyrelated piping systems.

- 2. Your program should also consider volumetric examination of a representative number of circumferential pipe welds by nondestructive examination techniques. Such examinations should be performed generally in accordance with Appendix I of Section XI of the ASME Code, except that the examined area should cover a distance of approximately six (6) times the pipe wall thickness (but not less than 2 inches and need not exceed 8 inches) on each side of the weld. Supplementary examination techniques, such as radiography, should be used where necessary for evaluation or confirmation of ultrasonic indications resulting from such examination.
- A report describing your program and schedule for these inspections should be submitted within 30 days after receipt of this Circular.
- 4. The NRC Regional Office should be informed within 24 hours, of any adverse findings resulting during nondestructive evaluation of the accessible piping welds identified above.
- 5. A summary report of the examinations and evaluation of results should be submitted within 60 days from the date of completion of proposed testing and examinations.



This summary report should also include a brief description of plant conditions, operating procedures or other activities which provide assurance that the effluent chemistry will maintain low levels of potential corrodants in such relatively stagnant regions within the piping.

Your responses should be submitted to the Director of this office, with a copy to the NRC Office of Inspection and Enforcement, Division of Rear or Inspection Programs, Washington, D.C. 20555.

Approval of NRC requirements for reports concerning possible generic problems has been obtained under 44 U.S.C. 3152 from the U.S. General. Accounting Office.

(GAO Approval B-180255 (R0062), expires 7/31/77).

((



LISTING OF IE BULLETINS ISSUED IN LAST TWELVE MONTHS

Bulletin No.	Subject	Date Issued	Issued To
78-11	Examination of Mark I Containment Torus Welds	7/21/78	BWR Power Reactor Facilities for action: Peach Bottom 2 and 3, Quad Cities 1 and 2, Hatch 1, Monti- cello and Vermont Yankee
78-12	Atypical Weld Naterial in Reactor Pressure Vessel Welds	9/26/78	All Power Reactor Facilities with an Operating License (OL) or Construc- tion Permit (CP)
78-12A	Atypical Weld Naterial in Reactor Pressure Vessel Welds	11/24/78	All Power Reactor Facilities with an Operating License (OL) or Construc- tion Permit (CP)
78-12B	Atypical Weld Material in Reactor Pressure Vessel Welds	3/19/79	All Power Reactor Facilities with an Operating License (OL) or Construc- tion Permit (CP)
78-13	Failures in Source Heads of Kay-Ray, Inc., Gauges Models 7050, 7050B, 7051, 7051B, 7060, 7060B, 7061 and 7061B	10/27/78	All General and Specific Licensees with Kay-Ray Gauges
			P

Enclosure Page 1 of 4

78-14 Deterioration of 12/19/78 All GE BWR facilities Buna-N Components with an Operating in ASCO Solenoids License (OL) or Construction Permit (CP) All Power Reactor 79-01 Environmental Quali-2/8/79 fication of Class IE Facilities with an Operating License Equipment (OL) or Construction Permit (CP) 79-01A Environmental Qualification 6/6/79 All Power Reactor of Class IE Equipment Facilities with an Operating License (OL) or Construction Permit (CP)3/8/79 All Power Reactor 79-02 Pipe Support Base Plate Designs Using Facilities with an Operating License Concrete Expansion (OL) or Construction Anchor Bolts Permit (CP) 6/21/79 All Power Reactor 79-02 Pipe Support Base Facilities with an (Rev. 1) Plate Designs Using Operating License Concrete Expansion (OL) or Construction Anchor Bolts Permit (CP) All Power Reactor 3/12/79 79-03 Longitudinal Weld Facilities with an Defects In ASME SA-312 Operating License Type 304 Stainless (OL) or Construction Steel Pipe Spools Permit (CP) Manufactured by Youngstown Welding and Engineering Company All Power Reactor 3/30/79 79-04 Incorrect Weights Facilities with an for Swing Check Operating License Valves Manufactured (OL) or Construction by Velan Engineering Permit (CP) Corporation

> Enclosure Page 2 of 4

79-05	Nuclear Incident at Three Mile Island	4/1/79	All Power Reactor Facilities with an Operating License (OL) or Construction Permit (CP)
79-05A	Nuclear Incident at Three Mile Island	4/5/79	All Power Reactor Facilities with an Operating License (OL) or Construction Permit (CP)
79-0 5B	Nuclear Incident at Three Mile Island	4/21/79	All B&W Power Reactor Facilities with an Operating License (OL)
79-06	Review of Operational Errors and System Misalignments Identified During The Three Mile Island Incident	4/11/79	All Pressurized Water Power Reactor Facilities Except B&W Facilities
79-06A	Review of Operational Errors and System Misalignments Identified During the Three Mile Island Incident	4/14/79	All Westinghouse PWR Facilities with an Operating License (OL)
79-06A (Rev. 1)	Review of Operational Errors and System Mis- alignments Identified During the Three Mile Island Incident	4/18/79	All Pressurized Water Power Reactor Facilities of Westinghouse Design with an Operating License (OL)
79-06B	Review of Operational Errors and System Misalignments Identified During The Three Mile Island	4/14/79	All Combustion Engineer- ing PWR Facilities with an Operating License (OL)
79-07	Seismic Stress Analysis of Safety-Related Piping	4/14/79	All Power Reactor Facilities with an Operating License (OL) or Construction Permit (CP)

Enclosure Page 3 of 4

- 79-08 Events Relevant to BWR 4/14/79 Reactors Identified During Three Mile Island Incident
- 79-09 Failures of GE Type AK-2 5/11/79 Circuit Breaker in Safety Related Systems
- 79-10 Requalification Training 5/11/79 Program Statistics
- 79-11 Faulty Overcurrent Trip 5/22/79 Device in Circuit Breakers for Engineered Safety Systems
- 79-12 Short Period Scrams at 5/31/79 BWR Facilities
- 79-13 Cracking In Feedwater System Piping
- 79-14 Seismic Analyses for 7/2/79 As-Built Safety-Related Piping System
- 79-15 Deep Draft Pump 7/11/79 Deficiencies
- 79-16 Vital Area Access Controls 7/26/79

All BWR Power Reactor Facilities with an Operating License (OL) or Construction Permit (CP)

> All Power Reactor Facilities with an Operating License (OL) or Construction Permit (CP)

All Power Reactor Facilities with an Operating License (OL)

All Power Reactor Facilities with an Operating License (OL) or a Construction Permit (CP)

All Power Reactor Facilities with an Operating License (OL) or a Construction Permit (CP)

All PWRs with an Operating License (OL) for action. All BWR with a Construction Permit (CP) for information

All Power Reactor facilities with an Operting License (OL) or a Construction Permit (CP)

All Power Reactor Facilities with a Construction Permit and/or Operating License (OL)

All Power Reactors with an Operating License (OL) or anticipating fuel loading prior to January 1981.

Enclosure Page 4 of 4