

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | G | A | E | I | H | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5

01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 0 | 3 | 6 | 6 | 7 | 0 | 8 | 1 | 8 | 7 | 9 | 8 | 0 | 8 | 2 | 9 | 7 | 9 | 9

02 | While performing normal surveillance procedure HNP-2-3105, for Main Steam Line
03 | Pressure Instrument Functional Test and Calibration, 2B21-N015A was found to have
04 | a setpoint of 835 psig decreasing. The Tech. Spec. acceptance criteria requires
05 | a setpoint of greater than or equal to 825 plus 15 psig head correction. There
06 | was no effect on the environs. No previous occurrences of this type have been
07 | reported.

09 | SYSTEM CODE | C | C | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | E | 13 | COMPONENT CODE | I | N | S | T | R | U | 14 | COMP. SUBCODE | S | 15 | VALVE SUBCODE | Z | 16

17 | LER NO REPORT NUMBER | 7 | 9 | 18 | EVENT YEAR | 7 | 9 | 19 | SHUTDOWN METHOD | Z | 20 | HOURS | 0 | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | N | 23 | NRRD-4 FORM SUB. | N | 24 | PRIME COMP. SUPPLIER | N | 25 | REVISION NO. | 0 | 32 | COMPONENT MANUFACTURER | B | 0 | 6 | 9 | 26

10 | CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
11 0 | The problem was attributed to setpoint drift. The instrument was recalibrated
11 1 | per HNP-2-5279 and returned to service.

11 5 | FACILITY STATUS | E | 23 | % POWER | 0 | 9 | 9 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | Functional Test | 32
11 6 | ACTIVITY CONTENT | Z | 33 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36

11 7 | PERSONNEL EXPOSURES. NUMBER | 0 | 0 | 0 | TYPE | Z | DESCRIPTION | NA | 39
11 4 | PERSONNEL INJURIES. NUMBER | 0 | 0 | 0 | DESCRIPTION | NA | 41

11 3 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | DESCRIPTION | NA | 43

11 2 | PUBLICITY ISSUED DESCRIPTION | N | NA | 45

NAME OF PREPARER R. T. Nix PHONE 912-367-7781

CPG 617-128