

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | B | R | F | 1 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 14 15 25 26 30 37 38 58

CON'T
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 0 | 2 | 5 | 9 | 7 | 0 | 8 | 0 | 5 | 7 | 9 | 8 | 0 | 9 | 0 | 4 | 7 | 9 | 9
7 8 59 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation a smoke detector for the auxiliary instrument room alarmed
0 3 | and would not clear. The alarm would have masked signals from detectors which are
0 4 | required to be operational by T. S. 3.11.C.1. There were no effects on public health
0 5 | or safety. There are no redundant systems. Similar events: 296/7722, 259/7801, 259/
0 6 | 7809, 296/7809, 296/7817, 296/7823, 296/7826, 296/7828.
0 7 |
0 8 |

0 9 | SYSTEM CODE | A B | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | F | 13 | COMPONENT CODE | I N S T R U | 14 | COMP. SUBCODE | E | 15 | VALVE SUBCODE | Z | 16
7 8 9 10 11 12 13 18 19 20

17 | LER RO REPORT NUMBER | 7 9 | EVENT YEAR | 21 22 | SEQUENTIAL REPORT NO. | 0 1 5 | OCCURRENCE CODE | 0 3 | REPORT TYPE | L | REVISION NO. | 0 |
23 24 26 27 28 29 30 31 32

ACTION TAKEN | C | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 0 0 0 | ATTACHMENT SUBMITTED | Y | 23 | NPRO-4 FORM SUB. | Y | 24 | PRIME COMP. SUPPLIER | L | 25 | COMPONENT MANUFACTURER | K 1 2 0 | 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The smoke detector went into alarm state due to increased detector sensitivity. The
1 1 | Kidde FT-200 detector was replaced. A fire watch was established until repairs were
1 2 | made.
1 3 |
1 4 |

1 5 | FACILITY STATUS | E | 28 | % POWER | 0 8 9 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Operator observed an alarm | 32
7 8 9 10 12 13 44 45 46 80

1 6 | ACTIVITY CONTENT | Z | 33 | RELEASED OF RELEASE | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36
7 8 9 10 11 44 45 80

1 7 | PERSONNEL EXPOSURES NUMBER | 0 0 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39
7 8 9 11 12 13 80

1 8 | PERSONNEL INJURIES NUMBER | 0 0 0 | 40 | DESCRIPTION | NA | 41
7 8 9 11 12 80

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43
7 8 9 10 80

2 0 | PUBLICITY ISSUED DESCRIPTION | N | 44 | NA | 45
7 8 9 10 80

328327

NAME OF PREPARER _____ PHONE _____

7909110 457

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 7915 - Technical Specification Involved T.S. 3.11.C-1 and 2
Reported Under Technical Specification T. S. 6.7.2.b.2
Date of Occurrence 8/5/79 Time of Occurrence 0450 Unit 1

Identification and Description of Occurrence:

A smoke detector for the auxiliary instrument room alarmed and would not clear. The alarm would have masked signals from detectors which are required to be operational by T. S. 3.11.C.1.

Conditions Prior to Occurrence:

The unit was under normal operating conditions with power output of 89%. All smoke detectors were operable and all alarms clear.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

A fire watch was established.

Apparent Cause of Occurrence:

Increased detector sensitivity due to normal aging.

Analysis of Occurrence:

NA

Corrective Action:

Detector was replaced.

Failure Data: Similar events: 296/7722, 259/7801, 259/7809, 296/7809, 296/7817, 296/7823, 296/7826, 296/7828.

*Retention: Period - Lifetime, Responsibility - Administrative Supervisor

*Revision: 

928328