

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | R | A | N | O | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CON'T
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 8 | 7 | 0 | 8 | 2 | 1 | 7 | 9 | 8 | 0 | 9 | 1 | 2 | 7 | 9 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | During Mode 1 operation, the "A" CPC trips were bypassed to
0 3 | allow the change out of the RSPT power supplies which
0 4 | were causing erroneous position indication inputs to the
0 5 | CPC. The pulse counter from CEAC #2 and the upper
0 6 | electrical limits were available for CEA position indications.
0 7 | There have been no similar occurrences. This occurrence is
0 8 | related to LER 50-368/79-073. Reportable per T.S.6.9.1.9b.

0 9 | SYSTEM CODE | I | E | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | E | 13 | COMPONENT CODE | I | N | S | T | R | U | 14 | COMP. NUM. | P | 15 | VALVE SUBCODE | Z | 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
17 | LER NO. REPORT NUMBER | 7 | 9 | EVENT YEAR | 7 | 9 | SEQUENTIAL REPORT NO. | 0 | 7 | 4 | OCCURRENCE CODE | 0 | 3 | REPORT TYPE | L | REVISION NO. | 0
21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
18 | ACTION TAKEN | A | FUTURE ACTION | Z | EFFECT ON PLANT | Z | SHUTDOWN METHOD | Z | HOURS | 0 | 0 | ATTACHMENT SUBMITTED | N | NRC-4 FORM SUR | N | PRIME COMP SUPPLIER | N | COMPONENT MANUFACTURER | L | 0 | 4 | 5 | 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | The "A" CPC was taken out of service as a precautionary
1 1 | step during the maintenance activity in the CPC
1 2 | cabinet. The RSPT power supplies were changed out and
1 3 | the "A" CPC was returned to service within three hours
1 4 | meeting the requirements of Action Statement T.S. Table 3.3-1 Action 2a.

1 5 | FACILITY STATUS | B | % POWER | 0 | 5 | 0 | OTHER STATUS | Pwr Escalation | TESTING | METHOD OF DISCOVERY | Z | NA | DISCOVERY DESCRIPTION | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 6 | ACTIVITY CONTENT | Z | RELEASED OF RELEASE | Z | AMOUNT OF ACTIVITY | NA | LOCATION OF RELEASE | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 7 | PERSONNEL EXPOSURES | 0 | 0 | 0 | TYPE | Z | DESCRIPTION | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 8 | PERSONNEL INJURIES | 0 | 0 | 0 | DESCRIPTION | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

1 9 | LOSS OF OR DAMAGE TO FACILITY | Z | DESCRIPTION | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

2 0 | PUBLICITY ISSUED | N | DESCRIPTION | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

NAME OF PREPARER Chris N. Shively PHONE 501/968-2519

7909180492

364360