

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 P A T M I I 2 0 0 0 - 0 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 1 1 4 \_\_\_\_\_ 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T  
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 2 0 7 0 3 0 5 7 9 8 0 9 / / / 7 9 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While in Mode 1, it was discovered that Fire Barrier Seals made of Firewall 50  
0 3 had cracked, spalled and seperated. Two seals which had been temporarily repaired  
0 4 had cracked further. A total of five were declared non-functional. During the  
0 5 investigation utilizing SP 2331-R3, completed on 3/22/79 an additional 60%  
0 6 of the seals made of Firewall 50 did not meet the surveillance acceptance criteria,  
0 7 but were considered functional. Although the Action Statement of T.S. 3.7.11 was  
0 8 complied with for the fire seals declared non-functional (i.e.: a fire watch was

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
A B (11) B (12) C (13) 7 1 Z 1 Z 1 Z 1 Z 1 Z (14) Z (15) Z (16)  
7 8 9 10 11 12 13 18 19 20  
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
79 (17) — (18) 0 1 1 2 (19) / (20) 0 3 (21) L (22) — (23) 0  
21 22 23 24 26 27 28 29 30 31 32  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NFPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
X (18) D (19) Z (20) Z (21) 0 0 0 0 (22) N (23) N (24) L L (25) Z 9 9 9 (26)  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 This event occurred due to cracks developing in Fire Barrier Penetration seals  
1 1 making the seals non-functional. A continuous fire watch was established within the  
1 2 time frame required by T.S 3.7.11.A . Temporary Repairs to the non-functional seals  
1 3 were made using silicone foam Sem-Kits. Inspection of the remaining seals was  
1 4 initiated. Seals identified as unacceptable as a result of this inspection will be repaired.

1 5 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)  
E (28) 0 0 0 5 (29) N/A (30) C (31) Special test (32)  
7 8 9 10 11 12 13 44 45 46 80  
1 6 ACTIVITY CONTENT RELEASER OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)  
Z (33) Z (34) N/A (35) N/A (36)  
7 8 9 10 11 12 44 45 80  
1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  
0 0 0 0 (37) Z (38) N/A (39)  
7 8 9 10 11 12 13 80  
1 8 PERSONNEL INJURIES NUMBER DESCRIPTION (41)  
0 0 0 (40) N/A (41)  
7 8 9 10 11 12 80  
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)  
Z (42) N/A (43)  
7 8 9 10 11 12 80

2 0 PUBLICITY ISSUED DESCRIPTION (45)  
Y (44) Weekly News Release (45)  
7 8 9 10 80  
NAME OF PREPARER R.A. Lengel  
PHONE 215-921-6581  
NRC USE ONLY

7-2-79