(7.77)	LICENSEE EVENT REPORT
	CONTROL BLOCK:
	M D C C N 1 0 0 0 - 0 0 0 0 0 - 0 0 0 0 - 0 0 0 0
CON'T	REPORT L 6 0 5 0 0 0 3 1 7 0 0 8 2 7 7 9 8 0 9 2 6 7 9 9 SOUNCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
02	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) The auxiliary high pressure safey injection (HPSI) header 12 and 13 charging
03	pumps were placed out of service from 1857 to 0345 on 8/27/79 (T.S.3.5.2 and
04	[3.1.2.4) in order to repair a cracked weld on the charging header (T.S.6.9.1.9).
015	The normal HPSI header and 11 charging pump which was lined-up to the auxiliary
0 6	HPSI heaver remained operable during the event. This is not a repetitive
07	Loccurrence.
	80
	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
, .	17 LER/RO EVENT YEAR SEQUENTIAL REPORT NO. NUMBER 799 22 24 26 27 28 29 30 31 32
	ACTION PUTURE EFFECT SHUTDOWN HOLRS (22) ATTACHMENT FORM SUB. PRIME COMP. COMPONENT TAKEN ACTION ON PLANT METHOD HOLRS (22) ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER (A) (B) (Z) (J) (A) (2) (A) (A) (A) (A) (A) (A) (A) (A) (A) (A
10	The action statements were voluntarily entered to repair a cracked weld on a
11	reducer for the sample line pipe. The reducer was removed and replaced. Lack
112	of fusion in the weld appears to be the cause of the crack. No further corrective
13	action is required as the weld was made during initial construction.
14	80
	PACILITY FACILITY E 28 0 8 5 29 0THER STATUS 30 METHOD OF NA DISCOVERY DESCRIPTION 32 A 30 A6 NA BO BO DISCOVERY DESCRIPTION 32 BO BO BO BO BO BO BO BO BO BO
	ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
17	
118	PERSONNEL INJURIES NUMBER DESCRIPTION (4) 0 0 0 10 (40) NA
7 8	SO 10 DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA 1060 002
7 8	9 10 PUBLICITY ISSUED DESCRIPTION (45) 7910010405 NRC USE ONLY
2 0	9 10 68 69 80.5
	NAME OF PREPARER S. M. Davis/M. J. Miernicki PHONE (301) 234-7942/7962