(7-77)	LICENSEE EVENT REPORT
	CONTROL BLOCK:
	N C B E P 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 0 5 9 LICENSEE CODE 14 15 LICENSE NUMBER - 0 25 26 LICENSE TYPE 30 57 CAT 58 5
	REPORT L 6 0 5 0 - 0 3 2 4 0 0 9 2 6 7 9 8 1 0 1 6 7 9 9 SOURCE 50 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
02	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
	operator noticed that indication for its position, notch 48, was no longer illuminated!
03	The position of rod 22-31 was verified by other available methods.
	Technical Specifications 3.1.3.7, 6.9.1.9b
0 5	Technical specifications 5.1.5.7, 0.9.1.90
06	L
0 7	
08 7 8	9 SYSTEM CAUSE CAUSE COMP. VALVE
09	CODE CODE SUBCODE COMPONENT CODE SUBCODE
, .	Image: Secure state Secure state OCCUR RENCE REPORT REPORT NO.   Image: Secure state
	ACTION FUTURE EFFECT SHUTDOWN TAKEN ACTION ON PLANT METHOD HOURS (2) ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. X 18 X 19 Z 20 Z (21 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
10	An investigation determined that the problem was located in the PIP probe located in the
11	the drywell. This problem will be corrected during the next outage of sufficient
12	length. An Engineering Work Request has been written to determine if a generic
13	problem exists with this type of indication.
	9 80
15	FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DISCOVERY DISCOVERY   E 28 0 5 6 2 <sup>-1</sup> NA A (31) Operator Surveillance   9 10 12 13 44 45 46 80
	ACTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 NA NA 80
17	PERSONNEL EXPOSURES NUMBER 0 0 0 37 Z 38 NA 9 11 12 13 80
18	9 PERSONNEL INJURIES NUMBER DESCRIPTION (41) 0 0 0 0 0 0 NA
19	LOSS OF OR DAMAGE TO FACILITY (3) TYPE DESCRIPTION 7910230555 Z (42) NA
7 8	PUBLICITY ISSUED DESCRIPTION 45 POOR ORIGINAL 1203 125 NRC USE ONLY N 44 NA POOR ORIGINAL 1203 125 NRC USE ONLY
7 8	9 10 NAME OF PREPARER A. C. Tollison, Jr. PHONE: 919-457-9521