



730

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

Docket No. 50-271

Vermont Yankee Nuclear Power Corporation
ATTN: Mr. Robert H. Groce
Licensing Engineer
20 Turnpike Road
Westborough, Massachusetts 01581


NOV 08 1979

Gentlemen:

Enclosed is IE Bulletin No. 79-02, Revision 2, which requires action by you with regard to your power reactor facility(ies) with an operating license or a construction permit.

Should you have questions regarding this Bulletin or the actions required of you, please contact this office.

Sincerely,


Boyce H. Grier
Director

Enclosures:

1. IE Bulletin No. 79-02, Revision 2
2. List of IE Bulletins Issued in the Last Six Months

CONTACT: L. E. Tripp
(215-337-5282)

cc w/encls:

W. F. Conway, Plant Superintendent
Ms. J. Abbey, Technical Secretary

1394 200

7911260 09.6 Q

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

SSINS No.: 6820
Accession No.:
7908220166

63

IE Bulletin No. 79-02
(Revision 2)
Date: November 8, 1979
Page 1 of 8

PIPE SUPPORT BASE PLATE DESIGNS USING CONCRETE EXPANSION ANCHOR BOLTS

Description of Circumstances:

Inspection experiences and the review of licensee response have identified several areas where the Bulletin intent has not been adequately addressed by licensees. Revision No. 2 of the Bulletin is intended to clarify the intent of the Bulletin and establish the NRC positions on minimum factors of safety, anchor bolt preload, and the expected date of completion for certain Bulletin actions.

Since the issuance of IE Bulletin No. 79-02 on March 8, 1979, IE inspection experience and many inquiries from licensees indicate that additional information and clarification is needed. This revision is intended to serve that purpose. None of the requirements of the original Bulletin have been deleted, and the due date for completion of the requested actions (July 6, 1979) has not been changed. The following text supersedes the text of Bulletin No. 79-02. Changes from the original text are identified by R1, R2 in the margin. The purpose of this revision is to identify acceptable ways of satisfying the Bulletin requirements.

While performing inservice inspections during a March-April 1978 refueling outage at Millstone Unit 1, structural failures of piping supports for safety equipment were observed by the licensee. Subsequent licensee inspections of undamaged supports showed a large percentage of the concrete anchor bolts were not tightened properly.

Deficiency reports, in accordance with 10 CFR 50.55(e), filed by Long Island Lighting Company on Shoreham Unit 1, indicate that design of base plates using rigid plate assumptions has resulted in underestimation of loads on some anchor bolts. Initial investigation indicated that nearly fifty percent of the base plates could not be assumed to behave as rigid plates. In addition, licensee inspection of anchor bolt installations at Shoreham has shown over fifty percent of the bolt installations to be deficient.

Vendor Inspection Audits by NRC at Architect Engineering firms have shown a wide range of design practices and installation procedures which have been employed for the use of concrete expansion are toward more rigorous controls bolts.

The data available on dynamic test fatigue failures can occur at load

R1 and R2 - Identifies those addi

1394 201

DUPLICATE DOCUMENT

Entire document previously
entered into system under:

ANO

7908220163

No. of pages:

12