



LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 7917 Technical Specification Involved Table 3.2.B

Reported Under Technical Specification 6.7.2.b(1)

Date of Occurrence 8/9/79 Time of Occurrence 3:30 p.m. Unit 1

Identification and Description of Occurrence:

Due to GE reevaluation of POST-LOCA conditions, GE SIL 299, High Drywell Temperature Effect on Reactor Water Level Instrumentation, the reactor water level indications can be 29 inches less than present setpoint.

Conditions Prior to Occurrence:

Normal Operation.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Heating of the water legs of the Reactor Water Level instruments during a LOCA condition could result in a 29-inch error indication in the instruments.

Analysis of Occurrence:

None


Corrective Action:

Design change request 1875, has been submitted requesting a setpoint change for LIS-3-58A-D, from  $\geq 378$  vessel inches to  $\geq 407$  vessel inches.

Failure Data:

None

\*Retention: Period - Lifetime, Responsibility - Administrative Supervisor

\*Revision: 

939335