LICENSEE EVENT REPORT

Elocitoci		
CONTROL BLOCK:	(PLEASE PRINT OR TYPE ALL	REQUIRED INFORMATION)
0 1 L Q A D 1 2 0 0 0 - 0 0 LICENSEE CODE 14 15	0 0 - 0 0 0 3 4 1 ENUMBER 25 26 LIE	1 1 1 1 4 57 CAT 58
O 1 SOURCE L 6 0 5 0 0 0 2 5 4	0 18 1 3 7 19 3 68 69 EVENT DATE 74	0 8 2 1 7 9 9
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (
0 2 While performing the HPCI Turbine Are	a High Temperature Isolat	ion Calibration, procedure
QIS 27-1, temperature switch TS 1-237		
0 4 Specification Table 3.2-1 limit of 20	10° F. The sixteen HPCI to	urbine area high
0 6 temperature switches are arranged in		
o 6 one-out-of-two twice logic scheme. T	herefore, the other switch	nes would have initiated
0 7 a group IV isolation at or below the	200° F LCO as designed.	
08		80
\$\frac{1}{2} \\ \frac{1}{2} \\ \frac	COMPONENT CODE SUBCO	SUBCODE SUBCODE SUBCODE SUBCODE
LER/RO EVENT YEAR REPORT NO. 17 REPORT 7 9 0 2 5 ACTION FUTURE ON PLANT METHOD E 18 Z 19 Z 20 Z 21 0 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)		PORT NO. I
1 10 The cause of this occurrence was due	to setpoint drift. The o	corrective action was to
recalibrate the switch. Switch TS 1	-2371A was successfully re	etested, tripping at
[1]2 L 189° F.		
131		
1 4 2 8 9		30
FACILITY STATUS 30 OTHER STATUS 30 NA NA	B 31 Routine Test/In	
ACTIVITY CONTENT 12 13 RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)		TON OF RELEASE (36)
1 6 Z 33 Z 34 NA NA PERSONNEL EXPOSURES	NA NA	80
1 7 0 0 0 37 Z 38 NA		
PERSONNEL INJURIES NUMBER DESCRIPTION	PANR ARICINAL	80
1 8 0 0 0 40 NA	I OUN UNIUNAL	
		22
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA	7909120415	433314
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA PUBLICITY ISSUED DESCRIPTION 45	7909120415	
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA PUBLICITY ISSUED DESCRIPTION 45		433314