	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M A P P S 1 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
CON'T	REPORT L 6 0 5 0 - 0 2 9 3 7 1 0 0 1 7 9 8 1 0 0 9 7 9 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  On October 1, 1979, Pilgrim Station was informed by 1: 3 Engineering Department
0 2	that while continuing it's evaluation of seismic restraints per I&E Bulletin 79-02
0 3	
0 4	it was discovered that a portion of "B" SSW Loop Piping did not meet criteria for
0 5	Safe Shutdown Earthquake in that the pipe could be overstressed during a seismic
0 6	event.
0 7	
7 8	9
0 9	SYSTEM CAUSE CAUSE SUBCODE SUB
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)   CODE   C
10	This situation was caused by design error. Plant Design Change Request (PDCR) 79-24
11	was initiated to add restraints to reduce potential pipe stress to acceptable
1 2	limits. Implementation of the modifications were completed and the system returned
1 3	to normal on October 5, 1979.
114	90
1 5	FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIPTION 32 C 31 Engineering Evaluation
	ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 N.A. N.A.
1 7 8	PERSONNEL EXPOSURES NUMBER  O O O O O O O O O O O O O O O O O O O
1 B	NUMBER   DESCRIPTION (41)  N.A. 1152 045
1 9	LOSS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION  N.A.  7910150 538
20	PUBLICITY ISSUED DESCRIPTION (45)  N.A.  NRC USE ONLY
	NAME OF PREPARER Gerald G. Whitney PHONE: 617-746-7900 0