



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION I  
631 PARK AVENUE  
KING OF PRUSSIA, PENNSYLVANIA 19406

*the*

Docket Nos. 50-277  
50-278

NOV 13 1979

Philadelphia Electric Company  
ATTN: Mr. S. L. Daltroff  
Vice President  
Electric Production  
2301 Market Street  
Philadelphia, Pennsylvania 19101

Gentlemen:

The enclosed IE Information Notice No. 79-27 provides information with regard to the sequence of events that followed incidents involving steam generator tube ruptures at two PWR units. If you have any questions regarding this matter, please contact this office.

Sincerely,

*Boyce H. Grier*  
Boyce H. Grier  
Director

Enclosures:

1. IE Information Notice No. 79-27
2. List of Recently Issued Information Notices

CONTACT: W. H. Baunack  
(215-337-5334)

cc w/encls:

W. T. Ullrich, Station Superintendent  
Troy B. Conner, Jr., Esquire  
Eugene J. Bradley, Esquire  
Raymond L. Hovis, Esquire  
Michael J. Scibinico, II, Assistant Attorney General

1503 058

7912050 286

ENCLOSURE 1

SSINS No.: 6870  
Accession No.:  
7910250488

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT  
WASHINGTON D.C. 20555

IE Information Notice No. 79-27  
Date: November 16, 1979  
Page 1 of 9

STEAM GENERATOR TUBE RUPTURES AT TWO PWR PLANTS

Description of Circumstances:

In recent months two incidents involving steam generator tube ruptures have occurred. In both instances, the units were cooled down and placed in the residual heat removal mode with existing procedures.

Event of June 25, 1979 at the Doel 2 Nuclear Power Plant in Belgium

The first event occurred on June 25, 1979, at the Doel 2 nuclear power plant in Belgium. The Doel unit is a 390 Mwe Westinghouse two-loop reactor. The event consisted of a rupture of several tubes in the loop B steam generator. The resultant leakage between the primary and secondary systems was estimated to be 125 gpm. The event started when the plant was heated up after a shutdown caused by a malfunction of the main steam isolation valve. At the time of the incident the primary coolant pressure was: 2233 psi and the temperature: 491°F. The reactor remained subcritical throughout the event.

The first indication of abnormal behavior was a rapid decrease of the primary system pressure (approximately: 28 psi/min.). This was followed by the sequence of events listed below:

	<u>Time, min.</u>
1. Increase of charging flow demand, requiring startup of a second charging pump.	1.8
2. Automatic isolation of the CVCS letdown line.	2.4
3. Shut off of the pressurizer heaters due to low liquid level in the pressurizer.	2.4

1503 059

DUPLICATE DOCUMENT

Entire document previously  
entered into system under:

ANO 7910250488  
No. of pages: 10