

TH

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION I  
631 PARK AVENUE  
KING OF PRUSSIA, PENNSYLVANIA 19406

Docket No. 50-271


NOV 26 1979

Vermont Yankee Nuclear Power Corporation  
ATTN: Mr. Robert H. Groce  
Licensing Engineer  
20 Turnpike Road  
Westborough, Massachusetts 01581

Gentlemen:

The enclosed IE Circular No. 79-24 is forwarded to you for information. No written response is required. Should you have any questions related to your understanding of the recommendations on this matter, please contact this office.

Sincerely,

  
for Boyce H. Grier  
Director

Enclosures:

1. IE Circular No. 79-24 w/Attachment
2. List of Recently Issued IE Circulars

CONTACT: W. H. Baunack  
(215-337-5253)

cc w/encls:

W. F. Conway, Plant Superintendent  
Ms. J. Abbey, Technical Secretary

1540 076

7912060

599

ENCLOSURE 1

Accession No: 7910250492  
SSINS No. 6830

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT  
WASHINGTON, D.C. 20555

IE Circular No. 79-24  
Date: November 26, 1979  
Page 1 of 3

PROPER INSTALLATION AND CALIBRATION OF CORE SPRAY PIPE BREAK DETECTION EQUIPMENT  
ON BWRs

Description of Circumstances:

During 1976 the Iowa Electric Light and Power Company identified and corrected a potential problem involving the core spray (CS) pipe break detection system at the Duane Arnold Energy Center (DAEC). The problem relates to the setpoint, function, and installation of the differential pressure (dp) instrument which monitors for a CS pipe break that is located in the annulus area of the reactor vessel (i.e., located outside the core shroud but inside the reactor vessel). The installed instrument, range of 0 - 24 psid, was found deflecting downscale (i.e., reading negative psid) during operation.

The licensee's investigation of the downscale deflection revealed that the original piping arrangement and calibration did not adequately take into account the effect of density changes of the water in the pressure leg connections. The original installation had the high pressure side of the dp instrument (see attached Figure 1) connected to the reference leg in the vessel (Figure 1 Connection X) and the low pressure side to the core spray piping outside the vessel but inside the drywell (Figure 1 Connection Y). With the piping intact, this arrangement senses the pressure difference between bottom and top of core. With a break in CS piping in the annulus area the instrument then senses the additional pressure drop across the separators (dp  $\sim$  7 psi additional) and dryers (dp  $\sim$  7-inches water). This installation was in accordance with GE design requirements.

Also in accordance with GE instructions the calibration of the dp instrument was performed with the reactor in the cold condition and the alarm was set to trip at 5 psid increasing. Because of this cold calibration the dp instrument then indicated full downscale negative during operation. This negative dp was due to the heat up of the reference leg (Figure 1 Connection X) which caused the fluid density to decrease as the plant reached full power. This density change was determined to be about 3.5 psid for the conditions discussed below.

Adding the 3.5 psi downscale deflection in a total required deflection of 8.5 psi. Since the total dp available across the

1540 077

DUPLICATE DOCUMENT

Entire document previously  
entered into system under:

ANO 7910250492  
No. of pages: ~~5~~ 4