

**LICENSEE EVENT REPORT**

CONTROL BLOCK: 

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

3	1	G	A	E	I	H	2	2	0	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5
8		9 LICENSEE CODE 14						15 LICENSE NUMBER 25												26 LICENSE TYPE 30					57 CAP 58				

REPORT SOURCE L 6 0 5 0 0 0 3 6 6 7 0 9 2 6 7 9 3 1 0 1 9 7 9 9

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

COCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing routine surveillance procedure, HNP-2-3002, High Drywell Pressure

0 3 | Functional Test and Calibration, instruments 2C71-N002A, C and D were found to exceed

0 4 | the Tech Spec limit of less than or equal to 2 psig. All switches actuated at a

0 5 | pressure of less than or equal to 2.16 psig. There was no effect on the environs.

0 6 | There have been no similar occurrences on these instruments.

0 7 |

0 8 |

3 9		SYSTEM CODE I A (11)		CAUSE CODE E (12)		CAUSE SUBCODE E (13)		COMPONENT CODE I N S T R U (14)				COMP. SUBCODE S (15)		VALVE SUBCODE Z (16)	
8		9 10		11		12		13 14 15 16 17 18				19		20	
17		EVENT YEAR 7 9		SEQUENTIAL REPORT NO. 1 0 8		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0					
21 22		23		24 25 26		27		28 29		30		31		32	
ACTION TAKEN E (18)		FUTURE ACTION G (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22)		ATTACHMENT SUBMITTED Y (23)		NPRO-4 FORM SUB. N (24)		PRIME COMP. SUPPLIER N (25)	
33		34		35		36		37 38 39 40		41		42		43	
44		45		46		47		48		49		50		51	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

110 The cause was contributed to setpoint drift. The instruments were recalibrated and  
111 returned to service. Investigations were made into reasons that may have caused a  
112 multiple drift. A possible item, which we believe contributed to the multiple drift.  
113 was the test equipment specified by HNP-2-3002 would allow the use of pressure  
114 instrumentation with lesser resolution than should be used on this application. (cont.)

8 9 FACILITY STATUS 1 5 E 28 10 11 12 13 % POWER 0 9 6 29 OTHER STATUS NA 30 44 45 46 METHOD OF DISCOVERY B 31 47 48 DISCOVERY DESCRIPTION Surveillance test 22

ACTIVITY CONTENT RELEASED OF RELEASE		AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
11	12	NA	NA

PERSONNEL NUMBER	DESCRIPTION
1010101	NA

POOR ORIGINAL

8	9	11	12	
LOSS OF OR DAMAGE TO FACILITY		(43)		
TYPE DESCRIPTION				
2	(12)		NA	1221 095

PUBLICITY  
 ISSUED DESCRIPTION 45  
 NA 7910290276 NRC USE ONLY

NAME OF PREPARER R. T. NIX

912-367-7781

NRC USE ONLY

Georgia Power Company  
Plant E. I. Hatch  
Baxley, Georgia 31513

Reportable Occurrence Reprot No. 50-366/1979-108

Cause Description and Corrective Actions (cont)

The procedure was revised to state explicitly what instrumentation should be used. No other factors were found which would contribute to multiple drift.

1221 096