U. S. NUCLEAR REGULATORY COMMISSION NRC FORM 366 (7.77) LICENSEE EVENT REPORT (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 10 CONTROL BLOCK: 134 (4 0 0 0 0 0 0 10 ANAS (2)0 0 1 LICENSE TYPE LICENSE NUMBER LICENSEE CODE CON'T REPORT 11 023 (8) 8 (7) 0 9 2 19 0 1 L 6 0 5 0 0 0 3 3 15 SOURCE DOCKET NUMBER 60 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) 0 2 While to Mode 3, operation personnel noted the steam driven auxiliary feedwater [0]3] | pump 1-FW-P-2 was turning due to a steam leak thru a steam inlet trip valve 0 4 | The steam supply to 1-FW-P-2 was isolated using manually operated isolation 0 5 | valves rendering it inoperable. This event is contrary to T.S. 3.7.1 Two half-size auxiliary feedwater pumps reportable pursuant to T.S. 6.9.1.9.b. 0 6 were operational; therefore the public health and safety were not affected by 0 7 0 8 this event. 80 8 COMP VALVE CAUSE SYSTEM CAUSE SUBCODE CODE CODE SUBCODE COMPONENT CODE (16) (15 B (12 B (13) V F B E V X H 0 9 13 10 10 REVISION SEQUENTIAL OCCURRENCE REPORT REPORT NO. CODE TYPE NO. EVENT YEAR LER/RO 01 (17)REPORT 7 9 3 0 3 0 1 NUMBER 31 32 28 NPRD-4 PRIME COMP. COMPONENT ATTACHMENT SUBMITTED EFFECT ON PLANT SHUTDOWN ACTION FUTURE HOURS (22) **MANUFACTURER** FORM SUB. SUPPLIER N (24) A 25 Y 23 3 0 11 Z (19 F Z (20) (21 0 Z (18) Z p 34 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) I lo Isolation of steam to 1-FW-P-2 became necessary due to a leak thru a steam inlet The plant was in the Hot Shutdown condition (Mode 4) within 1 1 |trip valve. 1 2 of the event due to a shutdown that was in progress for a planned refueling outage Therefore, the dictates of the action statement of T.S. 3.7.1.2 were met, The 14 |valve will be repaired during the refueling outage. 80 9 METHOD OF FACILITY (30) DISCOVERY DESCRIPTION (32) OTHER STATUS % POWER X (28) 0 0 0 0 29 mergency Shutdown Observation A (31 Operator 5 80 9 10 ACTIVITY CONTENT LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35) RELEASED_OF RELEASE Z 33 Z 34 6 NA NA 80 10 44 11 PERSONNEL EXPOSURES DESCRIPTION (39) TYPE NUMBER 0 0 0 3 Z 38 NA 7 80 PERSONNEL INJURIES 13 1.17.1 DESCRIPTION (41) NUMBER 0 0 0 40 NA 1 8 80 11 12 LOSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION TYPE Z (42) NA 9 10 7910300210 PUBLICITY NRC USE ONLY DESCRIPTION (45 ISSUED ED 44 N NA 0 80.5 69 68 10 0 d D PHONE --703-894-5151 NAME OF PREPARER W. R. Cartwright

Virginia Electric and Power Company North Anna Power Station, Unit #1 Docket No. 50-338 Report No. LER 79-130/03L-0

1210 340

Description of Event

On September 25, 1979, steam was observed leaking past the seat of trip valve TV-MS111B. During Mode 3 operation, TV-MS-111B was isolated for repair. This valve is located on the steam line leading to the steam driven steam generator auxiliary feedwater pump 1-FW-P-2.

Probable Consequences of Occurrence

The steam supply line to the auxiliary feedwater pump required isolation thereby bringing into effect the ACTION statement of T.S. 3.7.1.2. This calls for one of three auxiliary feedwater pumps to be powered by an operable steam supply within 72 hours or be in Hot Shutdown within the next 12 hours. Since both motor driven auxiliary feed pumps were available for operation, the health and safety of the general public were not affected by this event. Potential generic implications for Unit 2 exist because of past problems encountered with these valves.

Cause of Occurrence

The steam leak was caused by the valve not seating properly.

Immediate Corrective Action

The unit was taken to Cold Shutdown for a scheduled refueling outage.

Scheduled Corrective Action

The valve will be repaired during the refueling outage.

Actions Taken To Prevent Recurrence

Causes of failure are being evaluated. The vendor has been contacted and his recommendation will be evaluated and implemented, as appropriate, during the refueling outage.