

01 C I M N S 2 00 - 000000 - 00 3 4 1 1 1 1 1 4

CON'T REPORT SOURCE L 05000336 7 092979 8 1102579 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
02 During routine plant operations the Engineered Safety Features (ESF) channel A sensor
03 cabinet trip bistables all tripped due to a loss of power. In accordance with technical
04 specifications, section 3.3.2.1.b, the channel A ESF bistables were inhibited and
05 plant operation continued while the failure was investigated and repaired. Total time
06 out of service was 17 hours.

09 SYSTEM CODE I B 11 CAUSE CODE E 12 CAUSE SUBCODE G 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE X 15 VALVE SUBCODE Z 16
17 LER/RO REPORT NUMBER 79 EVENT YEAR 79 SEQUENTIAL REPORT NO. 030 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 0
ACTION TAKEN A 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0000 ATTACHMENT SUBMITTED N 23 NRC-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER 4045

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10 The cause of the power failure was a failed over-voltage protector (Lambda, Model -
11 LMOV-2) on the channel A -15 volt power supply which caused a fuse to blow. The
12 over-voltage protector and fuse were replaced and the ESF channel A sensor cabinet
13 was restored to operability.

15 FACILITY STATUS E 28 % POWER 100 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32

16 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

17 PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION NA 39 1281 002

18 PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

20 PUBLICITY ISSUED N 44 DESCRIPTION NA 45 7911010401 NRC USE ONLY